Swabbed and recovered water, no oil, small gas. Ran cement retainer and s tubing and stinger. Squeezed zone w/75 sacks Class H. Squeezed to 4500#. and stinger. Perforated 11906-918' w/48 .50" holes. Swabbed well. POOH cement retainer at 11850'. Ran tubing and stinger. Squeezed perfs 11906- Class H cement. Squeezed to 5000#. POOH. WIH and perforated 11660-664' Acidized perfs w/1000 gallons 15% NE acid and N ₂ . WIH and perforated thro w/10 holes. Acidized perfs 11670-75' w/1000 gallons 15% NE acid, 2% KCL a Swabbed back load. Released packer. POOH. Ran CIBP and set at 11600' w/3 top. Prep to perforate new zone.	ve stre , releas enting 2 ve stren , releas e (Atoka- et 12100 POOH w w/packer 918' w/7 w/10 .34 ough tubi nd ball 5' of ces	lows: ngth of ed pressure nd stage. gth of ed pressure Morrow). '. Ran /tubing . Set 5 sacks " holes. ng 11670-75' sealers. ment on
Swabbed and recovered water, no oil, small gas. Ran cement retainer and s tubing and stinger. Squeezed zone w/75 sacks Class H. Squeezed to 4500#. and stinger. Perforated 11906-918' w/48 .50" holes. Swabbed well. POOH cement retainer at 11850'. Ran tubing and stinger. Squeezed perfs 11906- Class H cement. Squeezed to 5000#. POOH. WIH and perforated 11660-664' Acidized perfs w/1000 gallons 15% NE acid and N ₂ . WIH and perforated thro w/10 holes. Acidized perfs 11670-75' w/1000 gallons 15% NE acid, 2% KCL a Swabbed back load. Released packer. POOH. Ran CIBP and set at 11600' w/3 top. Prep to perforate new zone.	ve stre , releas enting 2 ve stren , releas (Atoka-) et 12100 POOH w w/packer 918' w/7 w/10 .34 ough tubi nd ball 5' of ce	lows: ngth of ed pressure nd stage. gth of ed pressure Morrow). '. Ran /tubing . Set 5 sacks " holes. ng 11670-75' sealers. ment on
Swabbed and recovered water, no oil, small gas. Ran cement retainer and s tubing and stinger. Squeezed zone w/75 sacks Class H. Squeezed to $4500\#$. and stinger. Perforated 11906-918' w/48 .50" holes. Swabbed well. POOH cement retainer at 11850'. Ran tubing and stinger. Squeezed perfs 11906- Class H cement. Squeezed to 5000#. POOH. WIH and perforated 11660-664' Acidized perfs w/1000 gallons 15% NE acid and N ₂ . WIH and perforated thro w/10 holes. Acidized perfs 11670-75' w/1000 gallons 15% NE acid, 2% KCL a Swabbed back load. Released packer. POOH. Ran CIBP and set at 11600' w/3 top. Prep to perforate new zone.	ive stre , releas enting 2 ve stren , releas e (Atoka-1 et 12100 POOH w w/packer 918' w/7 w/10 .34 ough tubi nd ball	lows: ngth of ed pressure nd stage. gth of ed pressure Morrow). '. Ran /tubing . Set 5 sacks " holes. ng 11670-75' sealers.
Other	ef 4-1/2" egular g	13.5#'
PLAFOAN REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPHS. X PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JQB COMMENCE DRILLING OPHER Production Casing, Pe	PLUG AN	IC ADAHOONMENT
Check Appropriate Box To Indicate Nature of Notice, Report or Other D NOTICE OF INTENTION TO: SUBSEQUENT REF		
4221' GR Lea	County	
UNIT LETTER 0 660 FEET FROM THE SOUTH LINE AND 1980 FEET FROM THE East LINE, SECTION 17 TOWNSHIP 155 RANGE 33E NUMPH.		
	Told and Pool des. Ato	
Yates Petroleum Corporation S Address of Corrator 9. We	ams YC S	
OIL X GAS OTHER RE-ENTRY	ult Agreement	
SUNDRY NOTICES AND REPORTS ON WELLS	IC 130	VillIIIII.
LAND OFFICE	tate X ne Oil & Gus LG 138	
SANTA FE, NEW MEXICO 87501	ndicate Type c	Revised 10-1-73
ENERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION P. O. BOX 2088		Form C-103

-		DISTRIC	()	SOPERV	/
ONDITIONS	O₽	APPROVAL,	1F	ANYI	