Submit 3 copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

OIL CONSERVATION DIVISION 310 Old Santa Fe Trail, Room 206

WELL API NO.

	Santa Fe, Ne	re Trail, Roon w Mexico 875	03	WELL API NO. 30-025-01454	
DISTRICT_II P.O. Box Drawer DD, Artesia, NM 8821	0			5. Indicate Type of Lease STATE X FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410				6. State Oil & Gas 1.2ase No. B-214	-
(DO NOT USE THIS FORM FOR DIFFERENT RESE	CES AND REPORTS OF REPORTS OF REPORTS TO DRILL CONTROL OF THE PROPOSALS.)	OR TO DEEPEN OF	R PLUG BACK TO A	7. Lease Name or Unit Agreement Name	
1. Type of Well: Oil Gas Well Well	OTHER	Water Injection V	Vell	Caprock Maljamar Unit	
2. Name of Operator				8. Well No. 20	
The Wise  3. Address of Operator	er Oil Company			9. Pool name or Wildcat	
8115 Pre:	ston Road, Suite 400, Dallas,	TX 75225		Maljamar Grayburg San Andres	
4. Well Location  Unit Letter K:	1980 Feet From The South	Line and	1980 Feet From Th	e West	Line
Section 17	Township 17S	Range 33E	NMPM	County Lea	1
	10. Elevation (Show wh 4203' GR		c.)		
	eck Appropriate Box to Indi				
NOTICE OF INTE	NTION TO:		SUBSEQUENT REP	y 100 - 100 Up	- ·
ERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIA	L WORK	ALTERING CASING	
EMPORARILY ABANDON	CHANGE PLANS	COMMEN	ICE DRILLING OPNS.	PLUG AND ABANDONMENT	:
JLL OR ALTER CASING		CASING	TEST AND CEMENT JOB		
THER:		OTHER:	CONVERT PRODUCING	WELL TO WATER INJECTION	X
ppp. of	peration (Cibari) state an periment	dealing, and Brite person	one dates,	date of starting any proposed work)	
SEE RULE 1103. 10/22/96 MIR 10/23/96 Strip 11/02/96 Clea on 2 11/07/96 Set p POF	RU Gibson WS #134. Worked pped old rods & tbg out of hold aned out to 4457'. POH RU H 2-7/8" tbg. Set pkr @ 4041'.Hl pkr @ 4024'. Tested csg. Rls H w/work string & perma-late	d stuck rods. Backetle. Dug out cellar. 4/24 ES & perfd f/4406- ES treated w/750 gast pkr & POH. RIF- th pkr. Drld blocks	d off.  10' w/2 SPF (10 holes), fals Xylene+8000 gals 159  I w/perma-latch pkr & 2-did not have any springs.	/4420-30' w/1 SPF (11 holes). RIH w/R % Fer-check acid+1800# rock salt+40 ba 7/8" work string. Pkr would not test.	TTS pkr all sealer
SEE RULE 1103. 10/22/96 MIR 10/23/96 Strip 11/02/96 Clea on 2 11/07/96 Set p POF	RU Gibson WS #134. Worked apped old rods & tbg out of how aned out to 4457'. POH RU H 2-7/8" tbg. Set pkr @ 4041'.Hipkr @ 4024'. Tested csg. Rish Wwork string & perma-lated well well well are to 2-7/8"	d stuck rods. Backetle. Dug out cellar. 4/24 ES & perfd f/4406- ES treated w/750 gasts pkr & POH. RIF- th pkr. Drld blocks work string. Set plane	d off.  10' w/2 SPF (10 holes), falls Xylene+8000 gals 159  I w/perma-latch pkr & 2-did not have any springs.  kr @ 4024'. Stacked tbg	/4420-30' w/1 SPF (11 holes). RIH w/R % Fer-check acid+1800# rock salt+40 ba 7/8" work string. Pkr would not test. wt on pkr for 4 hrs. Risd on-off tool.	TTS pkr all sealer
SEE RULE 1103. 10/22/96 MIR 10/23/96 Strip 11/02/96 Clea on 2 11/07/96 Set p POF 11/08/96 RIH LD 1	RU Gibson WS #134. Worked apped old rods & tbg out of hold aned out to 4457'. POH RU H 2-7/8" tbg. Set pkr @ 4041'.HI pkr @ 4024'. Tested csg. RIsH w/work string & perma-lated w/perma-latch pkr on 2-7/8" tbg. PU 100 jts 2-3/8	d stuck rods. Backetle. Dug out cellar. 4/24 ES & perfd f/4406- ES treated w/750 gasts pkr & POH. RIF- th pkr. Drld blocks work string. Set plane	d off.  10' w/2 SPF (10 holes), falls Xylene+8000 gals 159  I w/perma-latch pkr & 2-did not have any springs.  kr @ 4024'. Stacked tbg	/4420-30' w/1 SPF (11 holes). RIH w/R % Fer-check acid+1800# rock salt+40 ba 7/8" work string. Pkr would not test. wt on pkr for 4 hrs. Risd on-off tool.	TTS pkr all sealer
SEE RULE 1103. 10/22/96 MIR 10/23/96 Strip 11/02/96 Clea on 2  11/07/96 Set p POF 11/08/96 RIH LD: 11/11/96 PU: 11/12/96 Wai	RU Gibson WS #134. Worked apped old rods & tbg out of hold aned out to 4457'. POH RU H 2-7/8" tbg. Set pkr @ 4041'.HI pkr @ 4024'. Tested csg. RIsH w/work string & perma-lated w/perma-latch pkr on 2-7/8" 2-7/8" tbg. PU 100 jts 2-3/8	d stuck rods. Backete. Dug out cellar.  4/24 ES & perfd f/4406- ES treated w/750 gasted pkr & POH. RIF- th pkr. Drld blocks work string. Set plane in IPC tbg.  (4,000'), 2-tbg. sub	d off.  10' w/2 SPF (10 holes), falls Xylene+8000 gals 159  I w/perma-latch pkr & 2-did not have any springs.  kr @ 4024'. Stacked tbg	/4420-30' w/1 SPF (11 holes). RIH w/R % Fer-check acid+1800# rock salt+40 ba 7/8" work string. Pkr would not test. wt on pkr for 4 hrs. Risd on-off tool.	TTS pkr all sealer
SEE RULE 1103. 10/22/96 MIR 10/23/96 Strip 11/02/96 Clea on 2  11/07/96 Set p POF  11/08/96 RIH LD: 11/11/96 PU : 11/12/96 Wai  12/31/96 Initi	RU Gibson WS #134. Worked apped old rods & tbg out of hold aned out to 4457'. POH RU H 2-7/8" tbg. Set pkr @ 4041'. Hi pkr @ 4024'. Tested csg. Rish w/work string & perma-lated w/perma-latch pkr on 2-7/8" 2-7/8" tbg. PU 100 jts 2-3/8 2-3/8" IPC tbg. Total 127 jts iting on Step Rate Test. ial Injection - 75 BWPD @ 1	d stuck rods. Backete. Dug out cellar.  4/24 ES & perfd f/4406- ES treated w/750 gasted pkr & POH. RIF- th pkr. Drld blocks work string. Set plants are plants.  4(4,000'), 2-tbg. subsequence.	d off.  10' w/2 SPF (10 holes), falls Xylene+8000 gals 159  I w/perma-latch pkr & 2-did not have any springs.  kr @ 4024'. Stacked tbg	74420-30' w/1 SPF (11 holes). RIH w/R 6/6 Fer-check acid+1800# rock salt+40 bands work string. Pkr would not test.  wt on pkr for 4 hrs. RIsd on-off tool.	TTS pkr all sealer
SEE RULE 1103. 10/22/96 MIR 10/23/96 Strip 11/02/96 Clea on 2 11/07/96 Set p POF 11/08/96 RIH LD: 11/11/96 PU: 11/12/96 Wai 12/31/96 Initi	RU Gibson WS #134. Worked apped old rods & tbg out of hold aned out to 4457'. POH RU H 2-7/8" tbg. Set pkr @ 4041'. Hi pkr @ 4024'. Tested csg. Rish w/work string & perma-lated w/perma-latch pkr on 2-7/8" 2-7/8" tbg. PU 100 jts 2-3/8 2-3/8" IPC tbg. Total 127 jts iting on Step Rate Test. ial Injection - 75 BWPD @ 1	d stuck rods. Backete. Dug out cellar. 4/24 ES & perfd f/4406- ES treated w/750 gasted pkr & POH. RIF- th pkr. Drld blocks work string. Set play "IPC tbg. (4,000'), 2-tbg. sub	d off.  10' w/2 SPF (10 holes), falls Xylene+8000 gals 159  I w/perma-latch pkr & 2-did not have any springs.  kr @ 4024'. Stacked tbg	74420-30' w/1 SPF (11 holes). RIH w/R 6/6 Fer-check acid+1800# rock salt+40 bands work string. Pkr would not test.  wt on pkr for 4 hrs. RIsd on-off tool.	TTS pkr all sealer
SEE RULE 1103. 10/22/96 MIR 10/23/96 Strip 11/02/96 Clea on 2 11/07/96 Set p POF 11/08/96 RIH LD: 11/11/96 PU: 11/12/96 Wai 12/31/96 Initial thereby certify that the information above is	RU Gibson WS #134. Worked oped old rods & tbg out of hold aned out to 4457'. POH RU H 12-7/8" tbg. Set pkr @ 4041'. Hill pkr @ 4024'. Tested csg. Rish w/work string & perma-lated w/perma-latch pkr on 2-7/8" 2-7/8" tbg. PU 100 jts 2-3/8 2-3/8" IPC tbg. Total 127 jts iting on Step Rate Test. ital Injection - 75 BWPD @ 1	d stuck rods. Backete. Dug out cellar. 4/24 ES & perfd f/4406- ES treated w/750 gasted pkr & POH. RIF- th pkr. Drld blocks work string. Set play "IPC tbg. (4,000'), 2-tbg. sub	d off.  10' w/2 SPF (10 holes), fals Xylene+8000 gals 159  I w/perma-latch pkr & 2-did not have any springs.  kr @ 4024'. Stacked tbg.  s (18'). Set pkr @ 4034'.	74420-30' w/1 SPF (11 holes). RIH w/R % Fer-check acid+1800# rock salt+40 be 7/8" work string. Pkr would not test. wt on pkr for 4 hrs. RIsd on-off tool.  Circ pkr fluid.	TTS pkr all sealer
SEE RULE 1103.   10/22/96   MIR   10/23/96   Strip   11/02/96   Clea   on 2   11/07/96   Set p   POF   11/08/96   RIH   LD   11/11/96   Wait   11/11/96   Wait   12/31/96   Initial   Interest   Int	RU Gibson WS #134. Worked pped old rods & tbg out of hold and out to 4457'. POH RU H 2-7/8" tbg. Set pkr @ 4041'.HI pkr @ 4024'. Tested csg. Rls H w/work string & perma-lated w/perma-lated pkr on 2-7/8" tbg. PU 100 jts 2-3/8" 2-7/8" tbg. PU 100 jts 2-3/8 2-3/8" IPC tbg. Total 127 jts iting on Step Rate Test. ial Injection - 75 BWPD @ 1 true an complete to the best of my known in the point of the point with the point of the p	d stuck rods. Backete. Dug out cellar. 4/24 ES & perfd f/4406- ES treated w/750 gasted pkr & POH. RIF- th pkr. Drld blocks work string. Set play "IPC tbg. (4,000'), 2-tbg. sub	d off.  10' w/2 SPF (10 holes), fals Xylene+8000 gals 159  I w/perma-latch pkr & 2-did not have any springs.  kr @ 4024'. Stacked tbg.  s (18'). Set pkr @ 4034'.	7/4420-30' w/1 SPF (11 holes). RIH w/R % Fer-check acid+1800# rock salt+40 be 7/8" work string. Pkr would not test. wt on pkr for 4 hrs. Risd on-off tool.  Circ pkr fluid.  Pare 03/31/97  TELEPHONE NO. (214)265-0080	all sealer
SEE RULE 1103. 10/22/96 MIR 10/23/96 Strip 11/02/96 Clea on 2 11/07/96 Set p POF 11/08/96 RIH LD 11/11/96 PU: 11/12/96 Wait 12/31/96 Initi hereby certify that the information above is SIGNATURE SET BETT NAME Betty Ep	RU Gibson WS #134. Worked oped old rods & tbg out of hold and out to 4457'. POH RU H 2-7/8" tbg. Set pkr @ 4041'.HI pkr @ 4024'. Tested csg. Rls H w/work string & perma-lated w/perma-latch pkr on 2-7/8" tbg. PU 100 jts 2-3/8 2-3/8" IPC tbg. Total 127 jts iting on Step Rate Test. ital Injection - 75 BWPD @ 1	d stuck rods. Backete. Dug out cellar. 4/24 ES & perfd f/4406- ES treated w/750 gasted pkr & POH. RIF- th pkr. Drld blocks work string. Set play "IPC tbg. (4,000'), 2-tbg. sub	d off.  10' w/2 SPF (10 holes), fals Xylene+8000 gals 159  I w/perma-latch pkr & 2-did not have any springs.  kr @ 4024'. Stacked tbg.  s (18'). Set pkr @ 4034'.	7/4420-30' w/1 SPF (11 holes). RIH w/R % Fer-check acid+1800# rock salt+40 bi 7/8" work string. Pkr would not test. wt on pkr for 4 hrs. RIsd on-off tool.  Circ pkr fluid.  Pare 03/31/97	all sealer