

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 2149
7. Lease Name or Unit Agreement Name Phillips State ^{BY}
8. Well No. 2
9. Pool name or Wildcat Maliamar G-SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4116' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Pennzoil Exploration and Production Co.
3. Address of Operator P.O. Drawer 1828 - Midland, TX 79702-1828	4. Well Location Unit Letter <u>I</u> : <u>1980</u> Feet From The <u>south</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>19</u> Township <u>17-S</u> Range <u>33-E</u> NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4116' GL
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

P&A Well Per The Attached Wellbore Diagram

- 1) Set CIBP @ 4000' w/35' cmt.
- 2) Load hole w/brine mud.
- 3) Cut and pull 5½" from 1400'
- 4) Set 50 sk stub plug 50' in and out of stub. Tag with tubing.
- 5) POOH to 390' and circulate cement to surface using 150 sks.
- 6) Install marker & restore location.

THE COMPLETION REPORT FOR THIS WELL IS
NOW BEING FORWARDED TO THE OFFICE OF
PUBLIC INFORMATION FOR THE RECORD
TO BE MAINTAINED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Randy M. Hodgins TITLE Engineer DATE 11/19/91
TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

NOV 21 1991