Submit 3 Copies to Appropriate District Office	State of Ne Ener, Minerals and Natu		ment	Form C-103 Revised 1-1-89
DISTRICT 1 P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVA P.O. Bo		ON WELL API NO	
TRICT II Santa Fe, New Mexico 87504-2088		5. Indicate T	30-025-01909 ype of Lease STATE FEE X	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil d	STATE FEE STATE FEE STATE
( DO NOT USE THIS FORM FOR PR DIFFERENT RESE (FORM C	TICES AND REPORTS ON TOPOSALS TO DRILL OR TO DE TRVOIR. USE "APPLICATION FO C-101) FOR SUCH PROPOSALS	EPEN OR PLUG BACK	TO A 7. Lease Nar	ne or Unit Agreement Name
I. Type of Well: Ol. OAS WELL WELL X	] OTHER			York ARQ
2. Name of Operator YATES PETROLEUM CORPOR	RATION		8. Well No.	1
3. Address of Operator	baada NN( 00210		9. Pool name	
105 South 4th St., Ar	tesia, NM 88210		K6	emnitz Morrow
Unit Letter :660	0 Feet From The Sou	th Line and	1980 Feet	From The East Line
Section 12	Township 16S	Range 34E Phether DF, RKB, RT, GR, 4068 ' GR	NMPM etc.}	Lea County
II. Check	Appropriate Box to Indi		lice Report or O	<u></u>
NOTICE OF IN				T REPORT OF:
	PLUG AND ABANDON		אפע [	
				ALTERING CASING
	CHANGE PLANS		PRILLING OPNS.	ALTEHING CASING L PLUG AND ABANDONMENT [
TEMPORARILY ABANDON	CHANGE PLANS		с. Г	
PULL OR ALTER CASING		COMMENCE D CASING TEST	AND CEMENT JOB	PLUG AND ABANDONMENT
<ul> <li>PULL OR ALTER CASING</li> <li>DTHER:</li></ul>	alions (Clearly state all pertinent de d rigged up pulling wn. Rigged up wire ng and tested plug. ipe testers. TIH w nippled up tree. Tested tree to 60 ff. Pulled blankin Swabbed. Shut wel reesaver. Frac'd p allons 40# CMHPG an for clean up. ck frac. Shut well	COMMENCE C CASING TEST OTHER: Fra ails, and give pertinent da unit. Bled c line. Set 1.8 Released on/ ith tubing hyd Circulate off 00 psi. Press g plug. Swabb 1 in. erforations 13 d 49000# 20-40 in.	AND CEMENT JOB AND CEMENT JOB ac perforation tes, including estimated a casing down. 575" blanking off tool. Ni coff tool. Ni coff tool. Ni coff on/off sured annulus oed tubing dow	PLUG AND ABANDONMENT
PULL OR ALTER CASING	rations (Clearly state all periment de d rigged up pulling wn. Rigged up wire ng and tested plug. ipe testers. TIH w nippled up tree. Tested tree to 60 ff. Pulled blankin Swabbed. Shut wel reesaver. Frac'd p allons 40# CMHPG an for clean up. ck frac. Shut well 11 to production de	COMMENCE C CASING TEST OTHER: Fra while, and give pertiment da unit. Bled of line. Set 1.8 Released on/ tith tubing hyd Circulate off 00 psi. Press g plug. Swabb 1 in. erforations 13 d 49000# 20-40 in. partment.	AND CEMENT JOB AND CEMENT JOB ac perforation tes, including estimated a casing down. 575" blanking off tool. Ni coff tool. Ni coff tool. Ni coff on/off sured annulus oed tubing dow	PLUG AND ABANDONMENT
PULL OR ALTER CASING DTHER: 12 Describe Proposed or Completed Open work) SEE RULE 1103. 6-2-98 - Moved in an KCL. Bled tubing do 12955'. Loaded tubing do 12955'. Loaded tubing do 12955'. Loaded tubing. 6-3-98 - Rigged up p Nippled down BOP and packer. Flanged up. minutes, OK. Bled o 6-4-98 - Bled down. 6-5-98 - Rigged up t Morrow) with 20000 g Flowing back to pit 6-6-7-98 - Flowed ba 6-8-98 - Released we	ations (Clearly state all pertinent de d rigged up pulling wn. Rigged up wire ng and tested plug. ipe testers. TIH w nippled up tree. Tested tree to 60 ff. Pulled blankin Swabbed. Shut wel reesaver. Frac'd p allons 40# CMHPG an for clean up. ck frac. Shut well 11 to production de	COMMENCE C CASING TEST OTHER: Fra ails, and give pertinent da unit. Bled c line. Set 1.8 Released on/ ith tubing hyd Circulate off 00 psi. Press g plug. Swabb 1 in. erforations 13 d 49000# 20-40 in. partment. dge md belief.	AND CEMENT JOB	PLUG AND ABANDONMENT
PULL OR ALTER CASING PULL OR ALTER CASING THER: 12 Describe Proposed or Completed Open work) SEE RULE 1103. 6-2-98 - Moved in an KCL. Bled tubing do 12955'. Loaded tubi tubing. 6-3-98 - Rigged up p Nippled down BOP and packer. Flanged up. minutes, OK. Bled o 6-4-98 - Bled down. 6-5-98 - Rigged up t Morrow) with 20000 g Flowing back to pit 6-6-7-98 - Flowed ba 6-8-98 - Released we I hereby certify that the Information above is the SKONATURE	rations (Clearly state all pertinent de d rigged up pulling wn. Rigged up wire ng and tested plug. ipe testers. TIH w nippled up tree. Tested tree to 60 ff. Pulled blankin Swabbed. Shut wel reesaver. Frac'd p allons 40# CMHPG an for clean up. ck frac. Shut well 11 to production de	COMMENCE C CASING TEST OTHER:_Fra waits, and give pertiment da unit. Bled c line. Set 1.8 Released on/ ith tubing hyd Circulate off 00 psi. Press g plug. Swabb 1 in. erforations 13 d 49000# 20-40 in. partment. dge md belief. Operation	AND CEMENT JOB	PLUG AND ABANDONMENT
PULL OR ALTER CASING DTHER: 12 Describe Proposed or Completed Open work) SEE RULE 1103. 6-2-98 - Moved in an KCL. Bled tubing do 12955'. Loaded tubi tubing. 6-3-98 - Rigged up p Nippled down BOP and packer. Flanged up. minutes, OK. Bled o 6-4-98 - Bled down. 6-5-98 - Rigged up t Morrow) with 20000 g Flowing back to pit 6-6-7-98 - Flowed ba 6-8-98 - Released we Ihereby certify that the Information above is the SKONATURE	rations (Clearly state all pertinent de d rigged up pulling wn. Rigged up wire ng and tested plug. ipe testers. TIH w nippled up tree. Tested tree to 60 ff. Pulled blankin Swabbed. Shut wel reesaver. Frac'd p allons 40# CMHPG an for clean up. ck frac. Shut well 11 to production de	COMMENCE C CASING TEST OTHER:_Fra waits, and give pertiment da unit. Bled c line. Set 1.8 Released on/ ith tubing hyd Circulate off 00 psi. Press g plug. Swabb 1 in. erforations 13 d 49000# 20-40 in. partment. dge md belief. Operation	AND CEMENT JOB	PLUG AND ABANDONMENT PLUG AND ABANDONMENT PLUG AND ABANDONMENT PLUG AND ABANDONMENT All of starting any proposed Loaded with 29 bb1s 3% plug in F profile at ppled up BOP. TOOH wi 8000 psi above slips. tool. Latch onto to 1500 psi for 5 n. Shut well in. ia 2-7/8" tubing - Shut in for 2 hours. DATE June 10, 1998 TELEPIKME NO. 505/748-1
PULL OR ALTER CASING DTHER: 12 Describe Proposed or Completed Open work) SEE RULE 1103. 6-2-98 - Moved in an KCL. Bled tubing do 12955'. Loaded tubi tubing. 6-3-98 - Rigged up p Nippled down BOP and packer. Flanged up. minutes, OK. Bled o 6-4-98 - Bled down. 6-5-98 - Rigged up t Morrow) with 20000 g Flowing back to pit 6-6-7-98 - Flowed ba 6-8-98 - Released we Ihereby certify that the Information above is the SKONATURE	rations (Clearly state all pertinent de d rigged up pulling wn. Rigged up wire ng and tested plug. ipe testers. TIH w nippled up tree. Tested tree to 60 ff. Pulled blankin Swabbed. Shut wel reesaver. Frac'd p allons 40# CMHPG an for clean up. ck frac. Shut well 11 to production de	COMMENCE C CASING TEST OTHER:_Fra waits, and give pertiment da unit. Bled c line. Set 1.8 Released on/ ith tubing hyd Circulate off 00 psi. Press g plug. Swabb 1 in. erforations 13 d 49000# 20-40 in. partment. dge md belief. Operation	AND CEMENT JOB	PLUG AND ABANDONMENT
PULL OR ALTER CASING DTHER: 12 Describe Proposed or Completed Open work) SEE RULE 1103. 6-2-98 - Moved in an KCL. Bled tubing do 12955'. Loaded tubi tubing. 6-3-98 - Rigged up p Nippled down BOP and packer. Flanged up. minutes, OK. Bled o 6-4-98 - Bled down. 6-5-98 - Rigged up t Morrow) with 20000 g Flowing back to pit 6-6-7-98 - Flowed ba 6-8-98 - Released we I hereby certify that the information above is in SKONATURE TYPE OR FRINT NAME Rusty Klef (This space for State Use) ORIGINAL SI DIST	rations (Clearly state all pertinent de d rigged up pulling wn. Rigged up wire ng and tested plug. ipe testers. TIH w nippled up tree. Tested tree to 60 ff. Pulled blankin Swabbed. Shut wel reesaver. Frac'd p allons 40# CMHPG an for clean up. ck frac. Shut well 11 to production de	COMMENCE C CASING TEST OTHER:Fra ails, and give pertinent da unit. Bled of line. Set 1.8 Released on/ ith tubing hyd Circulate off 00 psi. Press g plug. Swabb 1 in. erforations 13 d 49000# 20-40 in. partment. dge and belief.  S	AND CEMENT JOB	PLUG AND ABANDONMENT