

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-02707</u>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-9116
7. Lease Name or Unit Agreement Name STATE B
8. Well No. 1
9. Pool name or Wildcat Townsend Permo Upper Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3967 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator Charles B. Gillespie, Jr.
3. Address of Operator P.O. Box 8 Midland, Texas 79702
4. Well Location Unit Letter <u>P</u> : <u>3300</u> Feet From The <u>South</u> Line and <u>985</u> Feet From The <u>East</u> Line Section <u>1</u> Township <u>16-S</u> Range <u>35-E</u> NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set Cibp above perforations at 10,400'. Dump 4 SX CMT on yop of plug.
2. Set 100' plug at 8-5/8" casing shoe at 4701'. Tag.
3. Set 100' plug at 5-1/2" liner top at 4527'. Tag.
4. Cut off and pull 8-5/8" casing from approximately 1000'.
5. Set 100' plug at 8-5/8" casing stub. 50' in and 50' out. Tag.
6. Set 100' plug at 13-3/8" casing shoe at 364'. Tag.
7. Set 15 SX plug at surface.
8. Weld 4" marker to surface casing, clean location.

100' plug @ 7500'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kevin Widner TITLE Production Manager DATE 8/11/93
TYPE OR PRINT NAME Kevin Widner TELEPHONE NO. 683-1765

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE AUG 13 1993

CONDITIONS OF APPROVAL, IF ANY: