

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DATE	
SANTA FE	
FILE	
U.S.C.I.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	
B7766	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - "A" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒	GAS WELL ☐	OTHER ☐	7. Unit Agreement Name
Name of Operator			Lovington San Andres Unit
Address of Operator			8. Farm or Lease Name
P. O. Box 728, Hobbs, NM 88240			9. Well No.
Location of Well			57
UNIT LETTER M 660 FEET FROM THE South LINE AND 660 FEET FROM			10. Field and Pool, or Vicinity
THE West LINE, SECTION 36 TOWNSHIP 16S RANGE 36E N.M.P.M.			Lovington San Andres
15. Elevation (Show whether DF, RT, GR, etc.)			12. County
3861' DF			Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

REFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
WELL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	
OTHER ☐			

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU. Pull rods & pump.
- 2) Install BOP. Pull tubing.
- 3) GIH w/6 1/4" bit. Clean out to TD @ 4980'. POH.
- 4) GIH w/RBP and pkr to +4600'.
- 5) Pressure test csg to 500#. Repair if necessary.
- 6) GIH w/6 1/4" bit. Deepen from 4980' to 5140'.
- 7) Run GR-CNL-CAL-CCL 5140'-2500'.
- 8) GIH w/pkr to +4600'. Load backside.
- 9) Acidize San Andres OH 4640-5140 w/10,000 gallons gelled 20% NEFE in 3 stages. use I 1,000# rocksalt in gelled brine between each stage as a block. Mix 2 drums scale inhibitor with the acid (4000#, 5BPM).
- 10) Flow back load.
- 11) GIH w/RBP to +4620'.
- 12) Perforate Grayburg 4400-4620 w/1/4" casg gun casg 2 JSPI (est. 11 int, 22 holes) per GR,CNL, log.
- 13) GIH w/packer to +4300'.
- 14) Acidize GB perms w/5000 gal gelled 15% NEFE AND BALL SEALERS. Mix 1 drum scale inhibitor with the acid (4000#, 5BPM).
- 15) Flow back load.
- 16) Pull RBP.
- 17) Place on production.

ED Jim Browning TITLE District Admin. Supervisor DATE 10/09/86

ORIGINAL SIGNED BY DEPT. SECTION

DISTRICT SUPERVISOR

TITLE

DATE

OCT 17 1986

ADDITIONS OF APPROVAL, IF ANY: