

**Polaris Production Co.  
Plugging Procedure  
Buckley B # 1  
UL E, Sec 25, T14S, R37E**

**13 3/8" CSA 368 ft, Cement w/ 350 sacks, cmt circ  
8 5/8" CSA 4769 ft, Cement w/ 2950 sacks, cmt circ  
5 1/2" CSA 12372 ft, Cement w/ 850 sacks, TOC 7400 stretch  
Open hole from 12372 – 12580 ft**

- 1. Moving rig up plugging unit**
- 2. Nipple up BOP**
- 3. Pull production equipment. Tubing and tubing anchor in well??**
- 4. Run gauge ring by wire line to 12325 ft**
- 5. Pull wire line and tools**
- 6. Run cast iron bridge plug by wire line and set at 12325 ft**
- 7. Pull wire line and tools**
- 8. Run tubing open ended and tag cast iron bridge plug at 12325 ft**
- 9. Displace well with 25#/bbl gelled brine**
- 10. Spot 25 sacks Class "C" cement**
- 11. Pull tubing to 9300 ft**
- 12. Spot 25 sacks Class "C" cement**
- 13. Pull tubing**
- 14. Weld on pull nipple and stretch casing**
- 15. Cut and pull casing from free point**
- 16. Run tubing open ended to 50 inside casing stub**
  - If casing pulls from previous stretch at 7400 ft**
  - Run tubing to 50 ft inside of casing stub**
- 17. Spot 35 sacks Class "C" cement**
- 18. Pull tubing and WOC**
- 19. Run tubing and tag cement , maximum depth 50 ft above stub**
- 20. Pull tubing to 4820 ft**
- 21. Spot 35 sacks cement**
- 22. Pull tubing and WOC**
- 23. Run tubing and tag cement plug, maximum depth 4720 ft**
- 24. Pull tubing to 2150 ft**
- 25. Spot 30 sacks cement**
- 26. Pull tubing to 418 ft**
- 27. Spot 30 sacks cement**
- 28. Pull tubing and WOC**
- 29. Run tubing and tag cement plug, maximum depth is 318 ft**
- 30. Pull tubing to 60 ft**
- 31. Circulate cement to surface**
- 32. Pull tubing**
- 33. Cut off well head and install PA marker**
- 34. Rig down move out service unit**