

DISTRICT I
P.O. Box 1990, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-05254

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

~~503430~~

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Texaco Exploration and Production Inc.

3. Address of Operator

P.O. Box 730 Hobbs, New Mexico 88240

4. Well Location

Unit Letter E : 2287 Feet From The North Line and 990 Feet From The West Line

Section 2

Township 15S

Range 37E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3815' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Notify MHOCD (Hobbs 393-6161) prior to commencing plugging operations.
2. KIRKUPU. POOH with rods. Install BOPE. POOH with 2-7/8" production tubing laying down.
3. BU wireline unit. Set 5-1/2" CISP at \pm 9000'. Cap with 35' Class C cement (4 sk). Tag plug.
4. TIR with 5-1/2" casing spear. Run free point survey. Cut and pull casing. TOC at 4742' by TS.
5. TIR with 9-5/8" casing spear. Run free point survey. Cut and pull casing. TOC calculated at 3100' (50t fill-up).
6. TIR with tubing. Load hole with salt gel mud (10 ppg with 12.5 lbs gel/bbl).
7. Spot 110' cmt plug (25 sk) across 5-1/2" casing stub (4810-4700'). Tag plug.
8. Spot 100' cmt plug (47 sk) across 9-5/8" casing stub (3150-3050'). Tag plug.
9. Spot 100' cmt plug (64 sk) across 13-3/8" casing shoe (370-270'). Tag plug.
10. Spot 15' cmt surface plug (10 sk).
11. Cut off wellhead. Install dry hole marker. Clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

M.C. Duncan

TITLE

Engineer's Assistant

DATE 9-16-91

TYPE OR PRINT NAME

M.C. Duncan

TELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

18 1991