

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions
reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ <i>Injection</i>	7. UNIT AGREEMENT NAME <i>MCA</i>
2. NAME OF OPERATOR <i>CONOCO INC.</i>	8. FARM OR LEASE NAME <i>MCA Unit stry 1</i>
3. ADDRESS OF OPERATOR <i>P.O. Box 460, Hobbs, NM 88240</i>	9. WELL NO. <i>94</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <i>Unit P</i> <i>660' FSW + 660' FSL</i>	10. FIELD AND POOL, OR WILDCAT <i>Maljamar G/SA</i>
14. PERMIT NO. <i>30-025-08063</i>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>Sec. 20, T-17S-R32E</i>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH <i>Lea</i>
	13. STATE <i>NM</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANT ☐
(Other) *Fish & Recomplete* ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. M&L RU. Rel Baker Model R packer @ 3509'. Poon w/2 - 3/8" tby + Model R packer. Set RBP @ 200'. Test RBP to 500 psi. Spot 2 sx sand on RBP. Squeeze cmt holes from 35' to 180' w/100 SXS Class C w/2% CAC 12. WOL 24 hrs.
2. Drill out cmt from surface to 191.2. Circ sand off RBP. Fish junk. Clean out to top of OH pks. Wash over pks + clean out to TS @ 4098.
3. Plug back OH from 4098' to 3700' w/160 ft³ pea gravel. Lag top of pea gravel @ 3700'. Spot 1 sx Cal-Seal on top of pea gravel.
4. Cement Squeeze csg shoe @ 3400' + holes @ 3452' to 3520' w/100 SXS 50/50 Permit Class "C" + 50 sx class "H" Thixotropic cement.

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]* TITLE *Administrative Supervisor* DATE *March 2, 1987*

(This space for reference or State office use)

Org: *San Juan Co. NM*

APPROVED *[Signature]* TITLE *Supervisor* DATE *3-10-87*

CONDITIONS OF APPROVAL, IF ANY:

*See instructions on Reverse Side

Bm - (1) ARCO (2) Citic (1) Peter L... (1) NMCC (3) File

page 1

5. Set pkr @ 3400'. Establish an injection rate w/ fresh water. Set retainer @ 3400'. Cement Squeeze holes @ 3452' to 3520' & the Casing shoe w/100 SXS 50/50 pozmix Class C mixture & 50 SXS Class H thixotropic cement. Flush w/19 bbls fresh water.
6. Prepare wellbore to Cement Squeeze holes at 960' to 980'. Establish a pump-in rate. Set retainer @ 900'. Cement Squeeze holes @ 960' to 980' w/100 SXS Class C Cement w/290 CaCl₂ & 75 SXS Class H thixotropic cement. Lead in w/100 SXS Class C Cement. Tail in w/75 SXS Class H thixotropic cement. Flush w/5.2 bbls fresh water. W.O.C. 24 hours.
7. Drill out retainers, cement, Calseal & pea gravel to T.D. of 4098'. Prepare wellbore for "Puddle-Pack".
8. Establish a circulation rate down working with 24 bbls of 8.4 ppg filtered KCl water w/PH adjusted to 6.8 w/ clayfil or equivalent. Mix 15 bbls resin-pack slurry. Spot 15 bbls resin-pack slurry from 4098' - 4052'. Flush w/22 bbls KCl water. Pressure up to 200 psi if possible. W.O.R. 12 hrs. GIH & tag top of resin.
9. Plug back with pea gravel from 4050' to 3900'. Dump 17 ft³ of pea gravel to plug back from 4050' to 3900'. Tag top of pea gravel to insure that top is at 3900'.
10. Establish a circ. rate down working. Spot 12 bbls resin-pack slurry from 3900' to 3820'. Flush w/20 bbls KCl water. Close pipe rams & SI csg Valve. W.O.R. 24 hrs.
11. Drill out 6-1/4" bit resin-pack and pea gravel to T.D. of 4098'. Underream hole to 7" from 3750' to 3800' and 3900' to 3950'. Circ. hole clean.

12. Run and Cement 5- $\frac{1}{2}$ " 17 lb/ft, nominal weight, Seal-Tech ST/b liner from 4098' to 3100'. Seal in with 100 s/s 50/50 Pozmix Class C. Trip out of hole. WOC 24 hrs.
13. Prepare wellbore to run tie-back stem + tie-back to surface. Mill out cement to top of liner. Test liner top to 1000 psi. Clean out liner + drill out to 4090'.
14. Run + Cement 3100' of 5- $\frac{1}{2}$ ", 17 lb/ft nominal weight, Seal Tech st/b casing tie back to surface. Establish circulation with fresh water. Cement to surface w/300 s/s 50/50 pozmix Class C mixture. WOC 24 hrs.
15. Prepare wellbore for perforating. Perf Guangbung. San Andres w/1 JSPF at 4084 - 4050
4018 - 4002
3938 - 3932
3826 - 3862
3762 - 3738
Set pk @ 3650'.
16. Return MCA NO. 94 to injection not exceeding ²⁰⁰⁰ 1 psi surface injection pressure. Rig down.

RECEIVED
MAR 12 1987
OCD
HOBBS OFFICE