Budget	Bureau	No.	42-R358	.4.
ADDrove				•

Land Office . LAB. CTUCES.

Lasso No. 029509+B

Form 9-881 a (Feb. 1961)

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	X	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

 Artesia, New Mexico, May 29, 1947

 Baish B

 Well No. Input 10 is located 25 ft. from Site in and 50 ft. from Site of sec. 22

 SWISHI Sec. 22

 SWISH Sec. 22
 175

 (Yape)
 (Range)

 Maljamar
 Lea

 (County or Subdivision)
 (State or Territory)

The elevation of the derrick floor above sea level is 4029. ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, comenting points, and all other important proposed work)

After making test for shut-off of 7^{H} casing, drilling was resumed and while making the first run trouble of some nature occurred, by reason of which the tools could not be removed from the well. The tools would come up 19' from bottom and would go back freely, but could not be pulled above that point. The rope was cut and a string of drill pipe was run. We jarred on tools for several days with drill pipe, making no headway. At this time work was suspended.

We will now resume work on this well and will gun-perforate the 7" casing at approximately 3700' which is just above the top of the tools left in the hole. We will then set a retainer and squeeze cement through the tubing to repair any damage that may have occurred to the pipe and/or the original cement job. We will then set a whipstock above the retainer and will mill out through the 7" casing and drill the well to completion, and will core at least all the producing zones and probably will core the entire distance. This above outlined plan is in conformity with our discussion with Company Buffalo Oil Company Mr. Frank B. Stahl.

Address Box 265

Artesia, New Mexico

By ____/S/_ H. G. Ellis

•

Title Superintendent

GPO 918507