

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.  
10666

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name ---
2. Name of Operator Polaris Production Corp.	8. Farm or Lease Name Lee Carter
3. Address of Operator P. O. Box 1749, Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER M 510 FEET FROM THE West LINE AND 660 FEET FROM THE South LINE, SECTION 14 TOWNSHIP 15-S RANGE 38-E NMPM.	10. Field and Pool, or Wildcat Medicine Rock (Dev.)
15. Elevation (Show whether DF, RT, GR, etc.) 3736' GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The following work is proposed to begin on 12-19-88 @ 8:00 a.m. New Mexico time (48 hrs. notice will be given before actual operations begin).

1. Set CIBP & 3 sx cmt @ 12,750'.
2. Load hole w/ 9.5# mud.
3. Shoot & recover 9500' of 4 1/2" csg.
4. Set plugs as follows:  
20 sx @ 9550-9450'  
25 sx @ 8193-8093'  
30 sx @ 6460-6360'  
30 sx @ 4954-4854'
5. Shoot & recover 1500' of 8 5/8" csg.
6. Set plugs as follows:  
60 sx @ 1480-1380'  
10 sx & marker @ surface

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE President DATE 11-1-88

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: