to Appropriate District Office	State of New Mer Enery Ainerals and Natural Res		Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATIO		WELL API NO.
P.O. Box 1980, Hobba, NM 88240 P.O. Box 2088 DISTRICT II Santa Fe, New Mexico 87504-2088		30-025-212026	
P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No. VA - 433
SUNDRY NOT	ICES AND REPORTS ON WEL	LS	
(DO NOT USE THIS FORM FOR PRO DIFFERENT RESE (FORM C	OPOSALS TO DRILL OR TO DEEPEN RVOIR. USE "APPLICATION FOR PER D-101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
. Type of Well: OB. OAS WELL X WELL	OTHER		Maljamar APB State
. Name of Operator 8. W		8. Well No.	
YATES PETROLEUM CORPORATION		9. Pool name or Wildcat	
		Maljamar Grayburg San Andres	
I. Well Location		·····	Indijamar ordyburg ban indreb
Unit Letter P : 60	60 Feet From The South	Line and 660) Feet From The East Line
Section 34	Township 16S Ray	nge 32E	NMPM Lea County
7//////////////////////////////////////	10. Elevation (Show whether I		
		87' GR	
	Appropriate Box to Indicate N		
NOTICE OF IN	TENTION TO:	SU	
		REMEDIAL WORK	
LL OR ALTER CASING			
DTHER:		OTHER: Re-entry	
work) SEE RULE 1103.			uding estimated date of starting any proposed
location and cleaned unit. Nippled up and plugging mud at 4237 Tagged cement plug at psi. TOOH with tubin 4438'. Circulated ho wireline. Prep to 10 7-31-96 - TIH with 10 TIH with 8-5/8" CIBP Bigged down wireline	location. Set and test d tested BOP. TIH with '. Tested 8-5/8" casing t 4311'. Drilled cemen ng, collars and bit. T ole with 2% KCL. TOOH og. NOTE: Spudded at 2 ogging tools and ran CN . CIBP hung up at 3463 . TIH with bit, collar TOOH with tubing. co	ted anchors. No. bit, collars a g to 1500 psi. t plug down to IH with bit, so with tubing, so 2:00 PM 7-29-96 L/GR/CCL log. '. Set CIBP a s and 2-7/8" to 1lars and bit.	TOOH with logging tools. t 3463'. TOOH with wireline. ubing. Drilled CIBP out and Rigged up wireline. TIH with
pushed down to 4500' gauge ring to 4500'. CIBP with 35' of cem I hereby certify that the information above if the true to the second se	TOOH with gauge ring. nent. Tested CIBP to 15 faue and complete to the best of my knowledge and	TIH with 8-5 00 psi. Rigger Ibdid.	/8" CIBP and set at 4455'. Capped d down wireline. Prep to perf.
pushed down to 4500' gauge ring to 4500'. CIBP with 35' of cem I hereby certify that the information above into SKONATURE	TOOH with gauge ring. ment. Tested CIBP to 15 fore and complete to the best of my knowledge and unk m	TIH with 8-5 00 psi. Rigger Ibdid.	/8" CIBP and set at 4455'. Capped
pushed down to 4500' gauge ring to 4500'. CIBP with 35' of cem I hereby certify that the information above into SHONATURE HISTORY RUSTY TYPE OR FRINT NAME Rusty Kleit	TOOH with gauge ring. ment. Tested CIBP to 15 fore and complete to the best of my knowledge and unk m	TIH with 8-5 00 psi. Rigger Ibdid.	/8" CIBP and set at 4455'. Capped d down wireline. Prep to perf. Technician DATE July 31, 1996 TELEPHONE NO. 505/748-14
pushed down to 4500' gauge ring to 4500'. CIBP with 35' of cem I hereby certify that the information above into SKONATURE	TOOH with gauge ring. ment. Tested CIBP to 15 fore and complete to the best of my knowledge and unk m	TIH with 8-5 00 psi. Rigger Ibdid.	/8" CIBP and set at 4455'. Capped d down wireline. Prep to perf. Technician July 31, 1996