

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER ☐

2. Name of Operator

Union Oil Company of California

3. Address of Operator

P. O. Box 671 - Midland, Texas 79702

4. Well Location

Unit Letter N : 766 Feet From The south Line and 2086 Feet From The west Line

Section 12

Township 15-S

Range 34-E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

7. Lease Name or Unit Agreement Name

Reed

8. Well No.

1

9. Pool name or Wildcat

Morton (Wolfcamp)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Notify NMOC. MIRUDDPU & plugging equip. Dig work pit. NU BOP. 2. Rig up wireline unit. RIH w/5 1/2" CIBP and set @ 10,200'±. RD wireline unit. 3. Pick up workstring and RIH open-ended to CIBP. Mix mud and circulate the hole w/10# gal. MLF. Spot 15 sacks of cmt on top of CIBP. 4. PUH w/tbg to 8100' and spot a 24 sack cmt plug. 5. PUH w/tbg to 6100' and spot a 25 sack cmt plug. POOH w/tbg. 6. ND BOP and wellhead. Weld on a 5 1/2" pull nipple. Pull on casing, remove casing slips and determine free point from from stretch. Cut casing at free point (5500'±). 7. POOH w/csg and lay down.

(Continued Page 2)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Drilling Engineer

DATE 7-18-89

TYPE OR PRINT NAME

Jeffery J. Tokarsky

TELEPHONE NO. 915 682-9731

(This space for State Use)

Orig. Signed by  
**Paul Kautz**  
Geologist

APPROVED BY

TITLE

DATE

**JUL 21 1989**

CONDITIONS OF APPROVAL, IF ANY:

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

RECEIVED

JUL 20 1989

OCD  
MORAS OFFICE

Reed Well No. 1  
Condition of Hole and Procedure

Page 2

8. RIH w/tubing open-ended to 50' below casing stub and spot a 40 sack cement plug leaving 50' below the stub and 50' above the stub. PUH, WOC and tag.
9. When plug tags okay, PUH w/tubing to 4655' and spot a 80 sack cement plug. PUH, WOC, and tag. When plug tags okay, POOH w/tubing.
10. ND wellhead. Weld on an 8-5/8" pull nipple. Pull on casing, remove casing slips and determine free point from stretch. Cut casing at free point (3000'±).
11. POOH w/casing and lay down.
12. RIH w/tubing open-ended to 50' below casing stub and spot a 60 sack cement plug leaving 50' below the stub and 50' above the stub. PUH, WOC and tag.
13. When plug tags okay, PUH w/tubing to 1950' and spot a 65 sack cement plug.
14. PUH w/tubing to 1600' and spot a 65 sack cement plug.
15. PUH w/tubing to 404' and spot a 50 sack cement plug. POOH w/tubing.
16. Cut wellhead off 3' below ground level and place a 10 sack cement plug in surface. Rig down equipment and move off location.