NO. OF COPIES RECEIVED		
DISTRIBUTION		Form C-103 Supersedes Old
SANTA FE		C-102 and C-103
FILE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State 🕅 Fee
OPERATOR		5. State Oil & Gas Lease No.
		K-6234
SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
1. OIL CAS CAS CONTRER. Reentry - dry		7. Unit Agreement Name
2. Name of Operator	· · · · · · · · · · · · · · · · · · ·	8. Farm or Lease Name
Manzano Oil Corporation 505/623-1996		Apple State
3. Address of Operator		9. Well No.
P.O. Box 571, Roswell, NM 88202-0571		1
4. Location of Well		10, Field and Pool, or Wildcat
UNIT LETTER B	330 FEET FROM THE NORTH LINE AND 2310 FEET FR	
•		
East	34 TOWNSHIP 16S RANGE 33E	
	RANGE NMP	ω.ΥΠΠΠΠΠΠΠΠΙΧ
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4194' GR	Lea
16. Check A	ppropriate Box To Indicate Nature of Notice, Report or (Other Data
NOTICE OF INT		NT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON K REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
OTHER		

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9/23/86 to 10/17/86	Tagged plug back total depth @ 10,953', pulled up to 10,919' & spotted 200 gal 10% acetic acid. Swabbed casing down to 7000', welded 8-5/8" casing back to surface casing. Ran correlation logs & found wireline plug back total depth @ 10,924'. Perfed 10,836-10,838' w/3 holes & 10,870-10,888' w/19 holes. Acidized with 2000 gallons 15% NEFE w/packer @ 10,769. Packer leaked. Pulled packer & reset @ 10,769' & reacidized with 6500 gallons 20%
10/18/86	NEFE acid and 8000 gallons gelled water. Swabbed & tested well. Set pump jack & hung well on - tested well on pump until 12/30/86.
1/6/87	Prep to plug and abandon well as follows: Will attempt to recover approximately 6000' of 4-1/2" casing which was set and cemented at 11,008' (leave approximately 5008' in hole.) Will attempt to shoot off 8-5/8" casing at top of cement, 3000', and pull remainder of 8-5/8" (4218'-3000' = 1218'). Will then set the following plugs: Plug #1 - 35' within 100' above perfs. Plug #2 - 50' in and 50' out of stub of 4-1/2" casing. Plug #3 - 100' plug at 5960'(top of Glorietta 5963') Plug #4 - 50' in and out of stub of 8-5/8" casing. 10 sx at surface and set dry hole marker.
18. I hereby certify the	I'S CI - F K
ORIGINA	AL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR



.