

COPIES RECEIVED		
TRIBUTION		
FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K 2867-1	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Plugged & Abandoned		7. Unit Agreement Name
2. Name of Operator UNION TEXAS PETROLEUM CORPORATION		8. Farm or Lease Name New Mexico "15"
3. Address of Operator 1300 Wilco Building, Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER <u>0</u> , <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>15</u> TOWNSHIP <u>15-S</u> RANGE <u>32-E</u> NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Re-entered well and drilled out cement plug to 38' (10-1-74)
2. Moved bit to 1842' and drilled out plug to 1938'.
3. cut off the 8 5/8" casing @ 3000' and pulled this casing.
4. Set 35 Sx. cement plug @ 3030' to 2920' (8 5/8" stub @ 3000')
5. Set 35 Sx. cement plug @ 1550' to 1450'.
6. Set 35 Sx. cement plug @ 465' to 365'.
7. Set 10 Sx. cement plug in top of 11 3/4" surface casing with a dry hole marker.
8. Well is now permanently plugged and abandoned (10-9-74)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Stanley A. Post TITLE Gas Measurement Analyst DATE 10-11-74
APPROVED BY John W. Runyan TITLE Geologist DATE 10-11-74
CONDITIONS OF APPROVAL, IF ANY: