

NO. OF COPIES RECEIVED	
DISTRIBUTION	
ANYA FE	
ILE	
U.S.G.S.	
AND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
Getty Oil Company

Address of Operator
P. O. Drawer DD, Levelland, Texas 79336

Location of Well
UNIT LETTER **D** **960** FEET FROM THE **North** LINE AND **760** FEET FROM
THE **West** LINE, SECTION **2** TOWNSHIP **17-S** RANGE **33-E** N.M.P.M.

15. Elevation (Show whether DF, RT, CR, etc.)
4182' DF

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
K-4182

7. Unit Agreement Name

6. Form of Lease Name
Sun 2 State

9. Well No.
1

10. Field and Pool, or Wildcat
Sammal Penn

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK ☐ ALTERING CASING ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐ OTHER ☐ CASING TEST AND CEMENT JOBS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

PLUGGING PROCEDURE:

1. POH w/rods, pump & tbq.. Lay down rods.
2. GIH w/B.P. on tbq. & set B.P. @ 11,400'. Load hole w/9.5# mud. Spot 30' of cement on top. POH w/tbg.
3. Run Free-Point on 5½" csg. & cut @ Free-pt.
4. Pull csg. & lay down.
5. GIH w/tbg. open ended. Circulate hole full mud. Spot 100' cement plug in and out of 5½" csg. stub. Raise tbq. above plug and circulate hole clean. Raise tbq. and WOC 6 hrs. Tag plug. Repeat spotting plug if necessary.
6. If Wolfcamp, ABO, and Glorieta are exposed set 100' plug at top of each Zone.
7. Set 100' plug in and out of the 8-5/8" casing shoe @ 4540'. WOC for 6 hr. & tag. Repeat setting plug if necessary.
8. Spot 100' plug at top of salt suction inside 8-5/8" csg. 1550' to 1650'.
9. Pull to surface & set 10 sx. plug in-surface and cellar. Install abandoned hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E. P. Morales E. P. Morales TITLE Area Engineer

DATE 2-12-80

PROVED BY Jerry Sertea
Dist. 1, Supv.
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE FEB 18 1980

RECEIVED

FEB 14 '80

OIL CONSERVATION DIV.