N.M. Oil Cons. Division.

DEPARTMEN BUREAU OF I SUNDRY NOTICES Do not use this form for proposals to dri	TED STATES N.W. On COMO. Property of THE INTER 1625 N. French Dr. LAND MANAGEMENT HOBBS, NM 88240 AND REPORTS ON WELLS Il or to deepen or reentry to a different reservoir.	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 3 1,1993 5. Lease Designation and Serial No. LC 029509A 6. If Indian, Allottee or Tribe Name
	R PERMIT—" for such proposals IN TRIPLICA TE	7. If Unit or CA, Agreement Designation
		8. Well Name and No. MCA Unit #340 9. API Well No. 30-025-24461 10. Field and Pool, or Exploratory Area Maljamar Grayburg/SA 11. County or Parish, State Lea, NM RT. OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
13. Describe Proposed or Completed Operations (Clearly state all give subsurface locations and measured and true vertice. Conoco plans to plug and abandon this well ac	pertinent details, and give pertinent dates, including estimated date of starting cal depths for all markers and zones pertinent to this work.)* cording to the attached procedure.	g any proposed work. If well is directionally drilled,

APPROVED FOR 3 MONTH PERCE

or representations as to any matter within its jurisdiction.

alyst Date 12/5/02
Date
1

MCA Unit #340

Surface casing: 8-5/8" @ 851' cmt'd w/ 425 sx, circulated

Production csg: 5-1/2" 14# csg @ 4,175' cmt'd w/ 375 sx, TOC @ 2,550' by

temperature survey

Perforations: 3,771 – 3,893'; RBP @ 3,750' set 6/2/92

1. MIRU plugging equipment. NU BOP

2. RIH w/ tubing to PBTD @ 3,750'. Circulate hole w/ plugging mud and pump 25 sx C cmt on RBP.

3. Perforate 5-1/2" casing @ 1,000' (est. top of salt).

4. Squeeze 90 sx C cmt under packer 1,000 - 800'.

5. WOC and tag cement no deeper than 800'.

6. Pump 10 sx C cmt 50' to surface.

7. Cut off wellhead and install dryhole marker. Cut off anchors & close working pit.