

CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103

Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-		7. Unit Agreement Name
2. Name of Operator The Superior Oil Company		8. Farm or Lease Name State, D.J.
3. Address of Operator P. O. Box 3901, Midland, Texas 79702		9. Well No. 1
4. Location of Well UNIT LETTER <u>F</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>25</u> TOWNSHIP <u>15S</u> RANGE <u>32E</u> NMPM.		10. Field and Pool, or Wildcat South Sanders Permo Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4250.6' GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
FULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Actual P&A Operations

- Set CIBP @10,420', dump 35' ± Class H cmt on top, WOC 4 ± hrs, test cmt to 1000# on 11-1-83.
- Determine free point of 5½" csg (TOC @approx 8690').
- Cut & retrieve 5½" csg at free point @8661'.
- Spot 100' cmt plug @top of 5½" csg (8610'-8710') w/50 ± sx Class H neat cmt. Displace cmt w/ gelled 10# brine, tag top of cmt plug.
- Spot 100' cmt plug @top of Glorieta formation 5595-5695' (7 7/8" open hole) w/approx 75 sxs Class H neat cmt, displace w/gelled 10# brine, tag top of cmt plug.
- Spot 100' cmt plug across 8-5/8" csg shoe (4227'-5327') w/approx 60 sxs Class H neat cmt. Displace w/gelled 10# brine, tag top of cmt plug.
- Spot 100' cmt plug in 8-5/8" csg from 1572-1672' w/approx 35 sxs Class H neat cmt, displace w/gelled 10# brine, tag top of cmt plug.
- Spot 10 sxs Class H cmt at surface
- Cut csg off 3' below ground level and weld on steel plate w/4' marker above ground, clean and level location.
- P&A on 11-10-83.

6. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed D. E. Lutz TITLE Division Operations Supt. DATE 12-28-83
 Approved by Ronald M. [Signature] TITLE OIL & GAS INSPECTOR DATE MAY 24 1984
 CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
FEB 30 1983
O.F.D.
MOBILITY OFFICE