

**Leigh Operating Co.
Caudill State # 1
API # 30-025-27461
UL K, Sec 26, T15S, R36E
Plugging Procedure**

13 3/8" csg set 420 feet, Cement Circulated

9 5/8" csg set 4981 feet, Cemented with 1300 sacks, Calculated cement should have circulated in gauge hole

5 1/2" csg set 13780 feet, Cement with 1950 sacks, Calculated TOC 4671 feet

Perfs 13730-13748 feet

1. Move in rig up plugging rig
2. Nipple up BOP
3. Pull production equipment
4. Run gauge ring with wire line to 13690 feet
5. Pull wire line and tools
6. Run and set Cast Iron Bridge Plug at 13690 feet
7. Cap CIBP with 35 feet of cement with dump bailer
8. Run tubing open ended and tag cement at 13655 feet
9. Displace well with gelled brine water
10. Pull tubing to 11542 feet
11. Spot 25 sack cement plug
12. Pull tubing to 8350 feet
13. Spot 25 sack cement plug
14. Pull tubing to 6525 feet
15. Spot 25 sack cement plug
16. Pull tubing to 5031 feet
17. Spot 25 sack cement plug
18. Pull tubing and WOC
19. Run tubing and tag cement plug, Maximum depth 4931 feet
20. Weld on pull nipple and stretch casing
21. Cut and pull casing from 4000 feet if free
22. Run tubing to 50 feet inside of casing stub
23. Spot 40 sack cement plug
24. Pull tubing and WOC
25. Run tubing and tag cement plug, Maximum depth is 50 feet above casing stub
26. Pull tubing to 2075 feet
27. Spot 40 sack cement plug
28. Pull tubing to 470 feet
29. Spot 40 sack cement plug
30. Pull tubing and WOC
31. Run tubing and tag cement plug, Maximum depth 370 feet
32. Pull tubing to 60 feet
33. Circulate cement to surface
34. Pull tubing
35. Cut off wellhead and install PA marker
36. Rig down move out plugging rig
37. Cut off service unit anchors and clean location