

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Marathon Oil Company	8. Farm or Lease Name A. C. Taylor
3. Address of Operator P.O. Box 2409, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>0</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>35</u> TOWNSHIP <u>16S</u> RANGE <u>32E</u> NMPM.	10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 4256 GR, 4270 KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Completion Operations</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rigged up and pulled rods and pump on 3-1-83. Rigged up Jarrel Wireline and ran 72 hour buildup test. Ran back in the hole with the rods and pump. Started well pumping to a frac tank. The rods parted after 3 days on pump. Fished the rods and pulled out of the hole with rods and pump. Pulled out of the hole with the tubing. Rigged up Welex and set a 5-1/2" CIBP at 3850' and dumped two sacks of cement on top of CIBP. Perforated the casing with 1 JSPF from 3450 - 3470 and 3758 - 3768 for a total of 32 holes. Rigged up Halliburton and set an Rtts packer at 3725' and acidized the perforations from 3758 - 3768 with 1500 gallons of 15% acid. Presently swabbing back the acid load.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Steven A. Pohler TITLE Production Engineer DATE 3-11-83

APPROVED BY DISTRICT SUPERVISOR TITLE DATE MAR 15 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR 14 1983

O.C.D.
HOBBS OFFICE