

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Exxon Corporation		8. Farm or Lease Name Hulda A. Townsend A/C-2
3. Address of Operator P.O. Box 1600, Midland, TX 79702		9. Well No. 11
4. Location of Well UNIT LETTER <u>K</u> <u>1830</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM <u>West</u> <u>9</u> TOWNSHIP <u>16S</u> RANGE <u>35E</u> NMPM. THE <u>LINE, SECTION</u> <u>TOWNSHIP</u> <u>RANGE</u>		10. Field and Pool, or Wildcat Townsend-Permo (Upper Penn
15. Elevation (Show whether DF, RT, CR, etc.) 4015-GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- MIRU. POH with rods. Install shop tested BOP's ad POH w/tubing.
- RIF up wireline. Make a gauge ring run to top of Perfs. If scale or paraffin is found on production equipment make a bit run only if necessary.
- RIH with CIBP and set at 10140' use wireline measurement if collar log is unavailable.
- RIH and dump bail 35' of cement on CIBP. RD wireline.
- RIH with tubing and circulate with inhibited fresh water containing 10 gals. C-7672 and 20 gals. C-7720 per 100 bbls.
- Pressure test to 500#.
- RIH with rods and RDMO.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Jeanne Whitlock</u>	TITLE <u>Office Assistant</u>	DATE <u>5/22/86</u>
ORIGINAL SIGNED BY JERRY SEXTON		
APPROVED BY <u>DISTRICT 1 SUPERVISOR</u>	TITLE	DATE <u>JUN 2 1986</u>
CONDITIONS OF APPROVAL, IF ANY:		