

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Union Oil Company of California

3. Address of Operator

P. O. Box 671 - Midland, Texas 79702

4. Well Location

Unit Letter K : 1870 Feet From The south Line and 2080 Feet From The west Line

Section 12

Township 15-S

Range 34-E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4063' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

See attached

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bobby Bryan TITLE Drilling Superintendent DATE 12-19-89

TYPE OR PRINT NAME Bobby Bryan

TELEPHONE NO. (915) 682-9731

(This space for State Use)

OIL & GAS INSPECTOR

APPROVED BY Jack Griffin TITLE _____ DATE APR 6 1990

CONDITIONS OF APPROVAL, IF ANY:

Reed Well No. 2
Morton (Wolfcamp) Field

12-11-89-MIRU Pool Well Service-POH-LD R&P. NU BOP. TOH w/2 7/8" tbg.

12-12-89-Set CIBP on WL @ 9826'-RIH w/2 7/8" tbg open ended to 9826'. Circ hole w/10# mud. Spot 15 sxs Cl "C" cmt from 9826'-9745'. PU to 8100'. Spot 25 sxs Cl "C" cmt f/8100'-7850'. PU to 6100'. Spot 25 sxs Cl "C" cmt f/6100'-5850'.

12-13-89-Spot 25 sxs Cl "C" cmt f/4666'-4416'. POOH. ND BOP & well head. Weld on pull nipple-Freepoint 5 1/2" csg @ 2604'. Cut csg @ 2566'. Csg not free. Cut 5 1/2" csg @ 2292'. Pull out & lay down 30 jts + 2 pcs of 5 1/2" csg.

12-14-89-PO & LD 5 1/2" csg. Rec 60 jts + 2 pcs. RIH w/2 7/8" tbg to 2616'. Spot 60 sxs Cl "C" cmt f/2616'-2190'. PU to 1200', WOC.

12-15-89-Ran oe'd 2 7/8" tbg to TOC @ 2180'. Witnessed by NM O&G Comm. Rep. PUH to 1900'. Sptd 140 sxs f/1900'-1360'. PUH to 456'. Sptd 30 sxs Cl "C" f/456'-336'. TOH w/tbg. Cut off Well head. Pump 10 sxs -sur-face plug f/30'. Weld on P&A marker. RDMODDPU. Well P&A'ed 12-15-89.