ubmit 3 Copies Appropriate istrict Office	-	New Mexico atural Resources Department	Form C-103 Revised 1-1-89
ISTRICT I		ATION DIVISION	WELL API NO.
O. Box 1980, Hobbs, NM 88240		Box 2088	30-025-30398
ISTRICT II O. Drawer DD, Artesia, NM 88210	Santa Fe, New I	Mexico 87504-2088	5. Indicate Type of Lease STATE X FEE
<u>ISTRICT III</u> 000 Rio Brazos Rd., Aztec, NM 874	110		6. State Oil & Gas Lease No. V-148
	IOTICES AND REPORTS	ON WELLS	
DO NOT USE THIS FORM FOR DIFFERENT R		DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
Type of Well: OIL GAS WELL X WELL	C OTHER		Doubloon State 24P
Name of Operator			8. Well No.
Nearburg Producing	Company		1
Address of Operator	-		9. Pool name or Wildcat
P. 0. Box 823085, Well Location	Dallas, Texas 75382-	-3085	Lovington Wolfcamp
Section 24	3,840.7	ww.whether DF, RKB, RT, GR, etc.) 7 'GR	NMPM Lea County
	xk Appropriate Box to In INTENTION TO:	ndicate Nature of Notice, I	Report, or Other Data BSEQUENT REPORT OF:
	PLUG AND ABANDO	N REMEDIAL WORK	ALTERING CASING
Г			
	CHANGE PLANS		
Г		CASING TEST AND	
EMPORARILY ABANDON ULL OR ALTER CASING THER: 2. Describe Proposed or Completed work) SEE RULE 1103.	CHANGE PLANS	COMMENCE DRILLIN CASING TEST AND C OTHER:	IG OPNS. PLUG AND ABANDONMENT
EMPORARILY ABANDON ULL OR ALTER CASING THER: Describe Proposed or Completed work) SEE RULE 1103. 03/06/92 TIH with plug fro top of p	CHANGE PLANS Operations (Clearly state all pertinent tubing. Loaded ho m 10,112' to 9,960 olug at 10,000'.	COMMENCE DRILLIN CASING TEST AND CONTHER: OTHER: details, and give pertinent dates, inco ole with 9.0# salt ba '. Pulled 5 stands.	AG OPNS. PLUG AND ABANDONMENT
EMPORARILY ABANDON [ JLL OR ALTER CASING [ THER: 2. Describe Proposed or Completed work) SEE RULE 1103. 03/06/92 TIH with plug fro top of p 03/07/92 Spotted from 4,2	CHANGE PLANS Operations (Clearly state all periment tubing. Loaded ho om 10,112' to 9,960 olug at 10,000'. 30 sx cement plug 250' to 4,150'. POH Established circul	COMMENCE DRILLIN CASING TEST AND C OTHER: details, and give pertinent dates, inc ole with 9.0# salt ba '. Pulled 5 stands. from 6,200' to 6,100 with 2-3/8" tubing ation pumping down 4	AG OPNS. PLUG AND ABANDONMENT CEMENT JOB Auding estimated date of starting any proposed Ase gel. Spotted 7 sx cement Circulated 2 hours. Tagged C. Spotted 35 sx cement plug WOC 3-1/2 hours. Pump down 4-1/2" casing and out through
EMPORARILY ABANDON [ JLL OR ALTER CASING [ THER: 2. Describe Proposed or Completed work) SEE RULE 1103. 03/06/92 TIH with plug fro top of p 03/07/92 Spotted from 4,2 casing. 4-1/2" a down tub	CHANGE PLANS Operations (Clearly state all perimer tubing. Loaded ho m 10,112' to 9,960 olug at 10,000'. 30 sx cement plug 250' to 4,150'. POH Established circula and 8-5/8" casing a ping and out 4-1/2"	COMMENCE DRILLIN CASING TEST AND C OTHER: U details, and give pertinent dates, inc ole with 9.0# salt ba '. Pulled 5 stands. from 6,200' to 6,100 with 2-3/8" tubing ation pumping down 4 nnulus. Set 4-1/2" p x 8-5/8" casing at	AG OPNS. PLUG AND ABANDONMENT DEMENT JOB Auding estimated date of starting any proposed Auding estimated date of starting a
EMPORARILY ABANDON [ JLL OR ALTER CASING [ THER: 22. Describe Proposed or Completed work) SEE RULE 1103. 03/06/92 TIH with plug fro top of p 03/07/92 Spotted from 4,2 casing. 4-1/2" a down tub inside 4 Class '0	CHANGE PLANS Operations (Clearly state all periment tubing. Loaded ho om 10,112' to 9,960 lug at 10,000'. 30 sx cement plug 250' to 4,150'. POH Established circula and 8-5/8" casing a oing and out 4-1/2" -1/2" casing at 2, 2'. Good returns bu	COMMENCE DRILLIN CASING TEST AND C OTHER: details, and give pertinent dates, inc ole with 9.0# salt ba '. Pulled 5 stands. from 6,200' to 6,100 with 2-3/8" tubing ation pumping down 4 nulus. Set 4-1/2" p x 8-5/8" casing at 780'. Squeezed with t did not circulate	AG OPNS. PLUG AND ABANDONMENT DEMENT JOB Auding estimated date of starting any proposed Auding estimated date of starting estimated date of starting estimated date of star
EMPORARILY ABANDON [JLL OR ALTER CASING [THER:	CHANGE PLANS Operations (Clearly state all periment tubing. Loaded ho om 10,112' to 9,960 lug at 10,000'. 30 sx cement plug 250' to 4,150'. POH Established circula oing and out 4-1/2" -1/2" casing at 2, C. Good returns bu Spotted 10 sx plu	COMMENCE DRILLIN CASING TEST AND C OTHER: details, and give pertinent dates, inc ole with 9.0# salt ba '. Pulled 5 stands. from 6,200' to 6,100 with 2-3/8" tubing ation pumping down 4 nuulus. Set 4-1/2" p x 8-5/8" casing at 780'. Squeezed with t did not circulate g at surface.	AG OPNS. PLUG AND ABANDONMENT CEMENT JOB Juding estimated date of starting any proposed Augustic starting any proposed Aug
EMPORARILY ABANDON JLL OR ALTER CASING THER: 2 Describe Proposed or Completed work) SEE RULE 1103. 03/06/92 TIH with plug from top of p 03/07/92 Spotted from 4,2 casing. 4-1/2" a down tub inside 4 Class 'C at 251'. 03/09/92 Cut off I hereby certify that the information above	CHANGE PLANS Operations (Clearly state all periment tubing. Loaded ho om 10,112' to 9,960 olug at 10,000'. 30 sx cement plug 50' to 4,150'. POH Established circula and 8-5/8" casing a oing and out 4-1/2" 1/2" casing at 2, C. Good returns bu Spotted 10 sx plu wellhead and casing re is true and complete to the best of my to	COMMENCE DRILLIN CASING TEST AND CONTHER: CASING TEST AND CONTHER: COT	AG OPNS. PLUG AND ABANDONMENT CEMENT JOB Auding estimated date of starting any proposed Auding estimated date of starting a
EMPORARILY ABANDON JLL OR ALTER CASING THER: 2 Describe Proposed or Completed work) SEE RULE 1103. 03/06/92 TIH with plug from top of p 03/07/92 Spotted from 4,2 casing. 4-1/2" a down tub inside 4 Class 'C at 251'. 03/09/92 Cut off I hereby certify that the information above	CHANGE PLANS Operations (Clearly state all periment tubing. Loaded ho om 10,112' to 9,960 olug at 10,000'. 30 sx cement plug 50' to 4,150'. POH Established circula and 8-5/8" casing a oing and out 4-1/2" 1/2" casing at 2, C. Good returns bu Spotted 10 sx plu wellhead and casing re is true and complete to the best of my to	COMMENCE DRILLIN CASING TEST AND C OTHER: U details, and give pertinent dates, inc ole with 9.0# salt ba '. Pulled 5 stands. from 6,200' to 6,100 with 2-3/8" tubing ation pumping down 4 nnulus. Set 4-1/2" p x 8-5/8" casing at 780'. Squeezed with t did not circulate g at surface. 3' below ground. In	AG OPNS. PLUG AND ABANDONMENT CEMENT JOB Auding estimated date of starting any proposed Auding estimated date of starting estimated date of starting estimated date of star
EMPORARILY ABANDON JUL OR ALTER CASING THER: 22. Describe Proposed or Completed work) SEE RULE 1103. 03/06/92 TIH with plug fro top of p 03/07/92 Spotted from 4,2 casing. 4-1/2" a down tub inside 4 Class 'C at 251'. 03/09/92 Cut off Thereby certify that the information above SIGNATURE	CHANGE PLANS Operations (Clearly state all periment tubing. Loaded ho om 10,112' to 9,960 olug at 10,000'. 30 sx cement plug 50' to 4,150'. POH Established circula and 8-5/8" casing a oing and out 4-1/2" 1/2" casing at 2, C. Good returns bu Spotted 10 sx plu wellhead and casing re is true and complete to the best of my to	COMMENCE DRILLIN CASING TEST AND CONTHER: CASING TEST AND CONTHER: COT	AG OPNS. PLUG AND ABANDONMENT CEMENT JOB Auding estimated date of starting any proposed Auding estimated date of starting a
EMPORARILY ABANDON JUL OR ALTER CASING THER: 22. Describe Proposed or Completed work) SEE RULE 1103. 03/06/92 TIH with plug fro top of p 03/07/92 Spotted from 4,2 casing. 4-1/2" a down tub inside 4 Class 'C at 251'. 03/09/92 Cut off Thereby certify that the information above SIGNATURE	CHANGE PLANS Operations (Clearly state all perimen tubing. Loaded he om 10,112' to 9,960 lug at 10,000'. 30 sx cement plug 50' to 4,150'. POH Established circula to 4,150'. POH Established circula oing and out 4-1/2" -1/2" casing at 2, 2'. Good returns bu Spotted 10 sx plu wellhead and casing	COMMENCE DRILLIN CASING TEST AND CONTHER: CASING TEST AND CONTHER: COT	AG OPNS. PLUG AND ABANDONMENT DEMENT JOB Huding estimated date of starting any proposed August Spotted 7 sx cement Circulated 2 hours. Tagged Spotted 35 sx cement plug WOC 3-1/2 hours. Pump down H-1/2" casing and out through Dacker at 2,800'. Circulated 2.5 BPM. Set cement retainer 400 sx Howco Lite and 50 sx cement. Calculate cement top Installed dry hole marker. Analyst <u>A/2/92</u> TELEPHONE NO.214/739-11
EMPORARILY ABANDON JUL OR ALTER CASING THER: 2. Describe Proposed or Completed work) SEE RULE 1103. 03/06/92 TIH with plug fro top of p 03/07/92 Spotted from 4,2 casing. 4-1/2" a down tub inside 4 Class 'C at 251'. 03/09/92 Cut off I hereby certify that the information abov signature TYPE OR PRINT NAME Mild	CHANGE PLANS Operations (Clearly state all perimen tubing. Loaded he om 10,112' to 9,960 lug at 10,000'. 30 sx cement plug 50' to 4,150'. POH Established circula to 4,150'. POH Established circula oing and out 4-1/2" -1/2" casing at 2, 2'. Good returns bu Spotted 10 sx plu wellhead and casing	COMMENCE DRILLIN CASING TEST AND CONTHER: CASING TEST AND CONTHER: COT	AG OPNS. PLUG AND ABANDONMENT CEMENT JOB Auding estimated date of starting any proposed Auding estimated date of starting estimated date of starting estimated date of star
EMPORARILY ABANDON JUL OR ALTER CASING THER:  2. Describe Proposed or Completed work) SEE RULE 1103. 03/06/92 TIH with plug fro top of p 03/07/92 Spotted from 4,2 casing. 4-1/2" a down tub inside 4 Class 'C at 251'. 03/09/92 Cut off I hereby certify that the information above sionature TYPE OR PRINT NAME Mild (This space for State Use)	CHANGE PLANS Operations (Clearly state all perimen tubing. Loaded he om 10,112' to 9,960 lug at 10,000'. 30 sx cement plug 50' to 4,150'. POH Established circula to 4,150'. POH Established circula oing and out 4-1/2" -1/2" casing at 2, 2'. Good returns bu Spotted 10 sx plu wellhead and casing	COMMENCE DRILLIN CASING TEST AND O OTHER: OT	AG OPNS. PLUG AND ABANDONMENT DEMENT JOB Huding estimated date of starting any proposed August Spotted 7 sx cement Circulated 2 hours. Tagged Spotted 35 sx cement plug WOC 3-1/2 hours. Pump down H-1/2" casing and out through Dacker at 2,800'. Circulated 2.5 BPM. Set cement retainer 400 sx Howco Lite and 50 sx cement. Calculate cement top Installed dry hole marker. Analyst <u>A/2/92</u> TELEPHONE NO.214/739-11

N.