	· 	State of New Me	xico		
P.O. Box 1990, Holes, INM 88200 P.O. Box 2088 well AF1 NO.	to Appropriate				
DISTRICT Santa Fc, New Mexico 87504-2088 10-022-51637. DISTRICT Santa Fc, New Mexico 87504-2088 5. Index End and New Mexico 87504-2088 DISTRICT SUNDRY NOTICES AND REPORTS ON WELLS 6. Sate Oil & Case Lase No. (OO NOT USE THIS FORM FOR PROPOSALS TO DEEPEN OR PULG BACK TOA 7. Lase Name of Unit Agreemen Name (FORM C-101) FOR SUCH PROPOSALS) Fildson Kanch Unit 1. Type of Well State Coll & Case Lase No. VALUE S OTHER 1. Type of Well State Coll & Case Lase No. VALUE S OTHER 1. Type of Well State Coll & Case Lase No. VALUE S OTHER 1. Addresa do Oreano 9. Pool tame or Wilder 1.05 South 4th Str., Artessia, NM 58210 Arab-C San Andres 1.05 South 4th Str., Artessia, NM 58210 Arab-C San Andres 1.05 South 4th Str., Artessia, NM 58210 Subsect RT (GR.etc.) 1.05 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON 1.06 Atter Casing Chance Decline Cosing, Perforate, Acidize New Case State Sta				WELL API NO.	
INTERCITI STATE X FEE INDER KG RA. ADD. NN \$7410 6. SULC OI & GA LEAN NA SUNDEY NOTICES AND REPORTS ON WELLS V-3273 (DO NOT USE THIS FORM FOR FERORING USE AND FEPORTS ON PULG BACK TOA 7. LEAN NAME OF USE AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR FERORING USE AND PROPOSALS) 1. LEAN NAME OF USE AND REPORTS ON WELLS (DO NOT USE THIS FORM CORPORATION 2. Name of Orenace 3. Address of Orenace 8. Well NA (DS South 4 cht St., Artesia, NM \$8210 4rab-C San Andres Uluk Letter R.: 1980 Fee Form The SOUTh 4. (DS South 4 cht St., Artesia, NM \$8210 Arab-C San Andres Lise and 1650 (Uluk Letter R.: 1980 Fee Form The SOUTH Lise and 1650 Fee Form The East Lise (DS South 4 cht St., Artesia, NM \$8210 At21' CR I. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING I. PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDON CASING TEST AND CEMENT JOB OTHER: OTHER OTHER FLOADUCTION TO: SUBSEQUENT REPORT OF: REMEDI					
1000 Ro Bries A, Ames, NM 8740 6. Sale OLE Cas Leaw No. 1000 Ro Bries A, Ames, NM 8740 9. 23273 100 NOT USE THIS FORM FOR PROFONSALS TO DEPLLOR TO DEPEN OR PULO BACK TOA DEFERENT RESERVOR. USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSLS.) 7. Lease Name of Usit Agreement Name 1 Type of Well: 0 0:00, CUID FOR SUCH PROPOSLS.) E. Well No. 2 Name of Openator 8. Nell No. 1.3. Address of Openator 9. Food name or Widet 1.3. Address of Openator 9. Food name or Widet 1.3. Address of Openator 9. Food name or Widet 1.4. Well Leason 10. Elements South Lies and 1650 1.4. Well Leason 10. Elements South Lies and 1650 1.4. Well Leason 10. Elements South Well Not RER. RT. RR. RC. 10. Elements South 10. FR. RT. RR. RC. 1.1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSECUENT REPORT OF: PEFFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING I. 1.1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSECUENT REPORT OF: PEFFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK <td></td> <td></td> <td></td> <td>5. Indicate Type of Lease STATE X FEE</td>				5. Indicate Type of Lease STATE X FEE	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THE SOME NOR PROPOSALS) 1. Lease Name of Usik Agmeement Name DEFERENT RESERVORL USE 'APPLICATION FOR PERMIT (FORM-CIO) FOR SUCH PROPOSALS) Eldson Ranch Unit CRUE CION FOR SUCH PROPOSALS) Eldson Ranch Unit CRUE CION CORPORATION A Mare of Operator Value Comparison A Mare of Operator 10. Elevance 1650 Not Arab-C San Andres MITME List Comparison Addition of Operator 10. Elevance 1650 Subscrept 165 NATION Addition of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDAL WORK ALTERING CASING Commenter Mail of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDAL WORK ALTERING CASING Colspan= 0 Complete Mat					
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILLOR TO DEPEND OF PLUG BACK TOA 1. Leas Name of Visk Agreement Name	SUNDRY NOT	ICES AND REPORTS ON WEI	LS		
I. Type of Well: OTHER Eidson Ranch Unit Off. Wall OTHER Eidson Ranch Unit VATES PETROLEUM CORPORATION 4 4 105 South 4th St., Artesia, NM 88210 9. Pool name or Wilder 105 South 4th St., Artesia, NM 88210 Arab-C San Andres 4 Well Leauce 9. Pool name or Wilder Usit Lear R.: 1980 10. Elevation (Show whether DF, RAB, RT, GR, ec.) Lea Common 4421' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CAMMENCE DRILLING OPNS. PLUG AND ABANDON CHER: OTHER: Codmence for aning any proposed Wold SEERCHE IND. OTHER: Code and store st	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name	
vert vert ormex 2. Nume of Operator 8. Well No. 4 3. Addres of Operator 9. Pool name or Wildcat Arab-C San Andres 4. Well Location 4 arab-C San Andres 4 4. Well Location 105 South 4th St., Artesia, NM 88210 Arab-C San Andres 4. Well Location 105 Exercise (Show whether DF, RKB, R, GR, etc.) Lee Section 5 Tewnship 16S Ramge 33E NMFM Lee Section 5 Tewnship 16S Ramge 33E NMFM Lee Molit Leter	1. Type of Well:			- Eidson Ranch Unit	
YATES FETROLEUM CORPORATION 4 3. Address @ Openaor 9. Pool name or Wildat 105 South 4th St., Artesia, NM 38210 Arab-C San Andres 4. Well Location Usia Letter R : 1980 Feet From The South Lise and 1650 Feet From The East Lise Section 5 Township 16S Range 33E NMFM Lea County 4.421' GR 4.421' GR County 4.421' GR County County County 4.421' GR County County County 4.421' GR County Count	WELL X WELL OTHER				
105 South 4th St., Artesia, NM 88210 Arab-C San Andres 4. Well Locaice Arab-C San Andres 4. Well Locaice Intermediate Common Complete Common Co					
4. Well Location Index of out interest Unit Letter : 1980 Feet From The South Line and 1650 Feet From The East Line Section 5 Township 165 Range 33E NMFM Lea County 10 Elevation (Mow Whether DF, RKB, RT, GR, etc.) 4421' GR GR County 4421' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON GRMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULO RALTER CASING OTHER: Commence DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER:Production Casing, Perforate, Acidize X 12. Desche Progoed or Completed Opertions (Clearly state all periment date; including etimated date of starting any proposed work) SEE RULE 103. TD 8-20-93. Ran 148 joints 7" 26# J-55 casing set 5700'. Float shoe set 5700'. Feat chain w/150 sx "C" + .62. Halad-9 + 5#/sx Gilsonite (yield 1.32, wt 14.8). PD 9:19 AM 8-21-92. WOC 24 hrs. Tested casing to 2000 psi. THW whit, drill collars and 2-7/8" tubing to 5650'. Dropped down and tagged cement at 5795'. Displaced hole w/oil. artilled out 5' of cem	3. Address of Operator				
Unit Letter R: 1980 Feet From The South Line and 1650 Feet From The East Line Section 5 Township 165 Ramge 33E NMPM Lea Country 10 Elevation (Show whather DF, RKS, RT, GR, etc.) 4421' GR Country 4421' GR Country 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING Remedial WORK ALTERING CASING PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB TO THER.Production Casing, Perforate, Acidize X 12 Deckne Proposed or Completed Operations (Charly state all periment data), and give periment data, including estimated data graing any proposed Monte State St		esia, NM 88210		Arab-C San Andres	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4421' GR 4421' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: COMMENCE DRILLING OPNS. PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOS OTHER: POUL OR ALTER CASING OTHER: OTHER: Production Casing, Perforate, Acidize X 12. Describe Proposed of Completed Operations (Clearly state all periver datails, and give perivent dates, including estimated date of staring any proposed work) SEE RULE 103. TD 5700'. Reached TD 8-20-93. Ran 148 joints 7" 264 J-55 casing set 5700'. Float shoe set 5700', float collar set 5658'. Cemented w/85 sx HL "C" + .3% Halad-9 + 5#/sx Gilsonite (yield 1.84, wt 12.7). Tailed in w/150 sx "C" + .6% Halad-9 + 5#/sx Gilsonite (yield 1.84, wt 12.7). Tailed in w/150 sx "C" + .6% Halad-9 + 5#/sx Gilsonite (yield 1.84, wt 12.7). Tailed in w/150 sx "C" + .6% Halad-9 + 5#/sx Gilsonite (start at 5660' and 35' of cement at 5640'. RU and drilled out 20' of cement and float collars and 2-7/8" tubing to complet down and tagged cement at 5795'. Displaced hole w/oil. Drilled out 5' of cement and float shoe at 5700'. Drilled out below float shoe to 5728'. Circulated hole clean at 5728'. Perforated 5698-5703' with 4 SPF. TIH and dumped 11' of sand in bottom of open hole. Tagged sand 0 S722'. TH w/packer and set at 5672'. Swabbed well. Unset packer. TOH w/tubing and packer. TIH w/lauget and set at 5672'. Swabbed well. Unset packer. TOH w/tubing and packer. TH w/dump bailer. Tagged sand and open hole 0 5725'. Made 5 bailer runs, dumping sand in					
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4421' GR 4421' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: COMMENCE DRILLING OPNS. PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOS OTHER: POUL OR ALTER CASING OTHER: OTHER: Production Casing, Perforate, Acidize X 12. Describe Proposed of Completed Operations (Clearly state all periver datails, and give perivent dates, including estimated date of staring any proposed work) SEE RULE 103. TD 5700'. Reached TD 8-20-93. Ran 148 joints 7" 264 J-55 casing set 5700'. Float shoe set 5700', float collar set 5658'. Cemented w/85 sx HL "C" + .3% Halad-9 + 5#/sx Gilsonite (yield 1.84, wt 12.7). Tailed in w/150 sx "C" + .6% Halad-9 + 5#/sx Gilsonite (yield 1.84, wt 12.7). Tailed in w/150 sx "C" + .6% Halad-9 + 5#/sx Gilsonite (yield 1.84, wt 12.7). Tailed in w/150 sx "C" + .6% Halad-9 + 5#/sx Gilsonite (start at 5660' and 35' of cement at 5640'. RU and drilled out 20' of cement and float collars and 2-7/8" tubing to complet down and tagged cement at 5795'. Displaced hole w/oil. Drilled out 5' of cement and float shoe at 5700'. Drilled out below float shoe to 5728'. Circulated hole clean at 5728'. Perforated 5698-5703' with 4 SPF. TIH and dumped 11' of sand in bottom of open hole. Tagged sand 0 S722'. TH w/packer and set at 5672'. Swabbed well. Unset packer. TOH w/tubing and packer. TIH w/lauget and set at 5672'. Swabbed well. Unset packer. TOH w/tubing and packer. TH w/dump bailer. Tagged sand and open hole 0 5725'. Made 5 bailer runs, dumping sand in	Section 5	Township 16S B	nge 33F		
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER: OTHER:Production Casing, Perforate, Acidize X 12 Describe Proposed or Completed Operations (Clearly state all perinent datals, and give perinent data:, including estimated date of staring any proposed work) SEE RULE 103. TD 5700'. Reached TD 8-20-93. Ran 148 joints 7" 26# J-55 casing set 5700'. Float shoe set 5700', float collar set 5658'. Comented w/85 sx HL "C" + .37 Malad-9 + 5#/sx Gilsonite (yield 1.32, wt 14.8). PD 9:19 AM 8-21-92. WOC 24 hrs. Tested casing to 2000 psi. TIH w/bit, drill collars and 2-7/8" tubing to cement at 5640'. RU and drilled out 20' of cement and float collar at 5660' and 35' of cement below float collar. Circulated hole clean. TOH w/tubing, drill collars and 2-7/8" tubing to 5650'. Dropped down and tagged cement at 5795'. Displaced hole w/oil. Drilled out 5' of cement and float shoe at 5700'. Drilled out below float shoe to 5728'. Circulated hole clean at 5728'. Perforated 5698-5703' with 4 SPF. TIH and dumped 11' of sand in bottom of open hole. Tagged sand de 5722'. TIH w/packer and set at 5672'. Swabbed well.		10. Elevation (Show whether			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT DULL OR ALTER CASING CHANGE PLANS OTHER: CASING TEST AND CEMENT JOB PLUG AND ABANDONMENT OTHER: OTHER: OTHER: Production Casing, Perforate, Acidize X 12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of starting any proposed work) SEE RULE 1103. TD 5700'. Float shoe set 55700', float collar set 5658'. Cemented w/85 sx HL "(" + .3% Halad-9 + 5#/sx Gilsonite (yield 1.82, wt 12.7). Tailed in w/150 sx "C" + .6% Halad-9 + 5#/sx Gilsonite (yield 1.32, wt 14.8). PD 9:19 AM 8-21-92. WOC 24 hrs. Tested casing to 2000 psi. TIH w/bit, drill collars and 2-7/8" tubing to cement at 5640'. RU and drilled out 20' of cement and float collar at 5660' and 35' of cement below float collar. Circulated hole clean. TOH w/tubing, drill collars and bit. TIH w/logging tools. and logged well. TOH w/logging tools. TIH w/bit, drill collars and 2-7/8" tubing to 5650'. Dropped down and tagged cement at 5795'. Displaced hole w/oil. Drilled out 5' of cement and float shoe at 5700'. Drilled out below float shoe to 5728'. Circulated hole clean at 5728'. Perforated 5698-5703' with 4 SPF. TIH and dumped 11' of sand in bottom of open hole. Tagged sand de 5722'. TIH w/packer and set at 5672'. Swabbed well. Unset p					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER: CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: OTHER: OTHER: CASING TEST AND CEMENT JOB 12. Describe Proposed or Completed Operations (Clearly state all periment datails, and give periment data; including estimated date of staring any proposed work) SEE RULE 1103. TD 5700'. Reached TD 8-20-93. Ran 148 joints 7" 26# J-55 casing set 5700'. Float shoe set 5700', float collar set 5658'. Cemented w/85 sx HL "C" + .3% Halad-9 + 5#/sx Gilsonite (yield 1.32, wt 14.8). PD 9:19 AM 8-21-92. WOC 24 hrs. Tested casing to 2000 psi. TIH w/bit, drill collars and 2-7/8" tubing to cement at 5640'. RU and drilled out 20' of cement and float collar at 5660' and 35' of cement below float collar. Circulated hole clean. TOH w/tubing, drill collars and 2-7/8" tubing to 5650'. Dropped down and tagged cement at 5795'. Displaced hole w/oil. Drilled out 5' of cement and float shoe at 5700'. Drilled out below float shoe to 5728'. Circulated hole clean at 5728'. Perforated 5698-5703' with 4 SPF. TIH and dumped 11' of sand in bottom of open hole. Tagged sand @ 5722'. TIH w/packer and set at 5672'. Swabbed well. Unset packer. TOH w/tubing and packer. TIH w/dump bailer. Tagged sand and open hole @ 5725'. Made 5 bailer runs, dumping sand in open hole. Broughtsand up to					
PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER: CASING TEST AND CEMENT JOB OTHER: Production Casing, Perforate, Acidize X 12 Describe Proposed or Completed Operations (Clearly state all periment data), and give periment date:, including estimated date of staring any proposed work SEE RULE 1103. TD 5700'. Reached TD 8-20-93. Ran 148 joints 7" 26# J-55 casing set 5700'. Float shoe set 5700', float collar set 5658'. Cemented w/85 sx HL "C" + .3% Halad-9 + 5#/sx Gilsonite (yield 1.32, wt 14.8). PD 9:19 AM 8-21-92. WOC 24 hrs. Tested casing to 2000 psi. TIH w/bit, drill collars and 2-7/8" tubing to cement at 5640'. RU and drilled out 20' of cement and float collar at 5660' and 35' of cement below float collar. Circulated hole clean. TOH w/tubing, drill collars and bit. TIH w/logging tools and logged well. TOH w/logging tools. TIH w/bit, drill collars and 2-7/8" tubing to 5650'. Dropped down and tagged cement at 5795'. Displaced hole w/oil. Drilled out 5' of cement and float shoe at 5700'. Float shoe at 5700'. With 4 SPF. TIH and dumped 11' of sand in bottom of open hole. Tagged sand @ 5722'. TIH w/packer and set at 5672'. Swabbed well. Unset packer. TOH w/tubing and packer. TIH w/dump bailer. Tagged sand and open hole @ 5725'. Made 5 bailer runs, dumping sand in open hole. Broughtsand up to bottom of casing at 5704'. TOH w/bailer and RD wireline. TIH w/packer and tubing to 5562'. (continued page 2). Due for the show of my provide model of any show of the show of any set of my provide model. Thereby centry but the information above is transmation above is the best of my provide model. TIM w/packer and tubing to 5562'. (continued page 2). Due for the show of my provide model. Interviewers/ but the informatin above			REMEDIAL WORK		
PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER:Production Casing, Perforate, Acidize X 12 Describe Proposed or Completed Operations (Clearly state all perimers) details, and give periment dates, including estimated date of starning any proposed work) SEE RULE 1103. TD 5700'. Reached TD 8-20-93. Ran 148 joints 7" 26# J-55 casing set 5700'. Float shoe set 5700', float collar set 5658'. Cemented w/85 sx HL "C" + .3% Halad-9 + 5#/sx Gilsonite (yield 1.82, wt 14.8). PD 9:19 AM 8-21-92. WOC 24 hrs. Tested casing to 2000 psi. TIH w/bit, drill collars and 2-7/8" tubing to cement at 5640'. RU and drilled out 20' of cement and float collar at 5660' and 35' of cement below float collar. Circulated hole clean. TOH w/tubing, drill collars and bit. TIH w/logging tools and logged well. TOH w/logging tools. TIH w/bit, drill collars and 2-7/8" tubing to 5650'. Dropped down and tagged cement at 5705'. Displaced hole w/oil. Drilled out 5' of cement and float shoe as 5720'. Dirilled out 5' of cement and float shoe to 5728'. Circulated hole clean at 5728'. Perforated 5698-5703' with 4 SPF. TIH and dumped 11' of sand in bottom of open hole. Tagged sand @ 5722'. TIH w/packer and set at 5672'. Swabbed well. Unset packer. TOH w/tubing and packer. TIH w/long bailer. Tagged sand and open hole @ 5725'. Made 5 bailer runs, dumping sand in open hole. Brought sand up to bottom of casing at 5704'. TOH w/bailer and RD wireline. TIH w/packer and tubing to 5562'. (continued page 2). Our entry bat the information above is transide on my toowledge and beld. stonwarder A-5-93		CHANGE PLANS			
OTHER: OTHER: OTHER:Production Casing, Perforate, Acidize X I2 Describe Proposed or Completed Operations (Clearly state all perivent datails, and give perivent dates, including estimated date of starting any proposed work) SEE RULE 1103. TD 5700'. Reached TD 8-20-93. Ran 148 joints 7" 26# J-55 casing set 5700'. Float shoe set 5700', float collar set 5658'. Cemented w/85 sx HL "C" + .3% Halad-9 + 5#/sx Gilsonite (yield 1.84, wt 12.7). Tailed in w/150 sx "C" + .6% Halad-9 + 5#/sx Gilsonite (yield 1.32, wt 14.8). PD 9:19 AM 8-21-92. WOC 24 hrs. Tested casing to 2000 psi. TIH w/bit, drill collars and 2-7/8" tubing to cement at 5640'. RU and drilled out 20' of cement and float collar at 5660' and 35' of cement below float collar. Circulated hole clean. TOH w/tubing, drill collars and 2-7/8" tubing to 5650'. Dropped down and tagged cement at 5795'. Displaced hole w/oil. Drilled out 5' of cement and float shoe at 5700'. Drilled out below float shoe to 5728'. Circulated hole clean at 5728'. Perforated 5698-5703' with 4 SPF. TIH and dumped 11' of sand in bottom of open hole. Tagged sand @ 5722'. TIH w/packer and set at 5672'. Swabbed well. Unset packer. TOH w/tubing and packer. TIH w/dump bailer. Tagged sand and open hole @ 5725'. Made 5 bailer runs, dumping sand in open hole. Broughtsand up to bottom of casing at 5704'. TOH w/bailer and RD wireline. TIH w/packer and tubing to 5562'. (continued page 2). Displace for the start of					
work) SEE RULE 1103. TD 5700'. Reached TD 8-20-93. Ran 148 joints 7" 26# J-55 casing set 5700'. Float shoe set 5700', float collar set 5658'. Cemented w/85 sx HL "C" + .3% Halad-9 + 5#/sx Gilsonite (yield 1.84, wt 12.7). Tailed in w/150 sx "C" + .6% Halad-9 + 5#/sx Gilsonite (yield 1.32, wt 14.8). PD 9:19 AM 8-21-92. WOC 24 hrs. Tested casing to 2000 psi. TIH w/bit, drill collars and 2-7/8" tubing to cement at 5640'. RU and drilled out 20' of cement and float collar at 5660' and 35' of cement below float collar. Circulated hole clean. TOH w/tubing, drill collars and bit. TIH w/logging tools and logged well. TOH w/logging tools. TIH w/bit, drill collars and 2-7/8" tubing to 5650'. Dropped down and tagged cement at 5795'. Displaced hole w/oil. Drilled out 5' of cement and float shoe at 5700'. Drilled out below float shoe to 5728'. Circulated hole clean at 5728'. Perforated 5698-5703' with 4 SPF. TIH and dumped 11' of sand in bottom of open hole. Tagged sand @ 5722'. TIH w/packer and set at 5672'. Swabbed well. Unset packer. TOH w/tubing and packer. TIH w/dump bailer. Tagged sand and open hole @ 5725'. Made 5 bailer runs, dumping sand in open hole. Broughtsand up to bottom of casing at 5704'. TOH w/bailer and RD wireline. TIH w/packer and tubing to 5562'. (continued page 2). Super Thereby certify that the information above is the set of my knowledge and belid. SNATURE AMALA AMALA IMP Production Supervisor PATE					
TD 5700'. Reached TD 8-20-93. Ran 148 joints 7" 26# J-55 casing set 5700'. Float shoe set 5700', float collar set 5658'. Cemented w/85 sx HL "C" + .3% Halad-9 + 5#/sx Gilsonite (yield 1.84, wt 12.7). Tailed in w/150 sx "C" + .6% Halad-9 + 5#/sx Gilsonite (yield 1.32, wt 14.8). PD 9:19 AM 8-21-92. WOC 24 hrs. Tested casing to 2000 psi. TIH w/bit, drill collars and 2-7/8" tubing to cement at 5640'. RU and drilled out 20' of cement and float collar at 5660' and 35' of cement below float collar. Circulated hole clean. TOH w/tubing, drill collars and bit. TIH w/logging tools and logged well. TOH w/logging tools. TIH w/bit, drill collars and 2-7/8" tubing to 5650'. Dropped down and tagged cement at 5795'. Displaced hole w/oil. Drilled out 5' of cement and float shoe at 5700'. Drilled out below float shoe to 5728'. Circulated hole clean at 5728'. Perforated 5698-5703' with 4 SPF. TIH and dumped 11' of sand in bottom of open hole. Tagged sand @ 5722'. TIH w/packer and set at 5672'. Swabbed well. Unset packer. TOH w/tubing and packer. TIH w/dump bailer. Tagged sand and open hole @ 5725'. Made 5 bailer runs, dumping sand in open hole. Broughtsand up to bottom of casing at 5704'. TOH w/bailer and RD wireline. TIH w/packer and tubing to 5562'. (continued page 2). Displacer full the information above is true and complete to the best of my knowledge and belief. SHONATURE August August III and belief. SHONATURE August III and Builer. THE Production Supervisor DATE 4-5-93					
1.84, wt 12.7). Tailed in w/150 sx "C" + .6% Halad-9 + 5#/sx Gilsonite (yield 1.32, wt 14.8). PD 9:19 AM 8-21-92. WOC 24 hrs. Tested casing to 2000 psi. TIH w/bit, drill collars and 2-7/8" tubing to cement at 5640'. RU and drilled out 20' of cement and float collar at 5660' and 35' of cement below float collar. Circulated hole clean. TOH w/tubing, drill collars and bit. TIH w/logging tools and logged well. TOH w/logging tools. TIH w/bit, drill collars and 2-7/8" tubing to 5650'. Dropped down and tagged cement at 5795'. Displaced hole w/oil. Drilled out 5' of cement and float shoe at 5700'. Drilled out below float shoe to 5728'. Circulated hole clean at 5728'. Perforated 5698-5703' with 4 SPF. TIH and dumped 11' of sand in bottom of open hole. Tagged sand @ 5722'. TIH w/packer and set at 5672'. Swabbed well. Unset packer. TOH w/tubing and packer. TIH w/dump bailer. Tagged sand and open hole @ 5725'. Made 5 bailer runs, dumping sand in open hole. Broughtsand up to bottom of casing at 5704'. TOH w/bailer and RD wireline. TIH w/packer and tubing to 5562'. (continued page 2). I hereby certly that the information above is the set of my knowledge and belief. SHONATURE	TD 5700'. Reached TD 8-20-93. Ran 148 joints 7" 26# J-55 casing set 5700'. Float shoe set				
PD 9:19 AM 8-21-92. WOC 24 hrs. Tested casing to 2000 psi. TIH w/bit, drill collars and 2-7/8" tubing to cement at 5640'. RU and drilled out 20' of cement and float collar at 5660' and 35' of cement below float collar. Circulated hole clean. TOH w/tubing, drill collars and bit. TIH w/logging tools and logged well. TOH w/logging tools. TIH w/bit, drill collars and 2-7/8" tubing to 5650'. Dropped down and tagged cement at 5795'. Displaced hole w/oil. Drilled out 5' of cement and float shoe at 5700'. Drilled out below float shoe to 5728'. Circulated hole clean at 5728'. Perforated 5698-5703' with 4 SPF. TIH and dumped 11' of sand in bottom of open hole. Tagged sand @ 5722'. TIH w/packer and set at 5672'. Swabbed well. Unset packer. TOH w/tubing and packer. TIH w/dump bailer. Tagged sand and open hole @ 5725'. Made 5 bailer runs, dumping sand in open hole. Broughtsand up to bottom of casing at 5704'. TOH w/bailer and RD wireline. TIH w/packer and tubing to 5562'. (continued page 2). Dier Thereby certify that the information shore is true and complete to the best of my knowledge and belief.	5700', float collar set 5658'. Cemented w/85 sx HL "C" + .3% Halad-9 + 5 $\#$ /sx Gilsonite (yield 1.84, ut 12.7). Tailed in w/150 sx "C" + .6% Halad-9 + 5 $\#$ /sx Gilsonite (yield 1.32, ut 14.8).				
2-7/8" tubing to cement at 5640'. RU and drilled out 20' of cement and float collar at 5660' and 35' of cement below float collar. Circulated hole clean. TOH w/tubing, drill collars and bit. TIH w/logging tools and logged well. TOH w/logging tools. TIH w/bit, drill collars and 2-7/8" tubing to 5650'. Dropped down and tagged cement at 5795'. Displaced hole w/oil. Drilled out 5' of cement and float shoe at 5700'. Drilled out below float shoe to 5728'. Circulated hole clean at 5728'. Perforated 5698-5703' with 4 SPF. TIH and dumped 11' of sand in bottom of open hole. Tagged sand @ 5722'. TIH w/packer and set at 5672'. Swabbed well. Unset packer. TOH w/tubing and packer. TIH w/dump bailer. Tagged sand and open hole @ 5725'. Made 5 bailer runs, dumping sand in open hole. Broughtsand up to bottom of casing at 5704'. TOH w/bailer and RD wireline. TIH w/packer and tubing to 5562'. (continued page 2).					
bit. TIH w/logging tools and logged well. TOH w/logging tools. TIH w/bit, drill collars and 2-7/8" tubing to 5650'. Dropped down and tagged cement at 5795'. Displaced hole w/oil. Drilled out 5' of cement and float shoe at 5700'. Drilled out below float shoe to 5728'. Circulated hole clean at 5728'. Perforated 5698-5703' with 4 SPF. TIH and dumped 11' of sand in bottom of open hole. Tagged sand @ 5722'. TIH w/packer and set at 5672'. Swabbed well. Unset packer. TOH w/tubing and packer. TIH w/dump bailer. Tagged sand and open hole @ 5725'. Made 5 bailer runs, dumping sand in open hole. Broughtsand up to bottom of casing at 5704'. TOH w/bailer and RD wireline. TIH w/packer and tubing to 5562'. (continued page 2). Over I hereby certify that the information above is true and complete to the best of my knowledge and belief. SHONATURE UMATA Wolfith THE Production Supervisor DATE 4-5-93	2-7/8" tubing to cement at 5640'. RU and drilled out 20' of cement and float collar at 5660'				
2-7/8" tubing to 5650'. Dropped down and tagged cement at 5795'. Displaced hole w/oil. Drilled out 5' of cement and float shoe at 5700'. Drilled out below float shoe to 5728'. Circulated hole clean at 5728'. Perforated 5698-5703' with 4 SPF. TIH and dumped 11' of sand in bottom of open hole. Tagged sand @ 5722'. TIH w/packer and set at 5672'. Swabbed well. Unset packer. TOH w/tubing and packer. TIH w/dump bailer. Tagged sand and open hole @ 5725'. Made 5 bailer runs, dumping sand in open hole. Brought sand up to bottom of casing at 5704'. TOH w/bailer and RD wireline. TIH w/packer and tubing to 5562'. (continued page 2). Dier I hereby certify that the information above is true and complete to the best of my knowledge and belief. SHONATURE AMALTA A MALTA TITLE Production Supervisor DATE 4-5-93					
Drilled out 5' of cement and float shoe at 5700'. Drilled out below float shoe to 5728'. Circulated hole clean at 5728'. Perforated 5698-5703' with 4 SPF. TIH and dumped 11' of sand in bottom of open hole. Tagged sand @ 5722'. TIH w/packer and set at 5672'. Swabbed well. Unset packer. TOH w/tubing and packer. TIH w/dump bailer. Tagged sand and open hole @ 5725'. Made 5 bailer runs, dumping sand in open hole. Broughtsand up to bottom of casing at 5704'. TOH w/bailer and RD wireline. TIH w/packer and tubing to 5562'. (continued page 2). I hereby certify that the information above is true and complete to the best of my knowledge and belief. SKONATURE					
in bottom of open hole. Tagged sand @ 5722'. TIH w/packer and set at 5672'. Swabbed well. Unset packer. TOH w/tubing and packer. TIH w/dump bailer. Tagged sand and open hole @ 5725'. Made 5 bailer runs, dumping sand in open hole. Broughtsand up to bottom of casing at 5704'. TOH w/bailer and RD wireline. TIH w/packer and tubing to 5562'. (continued page 2). I hereby certify that the information above is true and complete to the best of my knowledge and belief. SHONATURE	Drilled out 5' of cement and float shoe at 5700'. Drilled out below float shoe to 5728'.				
Unset packer. TOH w/tubing and packer. TIH w/dump bailer. Tagged sand and open hole @ 5725'. Made 5 bailer runs, dumping sand in open hole. Broughtsand up to bottom of casing at 5704'. TOH w/bailer and RD wireline. TIH w/packer and tubing to 5562'. (continued page 2). I hereby certify that the information above is true and complete to the best of my knowledge and belief. SHONATURE UMATA Doddite TIME Production Supervisor DATE 4-5-93	Circulated hole clean at 5728'. Perforated 5698-5703' with 4 SPF. TIH and dumped 11' of sand				
Made 5 bailer runs, dumping sand in open hole. Brought sand up to bottom of casing at 5704'. TOH w/bailer and RD wireline. TIH w/packer and tubing to 5562'. (continued page 2). Der I hereby certify that the information above is true and complete to the best of my knowledge and belief. SKONATURE LAND Colline TIME Production Supervisor DATE 4-5-93	in bottom of open hole. Tagged sand @ 5722'. TIH w/packer and set at 5672'. Swabbed well.				
TOH w/bailer and RD wireline. TIH w/packer and tubing to 5562'. (continued page 2). Der I hereby certify that the information above is true and complete to the best of my knowledge and belief. SKONATURE Contact of the dest of my knowledge and belief. SKONATURE Contact of the dest of my knowledge and belief. TITLE Production Supervisor DATE 4-5-93	Made 5 bailer runs, dumping sand in open hole. Broughtsand up to bottom of casing at 5704'.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE LANTA O ditter TITLE Production Supervisor DATE 4-5-93	TOH w/bailer and RD w	ireline. TIH w/packer	and tubing to 5		
SIONATURE DATE	I hereby certify that the information above is tru	e and complete to the best of my knowledge and	belief.		
TYPE OR PRINT NAME JUANITA GOODLett TELEPHONE NO. 505/748-1471	SIGNATURE Canita	Dodlit m	Production S	upervisor 4-5-93	
	TYPE OR PRINT NAME JUANIT	a Goodlett	·	ТЕLЕРНОМЕ NO. 505/748-1471	
(This space for State Use) Urig. Signed by	(This space for State Use)	Signed by			
Paul Kautz APR 07 1993	Pau	l Kantz			
APPROVED BY DATE DATE DATE DATE				DATE	

الالالالة بسريانه شيون الماليان

page 2 - continued) Pumped pad acid job as follows: Pumped 5000 gals 20% NEFE acid at 13 BPM at 6200 psi. Pumped 20000 gals gelled 2% KCL water at 25 BPM at 5900 psi. Pumped 20000 gals gelled 20% NEFE acid at 25 BPM at 5200 psi. Pumped 42 bbls gelled 2% KCL water flush at 25 BPM at 5800 psi. Total load to recover 1048 bbls. 8-29-92 - 9-1-92. Swabbed well.

RECEIVED APR 0 • 1993

OCD HOBBS OFFICE