ultania 3 Coj ŭes) Appropriat s intrict Offic)		New Mexico atural Resources Department	Form C-103 Revised 1-1-89
STRICT I D. Box 1940, Hobbs, NM \$\$240	P.O. Box 2088 Santa Fe, New Mexico, 87504-2088		WELL API NO. 30-025-32164
STRICT I O. Drawer DD, Artesia, NM \$\$210			5. Indicate Type of Lesse STATE STATE
TRICT II () Rio Bratos Rd., Aztec, NM 87410		6. State Oil & Gas Lesse No. E-3510	
Do not jse this form for PF Different rese (form)	TICES AND REPORTS C ROPOSALS TO DRILL OR TO (ERVOIR. USE "APPLICATION C-101) FOR SUCH PROPOSAL	DEEPEN OR PLUG BACK TO A FOR PERMIT	7. Lease Name or Unit Agreement Name
Type of Vell: Office CAS Will CAS] omen.		- Anderson Ranch Unit
Name of Operator Concilo, Inc.			8. Well No. 21
Address of Operator 10 Desta Dr. Ste 100 Well Los tion	DW, Midland, TX 797	05	9. Pool mens or Wildow Wildcat Ellenburger
///////////////////////////////////////	4293.4	,	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>
NOTICE OF IN FORM REMEDIAL WORK	Appropriate Box to Inc ITENTION TO: PLUG AND ABANDON CHANGE PLANS	ticate Nature of Notice, F SUI REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER:	BSEQUENT REPORT OF: ALTERING CASING IG OPNS. PLUG AND ABANDONMENT EMENT JOB
NOTICE OF IN FORM REMEDIAL WORK	Appropriate Box to Inc. ITENTION TO: PLUG AND ABANDON CHANGE PLANS	ticate Nature of Notice, F SUI REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: details, and give pertinent dates, incl	BSEQUENT REPORT OF: ALTERING CASING IG OPNS. PLUG AND ABANDONMENT EMENT JOB
NOTICE OF IN FORM REMEDIAL WORK	Appropriate Box to Inc. ITENTION TO: PLUG AND ABANDON CHANGE PLANS	iicate Nature of Notice, I SUI REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: densils, and give pertinent dates, incl bs OCD Office to plut ted and changed to t	BSEQUENT REPORT OF: ALTERING CASING IG OPNS. PLUG AND ABANDONMENT EMENT JOB Maing estimated date of starting any proposed IG and abandon this well. The the one attached to this Sundry
NOTICE OF IN RFORM REMEDIAL WORK MPORARILY ABANDON LLOR ALTER CASING HER:	Appropriate Box to Inc. ITENTION TO: PLUG AND ABANDON CHANGE PLANS CHANGE PLANS	ticate Nature of Notice, F SUI REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: dessile, and give pertinent dates, incl bs OCD Office to plu ted and changed to t	BSEQUENT REPORT OF: ALTERING CASING IG OPNS. PLUG AND ABANDONMENT EMENT JOB

	HOME NO.
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR	MAY C 5 1994
DATE -	
•	A

CONDITIONS (F AFFRIDYAL, F ANY:	

Anderson Ranch Unit No. 21 PLUG AND ABANDON 04/28/94

Objective: To Plug and Abandon ARU 21.

Summary: 1.

- Regulatory Prep to P&A. 2.
- 3.
- Morrow. Set Cmt Ret @ 12,100'. Pump 35 sx below and 5 sx on top of retainer. 4.
- Wolfcamp. Pump 25 sx from 8790-8950'. 5.
- Salvage Prod Casing. Run freepoint and cut and pull prod csg from 7000'. 6.
- Stub Plug. Pump 40 sx fom 6950-7050'. 7.
- Glorietta Plug. Pump 45 sx from 5580'-5680'.
- Intermediate Casing Shoe. Pump 45 sx from 4160-4260'. 8. 9.
- Salt Section. Pump 45 sx from 1350-1450'.
- Surface Plug. Pump 250 sx from 600' to surface. 10.
- 11. Restore Location.

.

Anderson Ranch Unit No. 21 PROCEDURE 04/28/94

1. Regulatory

*Notify BLM/NMOCD of intent to P&A well. *Mud laden fluid of at least 9.5 PPG must be placed in all uncemented portions of the well.

2. Prep to P&A

MIRU. Kill well. ND wellhead, NU BOP. Release pkr and POOH w/ perforating equipment and packer. If well is not dead when packer is released, circulate 9.5 ppg fluid.

3. Morrow Plug

RIH w/ cmt retainer and stinger. Set retainer at 12,100'. Sting out of retainer and circulate 9.5 ppg fluid if not already done. Spot 40 sx Class C cmt to bottom of tubing. Sting into retainer and pump 35 sx cmt. Sting out of retainer and pump 5 sx on top.

4. Wolfcamp Plug

Pull up hole to 8950'. Pump 25 sx balanced plug from 8950' - 8790' (160').

5. Salvage Production Casing

POOH. Run freepoint survey to determine free production casing. RU casing cutters to cut 9-5/8" casing. RIH to free pipe limit and cut production casing. Lay down casing.

6. Stub Plug

RIH with tubing to 7050'. Top hole w/ 9.5 ppg fluid. Pump 40 sx in balanced plug from 50' below casing cut to 50' above casing cut (approximately 7050-6950'). WOC and tag.

7. Giorietta Plug

Pull up hole to 5680'. Pump 45 sx in balanced plug from 5680' - 5580'.

8. Intermediate Casing Shoe Plug

Pull up hole to 4260'. Pump 45 sx balanced plug from 4260' - 4160'.

9. Salt Section Plug

Pull up hole to 1450'. Pump 45 sx balanced plug from 1450' - 1350'. WOC and tag.

10. Surface Plug

Pull up hole to 600'. Pump 250 sx balanced plug from 600' to surface. WOC. Top off cmt to surface.

11. Restore Location

RDMO. Cut off casing 3' below surface. Top off w/ cmt. Weld on cap and install marker. Clean location and restore to natural condition. Send all paperwork to Bill Keithly in Midland.

Scott Listial

Engir eer

Cement Detail Type Water Req Mix Weight Yield

Class *C* 6.3 gal/sk 14.8 ppg 1.32 cu. ft./sk



BY: SCOTT LISTIAK

ARU No. 21 PROPOSED P&A 1700' FSL, 850' FWL, S1, T16S, R32E



DATE A 18 04