

DISTRICT I
1625 French Drive Hobbs, NM 88240

DISTRICT II
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P. O. Box 2088
Santa Fe, NM 7504-2088

WELL API NO.

30-025-32929

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-2148

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL

WELL ☒

GAS

WELL ☐

OTHER

2. Name of Operator

The Wiser Oil Company

3. Address of Operator

P.O. Box 2568 Hobbs, New Mexico (505) 392-9797

7. Lease Name or Unit Agreement Name

Caprock Maljamar Unit

8. Well No.

162

9. Pool name or Wildcat

Maljamar Grayburg San Andres

4. Well Location

Unit Letter O : 56 Feet From The South Line and 2595 Feet From The East Line

Section 17 18 Township 17S Range 33E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4148' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Perforate & Acidize ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/19/99 MIRU Tyler Well Service. ND WH. Could not pull tbg. Release TAC. POH w/rods & pump. Tight spot @ 4100' RU BOP.
11/22/99 RU Rotary WL & ran free point. Tbg. stuck @ 4200'. Free @ 4190'. POH. RIH w/cutters & cut off @ 4161'. POH w/tools. RD WL.
RIH w/4-11/16" overshot, bumper sub, Bowen jars, DC's, crossover & 2-7/8" tbg. Caught fish @ 4161'.
11/23/99 POH w/2-7/8" tbg. & tools. RIH w/4 11/16" overshot, extension & 2-7/8" tbg. Tbg. stopped 1 jt. above fish.
11/24/99 RIH w/additional jt. tbg. Caught fish @ 4161'. RU WL & RIH w/cutter to 4200'. Could not pass tight spot. POH w/cutter. RIH w/
2 1/16" jet cutter to 4222'. Cut off 2-7/8" tbg. 5' above collar. Pull tbg. thru tight spot @ 85,000#. POH w/2-7/8" tbg. RIH w/4-3/4"
impression block & 2-7/8" tbg. Set down @ 4200'. POH w/2-7/8" tbg. & block. Impression shows casing collapsed. RIH w/4-1/4"
swedge, bumper sub, Bowen jars, DC's, crossover & 2-7/8" tbg. to 4200'.
11/27/99 POH w/2-7/8" tbg. LD 4-1/2" swedge. RIH w/4 3/16" swedge to 4201.5'.
11/29/99 POH w/2-7/8" tbg., DC's & tools. RIH w/2-3/8" tbg. & crossover to tight spot. POH. & LD tbg.
11/30/99 RIH w/1 jt. 2-3/8" tbg. welded to a 4-3/4" string mill, DC's, jars & 2-7/8" tbg. to 4197'. Mill for 6 1/2 hrs. Pull tools to 4000'.
12/01/99 RIH to 4206'. Mill for 8 hrs. Broke @ 4208.5'. Circulate hole clean. POH w/2-7/8" tbg. LD tools.
12/02/99 RIH w/4-3/4" bit, bit sub, DC's & 2-7/8" tbg. to 4685'. POH w/2-7/8" tbg. LD tools. RU Computalog WL. Tag fish @ 4932'. Perforate
Grayburg f/4076', 77', 4106', 11', 12', 13', 36', 53', 64', 65', 66', 67', 94', 95', 98', 4216', 35', 36', 44', 49', 52', 53', 57', 68', 73', 77', 78', 79' w/4 SPF
Vacuum f/4353', 67', 70', 73', 81', 88', 89', 90', 4403', 04', 07', 08', 13', 42', 43' w/2 SPF & Jackson f/4610', 11', 12', 45', 46', 47', 49', 57', 59', 60'
& 63' w/2 SPF. RD WL. RIH w/RBP & pkr. on 2-7/8" tbg. Set RBP @ 4685'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner
TYPE OR PRINT NAME Mary Jo Turner

TITLE Production Tech II DATE December 27, 2001
TELEPHONE NO. (505) 392-9797

(This space for State Use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE PAUL F. KAUTZ DATE _____
PETROLEUM ENGINEER