

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 South First, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.

30-025-33977

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

Dickinson Cattle Company

8. Well No.

1

9. Pool name or Wildcat

Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

Ammonite Energy Texas, Inc.

3. Address of Operator

P.O. Box 10926, Midland, Texas

4. Well Location

Unit Letter **P** : **800** feet from the **South** line and **550** feet from the **East** line

Section **5** Township **15S** Range **38E** NMPM **Lea** County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3761'

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐


12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

SEE ATTACHED

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE



TITLE

Triple N Services, Inc. Phone: 915-687-1994

President

DATE **6/8/01**

Type or print name

James F. Newman, P.E.

Telephone No. **915-687-1994**

APPROVED BY

TITLE

Paul Kautz
Geologist

DATE

Conditions of approval, if any:

Handwritten initials



Proposed plugging procedure
Ammonite Energy Texas, Inc.
#1 Dickinson Cattle Company
API #30-025-33977
800 FSL & 550 FEL of section 5, T-15-S, R-38-E
Lea County, New Mexico

Wellbore & Casing

13-3/8" csg @ 465', cmt'd to surface
8-5/8" csg @ 4,917', cmt'd w/ 290 sx, TOC 3,770' calculated
5-1/2" csg @ 11,300', TOC @ 8,500'
2-7/8" tbg fish @ +/- 6,800'; Halliburton packer at 8,000'
perforations 9,650 – 9,666'

Procedure to Plug Well discussed w/ Gary Wink of Hobbs OCD 6/08/01

Notify Hobbs OCD (505-393-6161) 24 hrs prior to MI & minimum 4 hrs prior to pumping plugs:

- 1) MIRU pulling unit. ND wellhead and NU BOP.
- 2) RIH w/ gauge ring on sandline, tag top of fish. RIH w/ 5-1/2" AD-1 packer on workstring tubing and set at 6,500' (300' above tag).
- 3) RU cementer and establish rate into fish. Squeeze 100 sx C cmt w/ 2% CaCl₂ and displace to 100' above tag. Release packer and POOH.
- 4) WOC and tag this plug. Circulate hole w/ plugging mud.
- 5) POOH w/ tubing and packer. ND wellhead and stretch 5-1/2" casing. Cut and pull 5-1/2" casing based on stretch measurements or at 8-5/8" csg shoe, whichever is deeper.
- 6) RIH w/ tubing to 50' inside of 5-1/2" casing stub and pump 50 sx C cmt w/ 2% CaCl₂. WOC and tag this plug at least 50' above casing stub.
- 7) POOH w/ tubing to 4,967' and pump 60 sx C cmt w/ 2% CaCl₂. WOC and tag this plug at least 50' inside of casing shoe. **casing shoe**
- 8) POOH w/ tubing to 2,100' and pump 35 sx C cmt. **top of salt**
- 9) ND wellhead and stretch 8-5/8" casing. If casing free at 1,000' or deeper, cut and pull 8-8/8" casing based on stretch measurements. If less, cut at 13-3/8" csg shoe.
- 10) RIH w/ tbg to 515'. Load hole w/ mud and pump 85 sx C cmt @ 515'. **freshwater & shoe plug**
- 11) POOH w/ tbg to 50' and pump 20 sx surface plug.
- 12) Cut off wellhead 3' below ground level. Cap well w/ 1/4" plate and install dryhole marker, cut anchors. Cover pit and cellar.