Submit 3 Copies to Appropriate District Office <u>DISTRICT I</u>			•
DISTRICT I	State of New Energy, Minerals and Natural	Mexico Resources Department	Form C-103
	OII CONCEDVAN		Revised 1-1-89
P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVAT	ION DIVISION	WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM \$8210 DISTRICT III 1000 Rio Brazos Rd., Aziec, NM \$7410		30-025-34252	
		S. Indicate Type of Lease	
		STATE X FEE	
[6. State Oil & Gas Loase No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		VA-604	
		7. Lease Name or Unit Agreement Name	
	(Conto.)		
	OTHER		
2. Name of Operator YATES PETROLEUM CORPORATION		Field APK State Com	
3. Address of Operator		8. Well No.	
105 South 4th St., Arte	ste MM 99210		9. Pool same or Wildcat
A MART FORMULE			Wildcat Morrow
Unit Letter K 188	BO Feet From The South	1650	
		Line and1650	Feet From The West Line
	Township 165 R	ange 35E N	МРМ Тер
	10. Elevation (Show whether	DF, RKB, RT, GR, etc.) 5' GR	County
I. Check A	DECODE ate Box to Indicate 1	J GR	
NOTICE OF INTE	ppropriate Box to Indicate	Nature of Notice, Rej	port, or Other Data
<u> </u>		SUBS	EQUENT REPORT OF:
	PLUG AND ABANDON	REMEDIAL WORK	~ -
ILL OR ALTER CASING		COMMENCE DRILLING C	ALTERING CASING
		CASING TEST AND CEMI	
	[]	OTHER: Perforate	& frac
2. Describe Proposed or Completed Operation work) SEE RULE 1103.	s (Clearty state all pertinent details, and	leive neminant das statut	X
1-30-2-1-99 - Shut in.		give puriment dates, including	estimated date of starting any proposed
2-2-99 = Bigged up Learns	11.0		
and released TCP guns	Charal Services. Ran Sta	tic BHP bomb. T	IH with Otis shifting tool
$4 J^{-}J^{-} = R U U U \Delta A U D + M A A A A A A A A A A A A A A A A A A$			err in
12025-12048' (Morrow)		popoff to 3500 p	asi Frankland
\sim	//o cubrug) Mit	1 / 0 0 0 0 1	Port riac u periorations
	for 0 1	h 42000 gallons	70Q foam with 50000# 20-40
Rigged down treesawar	for 2 hours. Opened	& flowed for 30	minutes Shut $30000 \# 20-40$
Rigged down treesaver. 2-4-98 - Flowed back for	for 2 hours. Opened Flowing back frac.	& flowed for 30	minutes. Shut well in.
Rigged down treesaver. 2-4-98 - Flowed back for 2-5-98 - Rigged up slick	for 2 hours. Opened Flowing back frac. cleanup. Flow tester	& flowed for 30	minutes. Shut well in.
Rigged down treesaver. 2-4-98 - Flowed back for 2-5-98 - Rigged up slick. into profile. TOOM - back	for 2 hours. Opened Flowing back frac. cleanup. Flow tester line. TIH with 1.875	& flowed for 30 d. Shut well in. "S-lock blanking	minutes. Shut well in.
Rigged down treesaver. 2-4-98 - Flowed back for 2-5-98 - Rigged up slick into profile. TOOH - br: RBP. TOOH - blod tubbar	for 2 hours. Opened Flowing back frac. cleanup. Flow tester line. TIH with 1.875 idge plug packed with	& flowed for 30 d. Shut well in. "S-lock blanking frac sand. Clea	minutes. Shut well in.
Rigged down treesaver. 2-4-98 - Flowed back for 2-5-98 - Rigged up slick into profile. TOOH - br: RBP. TOOH - bled tubing bleed off. Opened tubing	for 2 hours. Opened Flowing back frac. cleanup. Flow tester line. TIH with 1.875 idge plug packed with down. Loaded tubing	& flowed for 30 d. Shut well in. "S-lock blanking frac sand. Clea with 72 bbls and	minutes. Shut well in. plug. Could not latch ned up tool. TIH and set
Rigged down treesaver. 2-4-98 - Flowed back for 2-5-98 - Rigged up slick into profile. TOOH - br: RBP. TOOH - bled tubing bleed off. Opened tubing equalizing probe & TOOH	for 2 hours. Opened Flowing back frac. cleanup. Flow tester line. TIH with 1.875 idge plug packed with down. Loaded tubing g and flowed back 2 mi	& flowed for 30 d. Shut well in. "S-lock blanking frac sand. Clea with 72 bbls and lnutes. Plug not	minutes. Shut well in. plug. Could not latch ned up tool. TIH and set pressured to 500#. Had
Rigged down treesaver. 2-4-98 - Flowed back for 2-5-98 - Rigged up slick into profile. TOOH - br: RBP. TOOH - bled tubing bleed off. Opened tubing equalizing probe & TOOH. 7500# disc. Latched into	for 2 hours. Opened Flowing back frac. cleanup. Flow tester line. TIH with 1.875 idge plug packed with down. Loaded tubing and flowed back 2 min TIH and pulled blank profile nipple do	& flowed for 30 d. Shut well in. "S-lock blanking frac sand. Clea with 72 bbls and inutes. Plug not cing plug. TIH w	minutes. Shut well in. plug. Could not latch ned up tool. TIH and set pressured to 500#. Had
Rigged down treesaver. 2-4-98 - Flowed back for 2-5-98 - Rigged up slick into profile. TOOH - br: RBP. TOOH - bled tubing bleed off. Opened tubing equalizing probe & TOOH. 7500# disc. Latched into	for 2 hours. Opened Flowing back frac. cleanup. Flow tester line. TIH with 1.875 idge plug packed with down. Loaded tubing and flowed back 2 min TIH and pulled blank profile nipple do	& flowed for 30 d. Shut well in. "S-lock blanking frac sand. Clea with 72 bbls and inutes. Plug not cing plug. TIH w hoff tool at 123 d. CONTIN	minutes. Shut well in. s plug. Could not latch and up tool. TIH and set pressured to 500#. Had holding. TIH and pulled ith FWE blanking plug with 80'. Pressured to 1500#. OK.
Rigged down treesaver. 2-4-98 - Flowed back for 2-5-98 - Rigged up slick into profile. TOOH - br RBP. TOOH - bled tubing bleed off. Opened tubing equalizing probe & TOOH. 7500# disc. Latched into reby certify the Us information above if the and q warrang Watty Warrang	for 2 hours. Opened Flowing back frac. cleanup. Flow tester line. TIH with 1.875 idge plug packed with down. Loaded tubing and flowed back 2 min TIH and pulled blank profile nipple do	& flowed for 30 d. Shut well in. "S-lock blanking frac sand. Clea with 72 bbls and lnutes. Plug not cing plug. TIH w Moff tool at 123	minutes. Shut well in. s plug. Could not latch and up tool. TIH and set pressured to 500#. Had holding. TIH and pulled ith FWE blanking plug with 80'. Pressured to 1500#. OK.
Rigged down treesaver. 2-4-98 - Flowed back for 2-5-98 - Rigged up slick into profile. TOOH - br: RBP. TOOH - bled tubing bleed off. Opened tubing bleed off. Opened tubing bleed off. Latched into roby cardify the the information above is true and e NATURE Rusty Klein	for 2 hours. Opened Flowing back frac. cleanup. Flow tester line. TIH with 1.875 idge plug packed with down. Loaded tubing and flowed back 2 min TIH and pulled blank profile nipple do	& flowed for 30 d. Shut well in. "S-lock blanking frac sand. Clea with 72 bbls and inutes. Plug not cing plug. TIH w hoff tool at 123 d. CONTIN	minutes. Shut well in. s plug. Could not latch ned up tool. TIH and set pressured to 500#. Had holding. TIH and pulled ith FWE blanking plug with 80'. Pressured to 1500#. OK.
Rigged down treesaver. 2-4-98 - Flowed back for 2-5-98 - Rigged up slick into profile. TOOH - br: RBP. TOOH - bled tubing bleed off. Opened tubing bleed off. Opened tubing capacity the us information above if true and qualizing roby certify the us information above if true and quality wature Rusty Klein	for 2 hours. Opened Flowing back frac. cleanup. Flow tester line. TIH with 1.875 idge plug packed with down. Loaded tubing g and flowed back 2 min TIH and pulled blank profile nipple in or template to the best of my knowledge and best mns.	& flowed for 30 d. Shut well in. "S-lock blanking frac sand. Clea with 72 bbls and inutes. Plug not cing plug. TIH w hoff tool at 123 d. CONTIN	minutes. Shut well in. plug. Could not latch ned up tool. TIH and set pressured to 500#. Had holding. TIH and pulled ith FWE blanking plug with 80'. Pressured to 1500#. OK. NUED ON NEXT PAGE: nician Feb. 19, 1999
Rigged down treesaver. 2-4-98 - Flowed back for 2-5-98 - Rigged up slick. into profile. TOOH - br: RBP. TOOH - bled tubing pleed off. Opened tubing pleed off. Opened tubing pleed off. Latched into 500# disc. Latched into the sed of the	for 2 hours. Opened Flowing back frac. cleanup. Flow tester line. TIH with 1.875 idge plug packed with down. Loaded tubing and flowed back 2 min TIH and pulled blank profile nipple do	& flowed for 30 d. Shut well in. "S-lock blanking frac sand. Clea with 72 bbls and inutes. Plug not cing plug. TIH w hoff tool at 123 d. CONTIN	minutes. Shut well in. plug. Could not latch ned up tool. TIH and set pressured to 500#. Had holding. TIH and pulled ith FWE blanking plug with 80'. Pressured to 1500#. OK. NUED ON NEXT PAGE: nician Feb. 19, 1999