Submit 3 Copies to Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources Department		Form C-103 Revised 1-1-89	
DISTRICT ! P.O. Box 1980, Hobbs. NM 88240	OIL CONSERVATION DIVISION 2040 Pacheco St. Santa Fe, NM 87505		WELL API NO.	
			30-025-34368	
P.O. Drawer DD, Artesia, NM 88210			sIndicate Type of Lease	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			STATE STATE FEE	
	CES AND REPORTS ON WE			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7Lease Name or Unit Agreement Name		
Type of Well:	TUT) FOR SUCH FROPOSALS.		Merit State "33"	
WELL X WELL	OTHER	FETAITIAL	sWell No.	
Pogo Producing Company	CONF	DENTIAL	1	
³ Address of Operator P. O.Box 10340, Midland, TX 7970	2-7340		Pool name or Wildcat Saumal Penn	
•Well Location				
Unit Letter <u>A</u> : <u>990</u>	Feet From The North	Line and990	Feet From The East Line	
Section 33	Township 16S	Range 33E	NMPM Lea County	
i₀Elevation (<i>Show whether DF, RKB, RT, GR, etc.</i>) 4207' GR				
¹¹ Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INT			SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
	CHANGE PLANS	COMMENCE DRILLING O	PNS. PLUG AND ANBANDONMENT	
PULL OR ALTER CASING	—	CASING TEST AND CEME		
OTHER:		OTHER: Spud, Set Surface, Inter & Prod Casing		
2Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed				
work) SEE RULE 1103.				
Spud & Set Surface Csg-MIRU Lakota Rig #1. Spud @ 2100 hrs CDT 04/19/98. Drld 17-1/2" hole to 445'. TD reached @ 0300 hrs CDT 04/20/98. Ran 10 jts 13-3.8", 48#, H-40, ST&C csg. TPGS @ 445'. IFV @ 399'. BJ cmt'd csg w/ 400 sxs BJ Lite @ 12.8 ppg followed by 200 sxs CI "C" + 2% CaCl2 @ 14.8 ppg. Plug down @ 0815 hrs CDT 04/20/98. Recov 185 sxs excess cmt. WOC 20 hrs. Cmt has a compressive strength over 500 psi after 8 hrs. Make cut-off. Weld on wellhead. NU BOP's & test to 2000 psi.				
Float shoe @ 4500'. Float collar @ 4	1469'. BJ cmt'd w/ 2150 sxs BJ Li	ite @ 12.4 ppg followed	Ran 120 jts 9-5/8", 47#, N-80, LT&C csg. by 200 sxs Ci "C" + 1% CaCl2 @ 14.8 ppg. . NU wellhead & test to 1500 psi. NU BOP's	
CL "H" + .8% FL-25 F/14,900'-14,750 LT&C csg. Float shoe @ 13,266'. F)'. Spot 200 sxs Cl "H" + .9% FL- loat collar @ 13,177'. BJ cmt'd w	25 F/13,700'-13,250'. V / 1400 sxs Cl "H" + .9%	well w/ Schlumberger. RU BJ. Spot 100 sxs VOC. Ran 307 jts 5-1/2", 17# & 20# P-110, FL-25 + .1% R3 + .1% SMS @ 15.7 ppg. te cut-off. Install wellhead & test to 4000 psi.	

I hereby certify that the information above is true and complete to the best of my SIGNATURE	knowledge and belief. TITLE Division Operations Engineer	DATE 08-19-98
TYPE OR PRINT NAME Barrett L. Smith		TELEPHONE NO. (915)685-8100
(This space for State Use)		
ORIGINAL SIGNED BY CHPIS WILLIAMS APPROVED BY DISTRICT I SUPERVISOR	TITLE	date <u>SEP 0.3.1998</u>