Sub it 3 Copies to / proprate D strict Office	State of New Energy, minerals and Natura		Form C-103 Revised 1-1-89
<u>DISTRICT I</u> P.O. Box 1980, Hodda, NM 88240 DISTRICT II	OIL CONSERVAT P.O. Box Santa Fe New Mex	2088	WELL API NO. 30-025-34714
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410		5. Indicate Type of Lease STATE X FEE	
(DO NOT USE THIS FORM FOR PF DIFFERENT RESE	TICES AND REPORTS ON A ROPOSALS TO DRILL OR TO DEE RVOIR. USE "APPLICATION FOR C-101) FOR SUCH PROPOSALS.)	PEN OR PLUG BACK TO A	VA-753 7. Lease Name or Unit Agreement Name
1. Type of Well: OIL OIL WELL X WELL C] OTHER		C. O. Jones ATK State Com
2. Name of Operator YATES PETROLEUM CORPORT	RATION		8. Well No. 1
 Address of Operator 105 South 4th St., Ar Well Location 	tesia, NM 88210		9. Pool name or Wildcat Wildcat Mississippian
	0 Feet From The South	Line and1080	Feet From The Line
Section 11	///////	Range 35E <i>ther DF, RKB, RT, GR, etc.)</i> 36' GR	NMPM Lea County
11. Check	Appropriate Box to Indica		eport, or Other Data
NOTICE OF IN	TENTION TO:	SUB	SEQUENT REPORT OF:
ل ـــا	PLUG AND ABANDON	BEMEDIAL WORK	
PERFORM REMEDIAL WORK		-	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER:_Perforat	BOPNS. PLUG AND ABANDONMENT
TEMPORARILY ABANDON Image: Complete Co	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER: Perforat of and give pertinent dates, inclu- anit. Nippled up ogging tools and r UH with bit, scrap and tubing and tag of acid. POOH with 'casing guns and 38, 39, 40, 41, 4 Dian). TOOH with off tool and 2-3/8 O gallons of 15% cree. Swabbed. S led tubing and uns end belief.	BOPNS. PLUG AND ABANDONMENT EMENT JOB ding estimated date of starting any proposed BOP. an GR/CCL/CBL log. TOOH with er and tubing. Shut well in. ged up at 12479'. Pickled h bit, scraper and tubing. perforated <u>12232-12265' w/42</u> 2, 43, 44, 47, 48, 58, 59, 60, casing guns and rigged down " tubing. Set packer at 12150'. iron control HCL acid and ball hut well in. et packer. TOOH with packer CONTINUED ON NEXT PAGE:
TEMPORARILY ABANDON PULL OR ALTER CASING PULL OR ALTER CASING DTHER: 12. Describe Proposed or Completed Operations 6-6-2000 - Moved in an 6-7-2000 - Rigged up to 1000 galloc 6-8-2000 - Finished TI tubing with 1000 galloc Shut well in. 6-9-2000 - Rigged up to .42" holes as follows: 61, 62, 63, 64 & 12265 wireline. TIH with particle Acidized perforations sealers. Nippled down 6-10-12-2000 - Swabbed 6-13-2000 - Bled well I hereby certify the the information above is the substant of the s	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER: Perforat of and give pertinent dates, inclu- anit. Nippled up ogging tools and r UH with bit, scrap and tubing and tag of acid. POOH with 'casing guns and 38, 39, 40, 41, 4 Dian). TOOH with off tool and 2-3/8 O gallons of 15% cree. Swabbed. S led tubing and uns end belief.	BOPNS. PLUG AND ABANDONMENT EMENT JOB te, acidize & frac ding estimated date of starting any proposed BOP. an GR/CCL/CBL log. TOOH with er and tubing. Shut well in. ged up at 12479'. Pickled h bit, scraper and tubing. perforated <u>12232-12265'</u> w/42 2, 43, 44, 47, 48, 58, 59, 60, casing guns and rigged down " tubing. Set packer at 12150'. iron control HCL acid and ball hut well in. et packer. TOOH with packer CONTINUED ON NEXT PAGE: echnician DATE July 31, 2000
TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Completed Operations 6-6-2000 - Moved in an 6-7-2000 - Rigged up to logging tools and rigg 6-8-2000 - Finished TI tubing with 1000 galloc Shut well in. 6-9-2000 - Rigged up to .42" holes as follows: 61, 62, 63, 64 & 12265 wireline. TIH with pa Acidized perforations sealers. Nippled down 6-10-12-2000 - Swabbed 6-13-2000 / Bled well I hereby certify the the information above is to .42.	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER: Perforat of and give pertinent dates, inclu- anit. Nippled up ogging tools and r UH with bit, scrap and tubing and tag of acid. POOH with 'casing guns and 38, 39, 40, 41, 4 Dian). TOOH with off tool and 2-3/8 O gallons of 15% cree. Swabbed. S led tubing and uns end belief.	BOPNS. PLUG AND ABANDONMENT EMENT JOB te, acidize & frac ding estimated date of starting any proposed BOP. an GR/CCL/CBL log. TOOH with er and tubing. Shut well in. ged up at 12479'. Pickled h bit, scraper and tubing. perforated <u>12232-12265'</u> w/42 2, 43, 44, 47, 48, 58, 59, 60, casing guns and rigged down " tubing. Set packer at 12150'. iron control HCL acid and ball hut well in. et packer. TOOH with packer CONTINUED ON NEXT PAGE: echnician DATE July 31, 2000 TELEPHONE NO. 505/748-14
TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Completed Operations 6-6-2000 - Moved in an 6-7-2000 - Rigged up w logging tools and rigg 6-8-2000 - Finished TI tubing with 1000 galloc Shut well in. 6-9-2000 - Rigged up w .42" holes as follows: 61, 62, 63, 64 & 12265 wireline. TIH with pa Acidized perforations sealers. Nippled down 6-10-12-2000 - Swabbed 6-13-2000 Bled well Ihereby certify the the information above is to SKONATURE Market Rusty Klein	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER: Perforat of and give pertinent dates, inclu- anit. Nippled up ogging tools and r UH with bit, scrap and tubing and tag of acid. POOH with 'casing guns and 38, 39, 40, 41, 4 Dian). TOOH with off tool and 2-3/8 O gallons of 15% cree. Swabbed. S led tubing and uns end belief.	BOPNS. PLUG AND ABANDONMENT EMENT JOB te, acidize & frac ding estimated date of starting any proposed BOP. an GR/CCL/CBL log. TOOH with er and tubing. Shut well in. ged up at 12479'. Pickled h bit, scraper and tubing. perforated <u>12232-12265'</u> w/42 2, 43, 44, 47, 48, 58, 59, 60, casing guns and rigged down " tubing. Set packer at 12150'. iron control HCL acid and ball hut well in. et packer. TOOH with packer CONTINUED ON NEXT PAGE: echnician DATE July 31, 2000

2A	mississippia	in