	-			
	State of New Mexico			Form C-103
abmit 3 Copies Appropriate istrict Office	Energy, Minerals and Natural Resources Department		·	Revised 1-1-89
ISTRICT I O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO.	
ISTRICT II	Santa Fe, New Mexico 87504-2088		30-025-35377 5. Indicate Type of Lease	
O. Drawer DD, Artesia, NM 88210				STATE X FEE
1000 Rio Brazos Rd., Aziec, NM 87410		6. State Oil & Gas Lease No. VO-4837		
	TICES AND REPORTS ON WEL	15		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT REGERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit	Agreement Name
Type of Well: OIL GAS WELL X OTHER		Avian AYA State		
Name of Operator			8. Well No.	<u> </u>
YATES PETROLEUM CORPO	RATION		1	
Address of Operator 105 South 4th St., Ar	tesia, NM 88210	-	9. Pool name or Wildow Wildow Hiss	ather Morrow
Well Location	050 0 1		0	
Unit Letter ?	850 Feet From The South	Line and <u>60</u>	0 Feet From The	<u> </u>
Section 20	Township 15S Ra	inge <u>32E</u>	NMPM Le	a County
	10. Elevation (Show whether	5' GR		
Checl	k Appropriate Box to Indicate		Report, or Other Da	ta
	NTENTION TO:	SUE	BSEQUENT REP	ORT OF:
		REMEDIAL WORK		
		COMMENCE DRILLIN		
	CHANGE PLANS			
JLL OR ALTER CASING	— 1	CASING TEST AND C		x
THER:		OTHER: Perfor		
 Describe Proposed or Completed Op work) SEE RULE 1103. 	verations (Clearly state all pertinent details, a	nd give pertinent dates, incl	uding estimated date of star	ting any proposed
	ocation and set anchors.	Moved in and	rigged up pull	ing unit. Nippled
up BOP. Shut well i	n.			
5-4-2001 - TIH with	bit, scraper and tubing ith tubing, scraper and	to 12556'. Dis	splaced hole W1 1 in.	th 7% KUL WITH
surfactants. 100h w 5-5-7-2001 - Rigged	up wireline. TIH with 1	logging tools a	nd ran GR/CBL 1	og. TOOH with
leasing toold and ri	gged down wireline. Shu	00 0		
Togging coors and in	Red down witerine. Dur	it well in.		
5-8-2001 - Rigged up	wireline. TIH with 3-3	it well in. 3/8" casing gun:	s and perforate	d 12513-12522'
5-8-2001 - Rigged up w/78 .42" holes (6)	wireline. TIH with 3-3 SPF - Morrow). TOOH. T	nt well in. 3/8" (casing gun) 11H with wirelin	s and perforate ne set Arrow pa	d 12513-12522' cker with blanking
5-8-2001 - Rigged up w/78 .42" holes (6	wireline. TIH with 3-3 SPF - Morrow). TOOH. T ipple. Set packer at 12	it well in. 3/8" casing gun TIH with wirelin 2270'. TOOH and	s and perforate ne set Arrow pa d rigged down w	d 12513-12522' cker with blanking ireline. TIH with
5-8-2001 - Rigged up w/78 .42" holes (6 plug in 1.87" seal n seal connector. Lat Shut well in.	wireline. TIH with 3-3 SPF - Morrow). TOOH. T hipple. Set packer at 12 sched onto packer and spa	at well in. 3/8" casing gun 21H with wirelin 2270'. TOOH and aced out. Nipp	s and perforate ne set Arrow pa d rigged down w led down tree a	d 12513-12522' cker with blanking ireline. TIH with nd nippled up flang
5-8-2001 - Rigged up w/78 .42" holes (6 plug in 1.87" seal n seal connector. Lat Shut well in. 5-9-2001 - Swabbed t	wireline. TIH with 3-3 SPF - Morrow). TOOH. T ipple. Set packer at 12 ched onto packer and spa ubing down to 3000'. Ri	it well in. 3/8" casing gun TH with wirelin 2270'. TOOH and aced out. Nipp lgged up slickl	s and perforate ne set Arrow pa d rigged down w led down tree a ine. TIH and p	d 12513-12522' cker with blanking ireline. TIH with nd nippled up flang ulled equalizing
5-8-2001 - Rigged up w/78 .42" holes (6 plug in 1.87" seal n seal connector. Lat Shut well in. 5-9-2001 - Swabbed t probe. Pressured to	wireline. TIH with 3-3 SPF - Morrow). TOOH. T hipple. Set packer at 12 sched onto packer and spa	it well in. 3/8" casing gun TH with wirelin 2270'. TOOH and aced out. Nipp lgged up slickl	s and perforate ne set Arrow pa d rigged down w led down tree a ine. TIH and p	d 12513-12522' cker with blanking ireline. TIH with nd nippled up flang ulled equalizing
5-8-2001 - Rigged up w/78 .42" holes (6 plug in 1.87" seal n seal connector. Lat Shut well in. 5-9-2001 - Swabbed t probe. Pressured to Shut well In.	wireline. TIH with 3-3 SPF - Morrow). TOOH. T Lipple. Set packer at 12 sched onto packer and spa subing down to 3000'. Ri 200 psi. TIH and pulle	at well in. 3/8" casing guns TIH with wirelin 2270'. TOOH and aced out. Nipp lgged up slickl ed plug. Rigge	s and perforate ne set Arrow pa d rigged down w led down tree a ine. TIH and p	d 12513-12522' cker with blanking ireline. TIH with nd nippled up flang ulled equalizing
5-8-2001 - Rigged up w/78 .42" holes (6 plug in 1.87" seal n seal connector. Lat Shut well in. 5-9-2001 - Swabbed t probe. Pressured to Shut well In.	wireline. TIH with 3-3 SPF - Morrow). TOOH. T Lipple. Set packer at 12 sched onto packer and spa ubing down to 3000'. Ri 200 psi. TIH and pulle	It well in. 8/8" casing guns TH with wirelin 2270'. TOOH and aced out. Nipp lgged up slickl ed plug. Rigged friment.	s and perforate ne set Arrow pa d rigged down w led down tree a ine. TIH and p d down slicklin	d 12513-12522' cker with blanking ireline. TIH with nd nippled up flang ulled equalizing
5-8-2001 - Rigged up w/78 .42" holes (6 plug in 1.87" seal n seal connector. Lat Shut well in. 5-9-2001 - Swabbed t probe. Pressured to Shut well In. Iterty Grad Conference as seed sionature	wireline. TIH with 3-3 SPF - Morrow). TOOH. T Lipple. Set packer at 12 sched onto packer and spa ubing down to 3000'. Ri 200 psi. TIH and pulle present protect of the department of the second present protect of the department of the second	at well in. 3/8" casing guns TH with wirelin 2270'. TOOH and aced out. Nipp lgged up slickl ed plug. Rigge	s and perforate ne set Arrow pa d rigged down w led down tree a ine. TIH and p d down slicklin	d 12513-12522' cker with blanking ireline. TIH with nd nippled up flang ulled equalizing e. Flow tested. DATE May 29, 2001
5-8-2001 - Rigged up w/78 .42" holes (6 plug in 1.87" seal n seal connector. Lat Shut well in. 5-9-2001 - Swabbed t probe. Pressured to Shut well In. Hordfordfordfordfordfordford	wireline. TIH with 3-3 SPF - Morrow). TOOH. T Lipple. Set packer at 12 sched onto packer and spa ubing down to 3000'. Ri 200 psi. TIH and pulle present protect of the department of the second present protect of the department of the second	at well in. 3/8" casing gun 2270'. TOOH and aced out. Nipp agged up slickl ed plug. Rigger frement. Operations	s and perforate ne set Arrow pa d rigged down w led down tree a ine. TIH and p d down slicklin Technician	d 12513-12522' cker with blanking ireline. TIH with nd nippled up flang ulled equalizing e. Flow tested.
5-8-2001 - Rigged up w/78 .42" holes (6 plug in 1.87" seal n seal connector. Lat Shut well in. 5-9-2001 - Swabbed t probe. Pressured to Shut well In. Histiger William Store as a seed skonature William Rusty Klee	wireline. TIH with 3-3 SPF - Morrow). TOOH. T Lipple. Set packer at 12 sched onto packer and spa ubing down to 3000'. Ri 200 psi. TIH and pulle present protect of the department of the second present protect of the department of the second	At well in. 3/8" casing guns CIH with wirelin 2270'. TOOH and aced out. Nipp 1gged up slickl ed plug. Rigger frement. Operations Cong. Paul	s and perforate ne set Arrow pa d rigged down w led down tree a ine. TIH and p d down slicklin Technician	d 12513-12522' cker with blanking ireline. TIH with nd nippled up flang ulled equalizing e. Flow tested. DATE May 29, 2001
5-8-2001 - Rigged up w/78 .42" holes (6 plug in 1.87" seal n seal connector. Lat Shut well in. 5-9-2001 - Swabbed t probe. Pressured to Shut well In. Iterty Gent Conductor as seed signature	wireline. TIH with 3-3 SPF - Morrow). TOOH. T Lipple. Set packer at 12 sched onto packer and spa ubing down to 3000'. Ri 200 psi. TIH and pulle present product rish department in	At well in. 3/8" casing guns CIH with wirelin 2270'. TOOH and aced out. Nipp 1gged up slickl ed plug. Rigger frement. Operations Cong. Paul	s and perforate ne set Arrow pa d rigged down w led down tree a ine. TIH and p d down slicklin Technician	d 12513-12522' cker with blanking ireline. TIH with nd nippled up flang ulled equalizing e. Flow tested.