

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 14931

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Tonto Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Lusk, Bone Springs &
Wolfcamp, East11. SEC., T., R., W., OR BLK. AND
SURVEY OR AREA

27-19S-32E

12. COUNTY OR PARISH 13. STATE

Lea

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)1. OIL ☒ GAS ☐
WELL WELL OTHER

2. NAME OF OPERATOR

Sun Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 1861 Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State **MODER, NEW MEXICO**
See also space 17 below.)
At surface

660 FNL, 660 FWL of Sec. 27, TNSP 19S, RG. 32E, UNIT D

14. PERMIT NO.

Blanket

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

RKB 3606, GR 3588

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.) *

1978

4-16/21

MIRU, cleaned around well & dugout cellar, NU BOP, pull 2 7/8" tbg, run gauge ring to 10000', dumped 35' cmt plug on CIB Pat 10,500', set CIBP @ 10,000', dumped 35' cmt plug on CIBP, load hole w/9.5# brine, ND BOP & WH, weld on to 5 1/2" csg, pull slips & worked csg, ran free point, stuck at 7700', cut pipe at 7650', pulled csg, NU BOP, TIH w/2 7/8" tbg to 7686, circ hole w/10# mud, spot 50 sk cmt plug 7500/7686', spot cmt plug 4400'/4586', spot 35 sks cmt 2530/2630', 35sk 950/1050, 30 sks 90' to surface. ND BOP, cut off csg flange. Weld plate on 9 5/8" csg, inst dry hole marker, RR 4 PM

18. I hereby certify that the foregoing is true and correct

SIGNED Dew Harry

TITLE Office Assistant


DATE 4-26-78

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:



*See Instructions on Reverse Side

APPROVED

RECEIVED

AUG 15 1978

U.S. DEPARTMENT OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION
WASHINGTON, D.C.