

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-02017</u>
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-1520
7. Lease Name or Unit Agreement Name BRIDGES STATE
8. Well No. 9
9. Pool name or Wildcat VACUUM GRAYBURG (SAN ANDRES)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator Mobil Producing Tx. & N.M. Inc.*	3. Address of Operator *Mobil Exploration & Producing U.S. Inc., as Agent for Mobil Producing TX. & N.M. Inc., P. O. Box 633, Midland, TX 79702	4. Well Location Unit Letter <u>N</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>1980</u> Feet From The <u>WEST</u> Line Section <u>13</u> Township <u>17S</u> Range <u>34E</u> NMPM LEA County <u></u>
10. Elevation (Show whether DF, RKB, RT, GR, etc.)			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU. DIG PIT. FLOW WELL TO PIT. ND WH. NU BOP.
2. POOH W/2JT 2-7/8 TBG. RIH W/CIBP @ 4343. LOAD HOLE W/MUD. CAP W/35 FT CL C CMT.
3. PUH TO 2910. SPOT 100 FT CMT PLUG 2910-2810.
4. PUH TO 1827. CUT & PULL 7 CSG; PERF & SQZ 100 FT CL C CMT PLUG 1827-1727.
5. PUH TO 855. SPOT 100 FT CL C CMT PLUG ACROSS 10-3/4 SHOE 855-755.
(IF 7 CSG NOT RECOVERED, PERF & SQZ 100 FT PLUG)
6. PUH TO 30. SPOT 30 FT CL C CMT PLUG 30-SURF. POOH W/WS.
7. ND BOP. RDPU. DIG OUT CELLAR; CUT CSG 3 FT BELOW SURF. WELD PLATE ON CSG STUB. ERECT
P&A MARKER W/WELL NAME AND P&A DATE. FILL CELLAR & CLEAN LOCATION

SEE ATTACHED CURRENT AND PROPOSE WELLBORE SKETCHES AND RECOMMENDED PROCEDURES FOR MORE INFORMATION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kaye Pollock TITLE REGULATORY TECH. DATE 05-07-93
TYPE OR PRINT NAME KAYE POLLOCK (915)
TELEPHONE NO. 688-2584

(This space for State Use)

APPROVED BY TITLE DATE MAY 11 1993

CONDITIONS OF APPROVAL, IF ANY:

BRIDGES STATE #9
VACUUM GRAYBURG (SAN ANDRES) FIELD
LEA COUNTY, NEW MEXICO

RECOMMENDED WORKOVER PROCEDURE

1. MIRU PU. DIG PIT. FLOW WELL BACK TO PIT. ND WH. NU BOP.
2. POOH W/ 2 JTS 2-7/8" TBG. RIH W/ WS TO CIBP @ 4343'. LOAD HOLE W/ 9.5 PPG MUD. CAP CIBP W/ 35' CLASS C NEAT CMT.
3. PUH TO 2910'. SPOT 100' CLASS C NEAT CMT PLUG ACROSS SALT BASE FROM 2910-2810'.
4. PUH TO 1827'. CUT AND PULL 7" CSG OR PERFORATE AND SQUEEZE 100' CLASS C NEAT CMT PLUG ACROSS SALT TOP FROM 1827-1727'.
5. PUH TO 855'. SPOT 100' CLASS C NEAT CMT PLUG ACROSS 10-3/4" CSG SHOE FROM 855-755'. (IF 7" CSG NOT RECOVERED, PERFORATE AND SQUEEZE 100' PLUG).
6. PUH TO 30'. SPOT 30' CLASS C NEAT CMT PLUG FROM 30'-SURFACE. POOH W/ WS.
7. ND BOP. RD PU. DIG OUT CELLAR AND CUT CSG 3' BELOW SURFACE. WELD STEEL PLATE ON CSG STUB. ERECT P&A MARKER WITH WELL NAME AND PLUGGED DATE. FILL CELLAR AND CLEAN SURFACE LOCATION.

NOTE: P&A PROCEDURE DISCUSSED WITH PAUL KAUTZ AT NMOC ON MAY 3, 1993.

