

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-1446	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	West Vacuum Unit
3. Address of Operator	8. Farm or Lease Name
P. O. Box 728, Hobbs, New Mexico 88240	West Vacuum Unit
4. Location of Well	9. Well No.
UNIT LETTER <u>H</u> 1980 FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM	10. Field and Pool, or Wildcat
THE <u>East</u> LINE, SECTION <u>3</u> TOWNSHIP <u>18-S</u> RANGE <u>34-E</u> NMPM.	Vacuum Grayburg
15. Elevation (Show whether DF, RT, GR, etc.)	San Andres
4030' (DF)	12. County
	Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Repair Waterflow

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Pull rods, pump & tubing. Install BOP.
2. Set RBP @ 3658'. Perforate 5 1/2" Csg w/2 JS @ 1645'.
3. Set cement retainer @ 1604'. Cemented to surface through perfs. @ 1645' w/720 sx. class 'H' cement. Follow with squeeze using 350 sx. class 'H' cement. WOC. DOC. Tested OK.
4. Install production equipment. Test & return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. Ahluff TITLE Asst. Dist. Mgr. DATE 5/6/81  
APPROVED BY Oil & Gas Insp. TITLE  DATE   
CONDITIONS OF APPROVAL, IF ANY: