

PR-4

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

## NEW MEXICO OIL CONSERVATION COMMISSION

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>Unknown</b>
7. Unit Agreement Name
8. Farm or Lease Name <b>New Mexico "H" State</b>
9. Well No. <b>1</b>
10. Field and Pool, or Wildcat <b>E. K. Queen</b>
12. County <b>Lea</b>

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator <b>Sunray DX Oil Company</b>
3. Address of Operator <b>P. O. Box 1416, Roswell, New Mexico</b>
4. Location of Well UNIT LETTER <b>0</b> <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM THE <b>East</b> LINE, SECTION <b>7</b> TOWNSHIP <b>18S</b> RANGE <b>34E</b> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) <b>4081 G.L.</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- TD 4410'. O.H. Comp. 4390-4410'. 5 1/2" 14#, J-55 csg. set @ 4390' w/150 sx. Calc. top of cement @ 3600'. 13 3/8" csg @ 247' w/250 sx. Cmt. circulated to surface.
- Pull rods, Load hole w/mud.
- Place 25 sx cmt. plug w/tubing over Queen prod form - 4410 to 4330'. Pull tbq.
- Cut off 5 1/2" csg @ approx. 3500'.
- Set 25 sx. cmt. plug in and out of 5 1/2" stub 3540-3460'.
- Set 25 sx. cmt. plug over Yates 3240-3160'.
- Set 25 sx. cmt. plug over salt section 3040-2960'.
- Set 25 sx. cmt. plug over Rustler anhydrite 1780-1700'.
- Place 25 sx cmt plug at base of 13 3/8" - 250-225'.
- Place 10 sx plug at surface and install dryhole marker.
- Remove surface equipment and clean up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. F. Brawley B. F. Brawley TITLE District Engineer DATE 10-20-66

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: