

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions
verse side)7-
e-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-063645

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Sivley-Federal

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

E-K Yates 7/Rivers Queen

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 19, T-18-S, R-34-E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Mobil Oil Corporation

3. ADDRESS OF OPERATOR

Box 633, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

2310' FWL to 343' FSL, Sec. 19, T-18-S, R-34-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3956 GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Sivley Federal #3

1. Pull rods and pump and tubing at 3630'

2. Circulate hole to mud laden fluid (25 sxgel/100 bbls water)

3. Spot 100' cement plug (3250'-3150') across top of Yates at 3200' (20 sx in 5½")

4. Check Free point of pipe

A. If free point is below 1600'

1. Cut and pull all free 5½" 14# casing and set 100' cement across stub
(35 sx plug)

2. Set 100' plug at 1700' in open hole (bottom at 1750' and top at 1650') (35sx)

OR B. If free point is above 1600'

1. Set 100' plug in 5½" casing at 1700' (bottom at 1750' and top at 1650' (20 sx)

2. Cut and pull all free 5½" 14# casing and set 100' plug across stub (35sx)

5. Set 100' cement plug across 2 5/8" casing seat at 294' (35 sx plug from 350' up to 250')

6. Spot 10 sx plug at surface, erect monument, remove equipment, flowlines and tank
battery, clear location.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Authorized Agent

DATE

7-30-75

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
JUL 25 1975
JIM R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.