Submit 3 Copies To Appropriate District Office	State of Ne Energy, Minerals and					Form C-1 Revised March 25, 1	
District I 1625 N. French Dr., Hobbs, NM 87240 District II 811 South First, Artesia, NM 87210	OIL CONSERVA			WELL AP 5. Indicate	30-025-0	03047	
District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV	2040 Sout Santa Fe, I				TE X	FEE	
2040 South Pacheco, Santa Fe, NM 87505				 6. State O B-1713 	il & Gas I	Lease No.	
(DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC		EPEN (OR PLUG BACK TO A	7. Lease N	lame or U	Init Agreement Name:	
PROPOSALS.) 1. Type of Well:				VACUUM AI	90 UNIT		
Oil Well 🕱 Gas Well 🗌	Other			TRACT 13			
2. Name of Operator				8. Well N	э.		
Phillips Petroleum Company				06			
3. Address of Operator				9. Pool na		ldcat	
4001 Penbrook Street Odessa, 4. Well Location	<u>TX 79762</u>			VACUUM AL	O REEF		_
Unit Letter A :	330 feet from the	NOF	TH line and	660	feet from	the EAST li	
	leet nom the	16.4		000	leet nom	theEASTlin	le
Section 4	Township 18		Range 35-E	NMPM	LEA	County	
		GR GR	, 3950' RKB				
11. Check A	ppropriate Box to Ind	icate	Nature of Notice,	Report, or	Other I	Data	
NOTICE OF INTE	ENTION TO:		SUB	SEQUEN	IT REP	ORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	X	REMEDIAL WORK			ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLI	NG OPNS.		PLUG AND ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AND CEMENT JOB			ADANDONNENT	
OTHER:			OTHER:				

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Plug and Abandon Procedure, before and after wellbore schematics attached.

THE COMMERCIAL MUST CONTRACT HOURS PRIME CONTRACT CONTRACT PLUGGMO MARKANGNE CLATTER AND 3 FO BE APPRIMED.

SIGNATURE Starsfinder			DATE_	02/05/02
Type or print name L. M. SANDERS			Telephone No.	915-368-1488
(This space for State use)	· .			
APPROVED BY		TITLE	DATE_	EB 0 7 2002
Conditions of approval, if any:			DATI	COUL

PLUG AND ABANDON WELL PROCEDURE VACUUM ABO UNIT #13-06

NOTE: Cement used is Class "C", density of 14.8 ppg, yield of 1.32 cubic feet per sack.

- 1. Notify NMOCD at (505) 393-6161, 24 hours prior to initiating plugging operations.
- 2. MIRU Plug & Abandon Package.
- 3. ND wellhead. Freepoint 5-1/2" casing. (TOC by temperature survey @ 3290') Freepoint 8-5/8" casing. NU PPCo. Class 1 shop tested BOPE stack.
- 4. GIH w/ 2-3/8" WS open-ended and tag CIBP @ 8420'. Circulate 5-1/2" casing with 9.5 ppg mud-laden fluid.
- 5. Spot Plug No. 1, minimum 25 sx., calculated interval: 8420'-8167'. WOC and tag. The plug will cover the Abo Reef.
- 6. POOH & LD to 6400'. Spot Plug No. 2, 30 sx., minimum 25 sx., calculated interval: 6400'-6104'. The plug will cover the Clearfork and Glorieta.
- 7. POOH & LD to 4650'. Spot Plug No. 3, minimum 25 sx., calculated interval: 4650'-4403'. The plug will cover the San Andres.
- 8. POOH & LD to 3975'. Spot Plug No.4, minimum 25 sx., calculated interval: 3975'-3728'. The plug will cover the Queen.
- 9. POOH w/ WS. MIRU wireline. GIH w/ wireline. Cut 5-1/2" casing @ 3275'or closest freepoint. POOH wireline. Pull 5-1/2" casing.
- 10. GIH w/ WS to 3325' (or 50' below stub or casing shoe, whichever is deeper) Spot Plug No. 5, 35 sx., minimum interval: 50' below stub or shoe 50' above stub or shoe (whichever is closer to surface), calculated interval: 3325'-3169'. WOC and tag. The plug covers the casing stub and intermediate casing shoe.
- 11. POOH & LD WS to 3010'. Spot Plug No.6, 35 sx., minimum interval: 3010'-2910', calculated interval: 3010'-2875'. The plug covers the Yates.
- 12. POOH & LD to 1650'. Spot Plug No. 7, 35 sx., minimum interval: 1650'-1550', calculated interval: 1650'-1521'. The plug will cover the Rustler.
- POOH w/ WS. GIH w/ wireline and stringshot 8-5/8" casing @ nearest collar above freepoint. RD wireline. LD 8-5/8" casing. Go to Step 14 if freepoint is above surface casing shoe; go to Step 15 if freepoint is below surface casing shoe.

- GIH w/ WS to 375'. Spot Plug No. 8, 50 sx., minimum and calculated interval: 375'-268'. The plug covers the surface casing shoe and serves as the surface plug. Go to Step 16.
- 15. GIH w/WS to 50' inside casing stub. Spot Plug No. 8, 50 sx., minimum interval: 50' below casing stub to 50' above surf. csg. shoe. The plug covers the csg. stub, & surface casing shoe.
- 16. POOH LD to 75'. Spot Plug #9, 50 sx, minimum interval: 60'-surface, calculated interval: 75'-surface. TOOH & LD workstring. WOC. Visually tag cement and top off if necessary.
- 17. Cut off casing and wellhead 3' below GL and cap well. Install dry hole marker. Perform reclamation work.
- 18. Send forms and reports to:

Phillips Regulatory 4001 Penbrook Odessa, Texas 79762



Phillips Petroleum Company - Southwest Region VACUUM ABO UNIT #13-06

O:\Everyone\Drilling\P&A's\New Mexico\VAU #13-06.xls

W. Negrey 1/23/2002