

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.E.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
B-1031

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name Central Vacuum Unit
2. Name of Operator Texaco Inc.	8. Farm or Lease Name Central Vacuum Unit
3. Address of Operator P. O. Box 728, Hobbs, New Mexico	9. Well No. 110
4. Location of Well UNIT LETTER J . . . 1980 FEET FROM THE South LINE AND 2310 FEET FROM THE East LINE, SECTION 6 TOWNSHIP 18-S RANGE 35-E NMPM.	10. Field and Pool, or Wildcat Vacuum Grayburg San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 3975' (GR)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice; Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <u>Repair waterflow & treat</u> <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Pull rods & pump. Pull tubing.
2. Set RBP @ 3800'. Perforate 5 1/2" csg w/2-JS @ 1555'.
3. Set cement retainer @ 1491'. Cement 5 1/2" csg perfs. @ 1555' w/680 sx. WOC.
4. Resqueeze w/60 sx. class 'C' Thix-set cement. WOC. DOC. Tested OK.
5. Set pkr. @ 4000'. Acidize open-hole 4070'-4700' w/7000 gals 20% NEFE Acid in 5-stages using 2000# moth balls & 200# rock salt between stages.
6. Install pumping equipment. Test & return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Asst. Dist. Mgr. DATE 2/13/81

ORIG. SIGNED BY Jerry Sexton

APPROVED BY Dist. Mgr. TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: