NO. OF COPIES RECEIVED	HOBBS OFFICE O. C. C.	Form C-103 Supersedes Old C-102 and C-103	
DISTRIBUTION			
SANTA FE	NEW MEXICO OF CONSERVATION COMMISSION	Effective 1-1-65	
FILE	9 45 AH 'FF	5g. Indicate Type of Lease	
U.S.G.S.		State X Fee.	
LAND OFFICE		5. State Oil & Gas Lease No.	
OPERATOR			
	E-818		
(DO NOT USE THIS FORM FOR F			
1.	7, Unit Agreement Name		
OIL CAS	-		
2. Name of Operator	8. Farm or Lease Name		
Humble Oil & Refi	New Mexico, State BP		
3. Address of Operator	9. Well No.		
Box 2100, Hobbs,	1		
4. Location of Well	10. Field and Pool, or Wildcat		
	south 1575	Vacuum Abo	
UNIT LETTER A	2300 FEET FROM THE South LINE AND 1575 FEET FROM		
TT 1	a 185 35-E		
THE West LINE, SEC	TION 7 TOWNSHIP 18-S RANGE 35-E NMPM	·/////////////////////////////////////	
	12. County		
	Lea Allilli		
$\overline{\mathbf{v}}$	3977 DF		
^{16.} Checl	Appropriate Box To Indicate Nature of Notice, Report or Ot	her Data	
NOTICE OF	INTENTION TO: SUBSEQUEN	T REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB		
	OTHER		
OTHER			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1905.

Moved in and rigged up contract unit. Killed well with 100 barrels of water. Tagged bottom at 9005. Pulled tubing. Ran Lynes straddle packers. Set top packer at 8864 and bottom packer at 8889. Acidized perforations 8868, 8875 and 8882 with 2,000 gals of 15% N. E. acid with an average injection rate of 1.25 BPM. Max. press. 3500#. Min. press. 2500#. Reset packers at 8839 and 8864. Acidized perforations 8845 and 8848 with 1,000 gals acid. Had communications. Jobs by Cardinal Chemical. Reset packers at 8814 and 8839. Packers deflated, therefore, unable to test perforations 8826 and 8831. Pulled one Lynes packer and tubing. Went back in hole found other Lynes packer had fallen to bottom of hole at 9005. Displaced free acid water in hole with fresh water. Pulled tubing. Reran tubing. Set Baker Model R packer at 8814. Swabbed well dry. Acidized perforations 8826, 8831, 8845, 8848, 8868, 8875 and 8882 with 6,000 gals of acid. Had communications above packer. Max. press. 3500#. Went in on vacuum. Job by the Western Company. Set packer at 8750. Swabbed. Reset packer at 8718. Swabbed. Reset packer at 8688. Swabbed. Reset packer at 8625. Swabbed. Pulled tubing and packer. Reran tubing and Baker Model R packer. Set packer at 8624. Swabbed. Reset packer at 8813. Swabbed. Reset packer at 8750. Swabbed. Reset packer at 8718. Swabbed. Reset packer at 8688. Swabbed. Pulled tubing and packer. Set Halliburton CI squeeze retainer on wire line at 8650. Ran tubing and squeezed perforations 8666, 8672, 8679, (Continued)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.								
SIGNED ESC	· · · · ·		Dist. Adm. Supvr.	DATE	11-24-65			
			<u> </u>					
APPROVED BY		TITLE		DATE	<u> </u>			

CONDITIONS OF APPROVAL, IF ANY