

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 3002503099
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. 011053
7. Lease Name or Unit Agreement Name New Mexico "R" State NCT-4
8. Well No. 1
9. Pool name or Wildcat Vacuum Grayburg (S. Andres)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER ☐	
2. Name of Operator Texaco E&P Inc.	
3. Address of Operator P.O. Box 3109 Midland, TX 79702	
4. Well Location Unit Letter C : 330 Feet From The North Line and 1904 Feet From The West Line Section 7 Township 18S Range 35E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3985 DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data.	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
- This well is dual completed in the same well bore w/central vacuum Unit 124. Both wells will be plugged. (CVU Oil & Gas Lease No. 011122) 124
1. Notify NMOCD of intent to plug & abandon well prior to moving in on well.
 2. RUWL Set CIBP @ 4600 (on central vacuum unit 124) dump 36' of cmt.
 3. Spot 10 sxs cmt. plug 4000-3700 (Queens) central vacuum Unit 124 side.
 4. Cut 2-7/8 csg (on central vacuum unit 124) Laydown 2-7/8" csg @ 3140.
 5. RUWL on New Mexico "R" State NCT #4 #1 side. Set CIBP 4600' dump 36' of cmt.
 6. Spot 10 sxs cmt. plug 4000-3700 (Queens) New Mexico "R" State NCT #4-#1.
 7. Cut 2-7/8 csg @ 3140 (NM"R")
 8. Spot 110 sxs cmt. 3140-2840 (shoe & Yates)
 9. Spot 40 sxs cmt plug 2750-2650 (B-salt)
 10. Spot cmt 40 sxs 1750-1650 (top salt)
 11. Perf. @ 450 Set CICR @ 400'. Circ. cmt. behind 8-5/8" csg to surface w/@115 sxs cmt. Unsting f/CICR & cap CICR w/40 sxs cmt. f/400-300.
 12. Spot 25 sxs cmt. plug f/50 to surface.
 13. Cut off wellhead & weld on cap& install dryhole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE RJ Harding III TITLE Operations Engineer DATE 10-19-94
TYPE OR PRINT NAME RJ Harding III TELEPHONE NO. 915-687-4816

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL IF ANY:

NOV 2 1994

CENTRAL VACUUM UNIT 124

PRESENT

NEW Mexico "R" STATE NCT-4
#1

10 3/4" CSG SET 336'
CMT w/ 300 SX, CMT
Circ. to Surface

8 5/8" CSG SET @ 3128'
CMT w/ 650 SX CMT top
597'.

2 7/8" CSG SET @ 8836'
CMT w/ 1180 SX CMT top
3140' (by temp survey)

Perf 4648-77


Perf 4685-4696'
CIBP @ 4720' w/ 10' of CMT

CIBP @ 8110' w/ 36' of CMT on top

Perf 8143-8760

PBTD 8799'
TD 8840'

PRESENT
 NM "R" State NCT-4 #1
 +
 CVA # 124



PBTD 8799'
 TD 8840