

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-07358
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	
North Hobbs (G/SA) Unit Section 19	
8. Well No.	112
9. Pool name or Wildcat	Hobbs (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER ☐ INJECTOR ☐	
2. Name of Operator Shell Western E&P, Inc.	
3. Address of Operator P.O. Box 576, Houston, TX 77001 Attn: S.A. Galik - 5239 WCK	
4. Well Location Unit Letter <u>D</u> : <u>990</u> Feet From The <u>North</u> Line and <u>990</u> Feet From The <u>West</u> Line Section <u>19</u> Township <u>18S</u> Range <u>38E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3671' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: OAP, AT ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/18 To 4/22/95

POOH w/inj equip. RIH w/Baker RBP and PKR. Set RBP @ 4125' and PKR @ 596'. Perf the following intervals: 4042-50, 4058-64, 4068-72, 4086-4106 (1 JSPF). RIH w/PKR and set @ 3930'. AT Perfs (4042-4106) w/3000 gal 15% HCL and 800# rock salt. Rel PKR and retrieve RBP. RIH w/PKR and set @ 4118'. AT 4127-48 and OH 4254-70 w/1500 gal 15% HCL. Rel PKR. RIH w/RBP and PKR. Set RBP @ 4007. Tst Tools - held ok. Reset PKR @ 777'. Tst csg to 500# for 30 min. - held ok. Tst csg from 777' to surf at 200# for 30 min. Rel PKR and retrieve RBP. POH w/tbg and tools. RIH w/Guiberson Uni VI Pkr and set @ 3937'. Circ csg w/inhibited fluid. Nipple up wellhead. (3 MIT charts attached). Return well to Injection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Shirley A. Galik TITLE Mgr. Reg. & Permitting DATE 10/30/95


TYPE OR PRINT NAME For: G. S. Nady TELEPHONE NO. 713/544-4219

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE NOV 09 1995

CONDITIONS OF APPROVAL, IF ANY:

N-H. u. 19-112
ST chart



PRINTED IN U.S.A.


ITEMS
INSTRUMENT ENGINEERS


BR-2221
0-1000.8

DAY

NIGHT

N.H.U.
19-112
2nd chart
30 min
12/95





PRINTED IN U.S.A.