NEW MEXICO OIL CONSERVATION COMMISSION



MISCELLANEOUS REPORTS ON WEELSN 13 PM

3:33

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RESULT OF TEST OF CASING SHUT-OFF	I	REPORT ON REPAIRING WELL	x
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RECOMPLETION OPERATION		REPORT ON (Other) Acidising	X

January	12, 1	955	Hebbs	, New	Mexico
(Date)					(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

Gulf Oil Corporat	tion	W.	D. Grimes (North	<u>1)</u>	
(Company or Operat	tor)		(Lease)		
Clarke Oil Well Serv	vicing Co.	, Well No	the SE 1/4 SW	1/4 of Sec. 21	
(Contractor)		, ,	, -	,	
т. 18-5, к. 38-Е, ммрм.,	Hebbs	Pool,	Lea	County.	
The Dates of this work were as folows: 1954 thru January 4, 1955					
Notice of intention to do the work (was)	EXECUTE: submitted on Form	m C-102 on Apr11 2	6, 1954 and Deer	19 54 .,	

and approval of the proposed plan (was) (DECOUR) obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

SEE THACKED SHETT

Witnessed by	Gulf	Oll Corporation (Company)	Field Forman (Title)
Approved: OIL CONSERVATION COMMISSION		Name	e information given above is true and complete ledge. Supt. of Prod. Oil Corporation
(Title)	(Date)	Address	

Attachmen t - C-103

Gulf Oil Corporation - W. D. Grimes (North) No. 2-N, 21-185-38E

Repaired easing leak, ran 5-1/2" casing, perforated and sold treated as follows:

- 1. Palled tubing.
- 2. Ban 7" Baker magnesium bridge plug set at 4091'.
- 3. Ran HRC tool. Found top hole at 425'. Found bottom hole at 1687'.
- 4. Set Howce DN retainer at 1550'. Pumped 250 sacks regular ement below retainer with 2000#. Waited 10 minutes, pumped 100 sacks cement at 1000#. Shut down and pressure dropped to 200# in 15 minutes.
- 5. Temperature survey could not find top of coment.
- 6. Ran HRC tool. Pumped below tool 4 bbls per minutes at 1000# at 854'.
- 7. Ran Howco DM retainer set at 814'. Pumped 250 sacks cement at 700#. Shut down and pressure dropped to 0#.
- 8. Ran tubing open ended to 806'. Spotted 66 sacks sement from 806' to 500'. Pumped 500 sacks cement down 7" casing. Circulated out 7" - 13-3/8" annulus approximately 60 sacks cement. Closed bradenhead and equeesed 434 sacks cement down 7" casing at 300#.
- 9. Waited on combat.
- 10. 7" casing would not hold pressure.
- 11. Deilled out coment, retainer, and bridge plug to 4225'.
- 12. Scraped ?" casing from 1031-4095'. Winderreamed from 4109-4225'.
- 13. Ban 132 Jts (4211') 5-1/2" casing set and comented at 4221' with 250 sacks 4% Gel coment. Circulated approximately 50 sacks coment.
- 14. Waited on cement.
- 15. Drilled cement plug from 4190-4210'.
- 16. Perforated 5-1/2" casing from 4176-4190' with 4, 1/2" Jet Heles per foot.
- 17. Acid treated perforations in 5-1/2" easing from 4176-4190' with 500 gallons MCA acid.
- 18. Ran rods and pump. Pumped 38 bbls oil, 56 bbls water 24 hours. Returned well to production.