

3-NMOCC  
1-FILE

XX

SUNDRY

XX

GETTY OIL COMPANY

H. D. MC KINLEY

P. O. BOX 249, HOBBS, NEW MEXICO 88240

3

H 2310

NORTH

330

BOWERS

EAST

30

18-S

38-E

3653 GR

LEA

Check Ap

OFFICE OF LIT

Port or Other  
FREQUENT

XX

It is proposed to plug and abandon the well as follows:

1. Rig up and pull tubing and set CIBP @ 3100'+. Dump 35' of cement on top of CIBP.
2. Circulate hole with mud. 9.5# brine mixed with 25 sk/100 bbl. salt gel). Cut 7" casing off at top of cement (top of cement calculated @ 2595'+) and pull 7" casing. Set a 100' cement plug in and out of 7" stub. (If top of cement behind 7" casing is found to be below 9-5/8" casing shoe, cut 7" casing off at that point. Set a 100' cement plug in and out of 7" stub. Pull tubing up and set a 100' cement plug in and out of the 9-5/8" casing shoe.
3. Pull tubing up and set a 100' cement plug at top of salt. (1575').
4. Cut 9-5/8" casing off at top of cement (top of cement calculated @ 226'+) and pull 9-5/8" casing. Set a 100' cement plug in and out of 9-5/8" stub. (If top of cement behind 9-5/8" casing is found to be below 13-3/8" casing shoe, cut 9-5/8" casing off at that point. Set a 100' cement plug in and out of 9-5/8" stub. Pull tubing up and set a 100' cement plug in and out of the 13-3/8" casing shoe.
5. Set a 10 sack surface plug.
6. Set marker and clean up location.

C. L. Wade: *[Signature]*

AREA SUPERINTENDENT

MAY 9, 1975

Orig. Signed by  
Joe D. Ramsey  
Dist. I, Supv.

HAO/bh