## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

Mar and Militer Pres Bu	 
NO. OF COPIES BECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	 
U.S.G.S.	 
LAND OFFICE	 
OPERATOR	1

## OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103

	T CANTA PE NEW MEVICO 97501	Kevisea (a-1-18
SANTA FE	SANTA FE, NEW MEXICO 87501	5a. Indicate Type of Lease
FILE	-	
U.S.G.S.	-	
LAND OFFICE	- <del>-</del>	5. State Otl & Gas Lease No.
OPERATOR	<b>_J</b>	
Sundf	RY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PA USE "APPLICAT	TION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
1.		
OIL X WELL .	OTHER-	N. HOBBS (G/SA) UNIT
2. Name of Operator		8. Farm or Lease Name
	•	SECTION 31
SHELL OIL COMPANY		9. Well No.
3. Address of Operator		441
P. O. BOX 991, HOUSTO	N, TEXAS 77001	10. Field and Pool, or Wildcat
4. Location of Well	·	
D ·	330 FEET FROM THE SOUTH LINE AND 330 FEET	HOBBS (G/SA)
UNIT LETTER	JUM PEET FROM THE	
FACT	10N 31 TOWNSHIP 18-S RANGE 38-E NI	
THE EAST LINE, SECT	10H TOWNSHIP TOUT HANGE NO	War. (111111111111111111111111111111111111
	CTTTTY CD L. I DC DT CD atc.	12. County
	15. Elevation (Show whether DF, RT, GR, etc.)	LEA AIIIIIIII
	\\\\\\ 3635' GR	LEA (((())))
16. Chark	Appropriate Box To Indicate Nature of Notice, Report or	Other Data
		ENT REPORT OF:
NOTICE OF I	INTENTION TO: SUBSEQU	
		ALTERING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON	COMMENCE DE LLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
PULL OR ALITA CASIA	OTHER	
ODEN ADDITIONAL	PAY AND ACIDIZE X	
	- IAL AND ACIDIZE	
	<b>1</b>	
Coland (	Proceedings (Clearly state all pertinent details, and give pertinent dates, incli	uding estimated date of starting any proposed
17. Describe Proposed or Completed C	Operations (Clearly state all pertinent details, and give pertinent dates, incli	uding estimated date of starting any proposed
17. Describe Proposed or Completed ( work) SEE RULE 1103.	Operations (Clearly state all pertinent details, and give pertinent dates, incli	uding estimated date of starting any proposed
17. Describe Proposed or Completed ( work) SEE RULE 1103.	Operations (Clearly state all pertinent details, and give pertinent dates, incli	uding estimated date of starting any proposed
work) SEE RULE 1103.		uding estimated date of starting any proposed
work) SEE RULE 1103.	Operations (Clearly state all pertinent details, and give pertinent dates, inclided as the state of the state	uding estimated date of starting any proposed
1. Clean out to PBTE	) (4211'). Spot 200 gals 15% HCl-NEA.	uding estimated date of starting any proposed
1. Clean out to PBTE	) (4211'). Spot 200 gals 15% HCl-NEA.	
1. Clean out to PBTE	) (4211'). Spot 200 gals 15% HCl-NEA.	
1. Clean out to PBTE  2. Perforate the fol  4112 to 13', 4123	O (4211'). Spot 200 gals 15% HCl-NEA. Howing intervals from the top/down: 3 to 24', 4133 to 34', 4146 to 51' and 4176 to	4199' (36' - 72 holes).
1. Clean out to PBTE  2. Perforate the fol  4112 to 13', 4123	O (4211'). Spot 200 gals 15% HCl-NEA. Howing intervals from the top/down: 3 to 24', 4133 to 34', 4146 to 51' and 4176 to	4199' (36' - 72 holes).
1. Clean out to PBTE  2. Perforate the fol 4112 to 13', 4123  3. Acidize perfs (41)	O (4211'). Spot 200 gals 15% HCl-NEA. Hlowing intervals from the top/down: 3 to 24', 4133 to 34', 4146 to 51' and 4176 to	4199' (36' - 72 holes).
1. Clean out to PBTE  2. Perforate the fol  4112 to 13', 4123	O (4211'). Spot 200 gals 15% HCl-NEA. Hlowing intervals from the top/down: 3 to 24', 4133 to 34', 4146 to 51' and 4176 to	4199' (36' - 72 holes).
1. Clean out to PBTE  2. Perforate the fol 4112 to 13', 4123  3. Acidize perfs (41 gals 15% HC1-NEA.	O (4211'). Spot 200 gals 15% HCl-NEA. Hlowing intervals from the top/down: 3 to 24', 4133 to 34', 4146 to 51' and 4176 to 166' to 4215') w/4,000 gals 15% HCl-NEA. Acidi	4199' (36' - 72 holes).
1. Clean out to PBTE  2. Perforate the fol 4112 to 13', 4123  3. Acidize perfs (41 gals 15% HC1-NEA.	O (4211'). Spot 200 gals 15% HCl-NEA. Hlowing intervals from the top/down: 3 to 24', 4133 to 34', 4146 to 51' and 4176 to	4199' (36' - 72 holes).
1. Clean out to PBTE  2. Perforate the fol 4112 to 13', 4123  3. Acidize perfs (41 gals 15% HC1-NEA.	O (4211'). Spot 200 gals 15% HCl-NEA. Hlowing intervals from the top/down: 3 to 24', 4133 to 34', 4146 to 51' and 4176 to 166' to 4215') w/4,000 gals 15% HCl-NEA. Acidi	4199' (36' - 72 holes).
1. Clean out to PBTE  2. Perforate the fol 4112 to 13', 4123  3. Acidize perfs (41 gals 15% HC1-NEA.	O (4211'). Spot 200 gals 15% HCl-NEA. Hlowing intervals from the top/down: 3 to 24', 4133 to 34', 4146 to 51' and 4176 to 166' to 4215') w/4,000 gals 15% HCl-NEA. Acidi	4199' (36' - 72 holes).
1. Clean out to PBTE  2. Perforate the fol 4112 to 13', 4123  3. Acidize perfs (41 gals 15% HC1-NEA.	O (4211'). Spot 200 gals 15% HCl-NEA. Hlowing intervals from the top/down: 3 to 24', 4133 to 34', 4146 to 51' and 4176 to 166' to 4215') w/4,000 gals 15% HCl-NEA. Acidi	4199' (36' - 72 holes).
1. Clean out to PBTE  2. Perforate the fol 4112 to 13', 4123  3. Acidize perfs (41 gals 15% HC1-NEA.	O (4211'). Spot 200 gals 15% HCl-NEA. Hlowing intervals from the top/down: 3 to 24', 4133 to 34', 4146 to 51' and 4176 to 166' to 4215') w/4,000 gals 15% HCl-NEA. Acidi	4199' (36' - 72 holes).

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. OCTOBER 28, 1982 J. FORE TITLE SUPERVISOR REG. & PERMITTING NOV 2 1982 ORIGINAL SIGNED BY JERRY SEXTON CONDITIONS OF APPROVAL, IF DETRICT I SUPR.

,