

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-20002
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1258-1

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name New Mexico "AE" State
2. Name of Operator Texaco Exploration and Production Inc.	8. Well No. 11
3. Address of Operator P.O. Box 730 Hobbs, New Mexico 88240	9. Pool name or Wildcat Vacuum Abo Reef
4. Well Location Unit Letter <u>I</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>11</u> Township <u>18S</u> Range <u>34E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3999' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1). Notify NMOC before plugging.
- 2). NIRS pulling unit. Install BOP.
- 3). Fish pump and grapple located at approximately 7600'.
- 4). TIR w/workstring and 2 7/8" bit. Clean out to 8700'. TOH w/bit and workstring.
- 5). By wireline, set CIBP at 8700'. Cap w/35' (1 sx) of class "C" cmt.
- 6). Load hole with salt gel mud (10 lb brine with 25 lbs of gel per barrel).
- 7). Run freepoint on 2 7/8" csg. Cut and pull casing.
- 8). Set CIBP at 5500'. Cap w/35' of class "C" cmt.
- 9). Set CIBP at 3335'. Cap w/35' of class "C" cmt.
- 10). Spot 100' plug (27 sx class "C" cmt) below salt section from 2990'-3090'.
- 11). Spot 100' plug (27 sx class "C" cmt) above salt section from 1770'-1870'.
- 12). Spot 100' plug (27 sx class "C" cmt) across 11 3/4" csg shoe from 315'-415'.
- 13). Spot a 10 sx plug (class "C" cmt) from 37'-surface.
- 14). Cut off wellhead. Install dry hole marker. Clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M.C. Duncan TITLE Engineer's Assistant DATE 8-30-91
TYPE OR PRINT NAME M.C. Duncan TELEPHONE NO. 393-7191

(This space for State Use) ORIGINAL SIGNED BY JERRY SEATON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

SEP 03 1991