

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-20265
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1258-1

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name New Mexico "AE" State
2. Name of Operator Texaco Exploration and Production Inc.	8. Well No. 20
3. Address of Operator P.O. Box 730 Hobbs, New Mexico 88240	9. Pool name or Wildcat Vacuum Abo Reef
4. Well Location Unit Letter <u>M</u> : <u>920</u> Feet From The <u>South</u> Line and <u>916</u> Feet From The <u>West</u> Line Section <u>12</u> Township <u>18-S</u> Range <u>34-E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3996' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1). Notify NMOCD before plugging.
- 2). MIRU pulling unit. Install BOP. Fish stuck pump.
- 3). TIH w/shoe and 1 5/8" drill pipe. Clean out to 8650'. TOH w/drill pipe.
- 4). By wireline, set CIBP at 8650'. Cap w/35' of class "C" cmt.
- 5). Load hole w/salt gel mud (10# brine with 25# of gel per Bbl).
- 6). Set CIBP at 5176'. Cap w/35' of class "C" cmt.
- 7). Run freepoint on 2 7/8" csg. Cut and pull.
- 8). Spot 100' plug (27 sx class "C") across 8 5/8" shoe from 3534'--3634'.

(Continues on back)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M.C. Duncan TITLE Engineer's Assistant DATE 12-04-91
TYPE OR PRINT NAME M.C. Duncan TELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY Geologist TITLE Geologist DATE
CONDITIONS OF APPROVAL, IF ANY:

- 9). Spot 100' plug (27 sx class "C") below salt section from 3030'-3130'.
- 10). Spot 100' plug (27 sx class "C") above salt section from 1775'-1875'.
- 11). Spot 100' plug (27 sx class "C") across 11 3/4" shoe from 300'-400'.
- 12). Spot a 10 sx plug (class "C" cmt) from 37'-surface.
- 13). Cut off wellhead. Install dry hole marker. Clean location.

RECEIVED

DEC 06 1991

**OCD
HOBBS OFFICE**