

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRI
(Other instructive
verse side)

DATE*

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0309375

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Middleton Pasture "A"

9. WELL NO.

#3

10. FIELD AND POOL, OR WILDCAT

Lusk

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

NMPM

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

1. OIL
WELL ☒ GAS
WELL ☐ OTHER

2. NAME OF OPERATOR

Shell Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 1509, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FNL & 660' FEL, Section 31, T-19-S, R-32-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3557' DF

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Run tubing and spot 25-sack plug across perfs and extend plug 200' above perforations. Fill 13' per sack in 11.6# 4.5.
2. Pull tubing.
3. Cut 4 1/2" casing (est. 7000').
4. Pump 50-sack plug down 4 1/2" casing and spot plug on top of 4 1/2" stub.
5. Pull 4 1/2" casing to 4500' and spot 30-sack plug.
6. Pull 4 1/2" casing to 3750' and spot 50-sack plug, bring cement 50' inside 8 5/8".
7. Pull 4 1/2" casing to 2500' and spot 30-sack plug.
8. Pull remaining 4 1/2" casing and spot 10-sack plug at surface.
9. Erect marker.
10. Have hole full of mud before setting plugs.

(Verbal approval granted A. R. Brown, USGS, Hobbs, New Mexico -
Date 11-1-68).

Date Last Produced - August 26, 1966

18. I hereby certify that the foregoing is true and correct

Original Signed By

D. DUREN

N.W. Harrison

TITLE

Staff Exploitation Engineer

DATE 11-25-68

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.