

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

MAY 9 1969

Indicate Type of Lease
State 23 Fee ☐
5. State Oil & Gas Lease No.
B-3936-1

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name <u>None</u>
2. Name of Operator <u>TEXACO Inc.</u>	8. Farm or Lease Name <u>New Mexico "AA" State</u>
3. Address of Operator <u>P. O. Box 728, Hobbs, New Mexico 88240</u>	9. Well No. <u>NCT-4</u>
4. Location of Well UNIT LETTER <u>B</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>South</u> LINE, SECTION <u>10</u> TOWNSHIP <u>18-S</u> RANGE <u>34-E</u> NMPM.	10. Field and Pool, or Wildcat <u>Vacuum Abo</u>
11. Elevation (Show whether DF, RT, GR, etc.) <u>4031' (D. F.)</u>	12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERMANENT REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TEXACO PROPOSES TO DO THE FOLLOWING WORK ON SUBJECT WELL:

1. Pull subsurface pumping equipment and set a permanent cast iron bridge plug @ 8900'.
2. Dump 5 gal. of hydromite on top of bridge plug.
3. Perforate 2 7/8" O. D. casing with 2 JSPF @ 8768', 8812' to 8830', and 8856'.
4. Acidize new perforation with 3000 gals. 28% Unisol acid.
5. Pump 1500 gals. 5% acid W/2 Gal. L.S.T. 5.
6. Pump 1500 gals. Treated water W/ 2 Gal. L. S. T. 5.
7. Pump 150# of unbeads in leas crude.
8. Repeat steps 4, 5, 6, 7.
9. Repeat steps 4, 5, 6.
10. Flush with 50 barrels water.
11. Swab, test and return to production.

14. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Assistant District Superintendent DATE May 9, 1969

APPROVED BY [Signature] TITLE DATE 1969

CONDITIONS OF APPROVAL IF ANY: