

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Lone Star Producing Company		8. Farm or Lease Name P. H. Golden, et al	
3. Address of Operator Box 4815, Midland, Texas 79702		9. Well No. 1	
4. Location of Well UNIT LETTER L 1,830 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 7 TOWNSHIP 18-S RANGE 38-E NMPM.		10. Field and Pool, or Wildcat Wildcat	
15. Elevation (Show whether DF, RT, GR, etc.) Ground 3,674.7'		12. County Leon	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Plug Back and Test	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Perforate 2 holes per foot from 4472'-74', 4478'-80', 4486'-88', 4490'-92' and 4494'-96'. Acidise with 1,000 gallons mud acid and test with tubing swab.
2. If zone from 4472'-96' tests water, squeeze off.
3. Perforate 2 holes per foot from 4336'-39', 4364'-68' and 4378'-82'. Acidise with 1,000 gallons mud acid.
4. If zone from 4336'-82' tests water, squeeze off.
5. Cut and pull 5 1/2" casing at free point between 3000' and 4000'.
6. Cut 7-5/8" casing opposite cut on 5 1/2" casing.
7. Lay 50 sack cement plug 25' inside where casing cut is made.
8. Fill hole with heavy mud to surface.
9. Put 10 sack plug in top of 10-3/4" surface casing.
10. Install 4 1/2" wall marker 5' above ground level.
11. Fill cellar to 6" above original ground level.
12. Fill reserve pits and clean up location when pits are dry enough to do so.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E. J. Amick TITLE Dist. Prod. Supt. DATE February 8, 1965

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

352-1001/17