	State of New M	laviaa			
Submit 3 copies to Appropriate District Office	Er , Minerals and Natural R			Form C-103 Revised 1-1-89	
	IL CONSERVATI	ON DIVISION	WELL API NO.		
P.O. Box 198C. Hobbs, NM 88240	P.O. Box 208		30-025-22451		
DISTRICT_II_	Santa Fe, New Mexic		5. Indicate Type of Lease		
P.O. Box Draw ir DD, Artesia, NM 88210		0 0100+ 2000	STATE		
DISTRICT III			6. State Oil / Gas Lease No.		
1000 Rio Brazes Rd., Aztec, NM 87410	ES AND REPORTS ON WEL	1	<u>B-1113</u>	-1	
(DO NOT U! E THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement	t Name	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)			CENTRAL VACUUM UNIT		
WELL WELL	OTHER				
2. Name of Ope ator TEXACO EXPLORATION & PRODUCTION INC			8. Well No. 118		
3. Address of Coerator 205 E. Bender, HOBBS, NM 88240			9. Pool Name or Wildcat		
4. Well Location					
Unit Letter N 9	90 Feet From The SOU	TH Line and 1650	_Feet From The _WESTI	Line	
Section 6 T	ownship18SF	Range <u>35E</u> NM	PM LEA_ CO	YTAUC	
	0. Elevation (Show whether DF, RI	(B, RT,GR, etc.) 3977' GL			
11. Check Appr	opriate Box to Indicate Na	ture of Notice Report	or Other Data		
	•			25	
NOTICE OF INTENTION		50			
	JG AND ABANDON	REMEDIAL WORK		브	
TEMPORARIL' ABANDON	ANGE PLANS	COMMENCE DRILLING OPE			
PULL OR ALTI R CASING		CASING TEST AND CEMEN	П ЗОВ		
OTHER:		OTHER:	· <u> </u>	🗋	
 Describe P oposed or Completed Opera any proposed work) SEE RULE 1103. 	tions (Clearly state all pertinent	details, and give pertinen	it dates, including estimated dat	e of starting	
7/6/97-7/12/97					
1. MIRU. NU EOP, pull rods, pump and tubing] .				
2. TIH with 3-3-4" bit and Bulldog Bailer. Clean out to PBTD @ 4774' (float collar). Analyze scale samples. Spot 110 gals TS-164 and scale converter, as necessary, across open hole and shut in for 24 hours. Spot 300 gals 15% NEFE across open hole. Shut in one hour and swab back.					
3. TIH with 5-1/2" treating packer @ 4403'. Use burst plate if necessary. Load backside and test to 500 psi. Open bypass and pickle tubing with 15% acid. Reverse to pit, flush tubing and close bypass.					
4. Acidize perf⇔ with 5500 gals 15% NEFE HCL at 4 BPM (max TP =1447 psi) using 3000# rock salt.					
5. Spot two drums TH-793 scale inhibitor mixed in 24 Bbls fresh water and flush with 250 Bbls fresh water.					
6. POH with packer and tubing. Run production equipment and return to production. Place on test.					
0. POT with protect and tability. Run production					
OPT 7/16/97 Fumping on POB BO-68 BW-1	92 MCF-12				
(INTERNAL TEPI STATUS REMAINS PM)					
	when have not says been shown and the total				
I hereby certify that he information above is true and complete to	A	neering Assistant	DATE 10/	/1/97	
Robb	y G. McCurry		Telephone No.	397-0446	
TYPE OR PRIN NAME BODD					
(This space for State Use) QRIGINA 1	STERNIS MELIAMS			· * 07	
APPROVED BYDISTAILT	LERVISOR		DATE		

APPROVED BY	יכום
CONDITIONS OF APPROVAL, I	F ANY:

5 (